



report date: 2024-03-28

General information

Make	FIAT
Model	PUNTO EASY
Colour	Black
Year of manufacture	-
Top speed	97 mph
0 - 60 mph	14.4 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	64.2 mpg
Consumption combined	52.3 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #13** 2022-04-06 15:58**MOT test number** 816651536829**Result** ✓ Passed**Next expiry date** 2023-04-05**Advice** Exhaust back box outer skin corroded**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive gearbox seal (8.4.1 (a) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2021-04-02 13:23**MOT test number** 407218996796**Result** ✓ Passed**Advice** Exhaust system corroded**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front brake discs worn and slightly corroded**MOT #11** 2021-04-02 09:15**MOT test number** 801465530637**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Front brake discs worn and slightly corroded**Advice** Rear heat shield insecure**Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Exhaust system corroded

**MOT #10** 2020-01-27 09:27**MOT test number** 867276600532**Result** ✓ Passed**MOT #9** 2020-01-15 09:56**MOT test number** 778002590462**Result** ✗ Failed**Fail** Nearside Parking brake inoperative on one side (1.4.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2019-02-05 11:58**MOT test number** 814318738474**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #7** 2019-02-04 09:25**MOT test number** 230262620012**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #6** 2018-02-14 15:48**MOT test number** 512679949042**Result** ✓ Passed**MOT #5** 2017-11-08 08:46**MOT test number** 935459054992**Result** ✓ Passed**Advice** Exhaust rear box the outer protective metal skin corroded incomplete.

**MOT #4** 2017-11-08 08:46**MOT test number** 100778206559**Result** ✗ Failed

**Pass with rectification** Offside Rear Direction indicator incorrect colour bulb showing a white light (1.4.A.2f)

**Advice** Exhaust rear box the outer protective metal skin corroded incomplete.

**Pass with rectification** Offside Headlamp aim too high adjusted by tester s.f.ward (1.8)

**Pass with rectification** Nearside Headlamp aim too high adjusted by tester s.f.ward (1.8)

**MOT #3** 2016-10-08 16:50**MOT test number** 471284313883**Result** ✓ Passed**MOT #2** 2016-09-19 09:58**MOT test number** 740877261345**Result** ✗ Failed

**Fail** Nearside Rear rear parking brake recording little or no effort (3.7.B.6a)

**Fail** Parking brake: efficiency below requirements (3.7.B.7)

**Fail** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail** Offside Rear rear parking brake recording little or no effort (3.7.B.6a)

**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Rear valve stem slightly deteriorated

**MOT #1** 2015-11-26 11:11**MOT test number** 643026429970**Result** ✓ Passed



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-12-18
Last registration	2022-04-06
Complete history	<a href="#">See info</a>



Registration #1	2012-12-18	10 mi
Registration #2	2015-11-26	36.276 mi
Registration #3	2016-09-19	51.590 mi
Registration #4	2016-10-08	51.628 mi
Registration #5	2017-11-08	53.412 mi
Registration #6	2017-11-08	53.412 mi
Registration #7	2018-02-14	53.621 mi
Registration #8	2019-02-04	55.998 mi
Registration #9	2019-05-29	56.377 mi
Registration #10	2019-05-29	56.377 mi
Registration #11	2019-05-29	56.377 mi
Registration #12	2019-05-29	56.377 mi
Registration #13	2019-05-29	56.377 mi
Registration #14	2019-05-29	56.377 mi
Registration #15	2019-05-29	56.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4065 mm
Wheel base	2510 mm
Kerb weight	1030 kg
Max. allowed weight	1590 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Engine number 0207966