



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS GTI EDITION30 T 230
Colour	Blue
Year of manufacture	2007
Top speed	150 mph
0 - 60 mph	6.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	227 BHP
Max. torque	300 Nm at 2.200 rpm
Engine capacity	1.984 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	194 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-05-23
Pictures	14
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-11
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	21
Total items failed	1

MOT #17	2023-05-12 10:24
MOT test number	529467775329
Result	✓ Passed
Next expiry date	2024-05-11
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Exhaust has a minor leak of exhaust gases Middle To Tail Box Clamp (6.1.2 (a))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Suspension component mounting prescribed area is corroded but not considered excessive Rear Suspension (5.3.6 (a) (i))
Advice	Hanbrake Has Alot Of Travel

MOT #16	2022-03-24 08:36
MOT test number	750106256679
Result	✓ Passed

Advice Handbrake Has A lot Of Travel

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

**MOT #15** 2021-03-11 15:04**MOT test number** 745531038659**Result** ✓ Passed**MOT #14** 2021-03-10 09:49**MOT test number** 185245572973**Result** ✗ Failed**MAJOR** Nearside Front Service brake excessively binding (1.2.1 (f))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MAJOR** Nearside Rear Service brake excessively binding (1.2.1 (f))**MOT #13** 2020-02-28 11:22**MOT test number** 344130902222**Result** ✓ Passed**MOT #12** 2019-03-13 17:04**MOT test number** 843100993607**Result** ✓ Passed**MOT #11** 2019-03-07 10:54**MOT test number** 847896510035**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Offside Front Service brake excessively binding (1.2.1 (f))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**MOT #10** 2018-03-19 09:56**MOT test number** 587896330025**Result** ✓ Passed**MOT #9** 2017-03-21 08:55**MOT test number** 558800172804**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2016-03-16 08:51**MOT test number** 648268190563**Result** ✓ Passed**MOT #7** 2016-03-16 08:51**MOT test number** 359326473965**Result** ✗ Failed**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #6** 2015-02-23 14:15**MOT test number** 567184255054**Result** ✓ Passed**MOT #5** 2014-02-24 10:45**MOT test number** 818415054073**Result** ✓ Passed**MOT #4** 2013-02-26 10:38**MOT test number** 227947853032**Result** ✓ Passed



MOT #3	2012-02-28 16:47
MOT test number	576979852066
Result	✓ Passed
MOT #2	2011-02-25 12:32
MOT test number	159306051059
Result	✓ Passed
MOT #1	2010-03-18 14:27
MOT test number	661827970091
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2024

✓
MOT

Expires:
11 May 2024

Tax status	Valid until 1 May
Days left	3
MOT expiry date	11 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2020-01-01
Current registration	 XXXXXX
Plate since	2020-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2007-03-19
Last registration	2023-05-12
Complete history	See info



Registration #1	2007-03-19	7 mi
Registration #2	2010-03-18	24.977 mi
Registration #3	2011-02-25	31.537 mi
Registration #4	2012-02-28	37.146 mi
Registration #5	2013-02-26	42.733 mi
Registration #6	2014-02-24	46.965 mi
Registration #7	2015-02-23	51.539 mi
Registration #8	2016-03-16	59.078 mi
Registration #9	2016-03-16	59.078 mi
Registration #10	2017-03-21	68.933 mi
Registration #11	2018-03-20	75.377 mi
Registration #12	2019-03-20	81.377 mi
Registration #13	2020-03-20	87.377 mi
Registration #14	2021-03-20	93.377 mi
Registration #15	2022-03-20	99.377 mi
Registration #16	2023-03-20	105.377 mi
Registration #17	2024-03-20	111.377 mi
Registration #18	2025-03-20	117.377 mi
Registration #19	2026-03-20	123.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1759 mm
Height	1469 mm
Length	4216 mm
Wheel base	2578 mm
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

NOT KNOWN