



report date: 2024-03-28

General information

Make	VOLVO
Model	S40 D SPORT
Colour	Silver
Year of manufacture	-
Top speed	118 mph
0 - 60 mph	11.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	67.3 mpg
Consumption combined	57.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-06
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history****MOT #18** 2022-03-30 10:59**MOT test number** 984983536872**Result** ✓ Passed**Next expiry date** 2023-03-29

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated cover split (5.3.4 (b) (i))

**MOT #17** 2022-03-25 15:13**MOT test number** 927341052726**Result** ✗ Failed

**MAJOR** Brake lever has insufficient reserve travel handbrake (1.1.2 (a))

**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated cover split (5.3.4 (b) (i))

**MOT #16** 2021-03-24 12:43**MOT test number** 225502418681**Result** ✓ Passed

**Advice** Front Inner Tyre worn close to legal limit/worn on edge BOTH (5.2.3 (e))

**MOT #15** 2020-02-27 13:17**MOT test number** 519544793263**Result** ✓ Passed**MOT #14** 2018-09-22 11:21**MOT test number** 402396347147**Result** ✓ Passed**MOT #13** 2018-09-22 11:21**MOT test number** 564357525709**Result** ✗ Failed

**Pass with rectification**

Rear All direction indicators incorrect colour X 2 (4.4.3 (a))



MOT #12 2017-05-04 15:39

MOT test number 348520973171

Result ✓ Passed

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Undertrays installed obscuring some components.

**Advice** Offside Front Tyre - Worn on inner edge.

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Engine bay covers installed obscuring some components.

**Advice** Nearside Front Tyre - Worn on inner edge.

**Advice** Parking brake lever has little reserve travel (3.1.6b)

MOT #11 2017-05-04 15:39

MOT test number 498436188782

Result ✗ Failed

**Advice** Undertrays installed obscuring some components.

**Advice** Offside Front Tyre - Worn on inner edge.

**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**Advice** Engine bay covers installed obscuring some components.

**Advice** Nearside Front Tyre - Worn on inner edge.

**Advice** Parking brake lever has little reserve travel (3.1.6b)

**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

MOT #10 2015-10-17 12:32

MOT test number 512640675747

Result ✓ Passed

**MOT #9** 2015-10-13 14:21**MOT test number** 945514791993**Result** ✗ Failed

**Fail** Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #8** 2014-10-15 12:25**MOT test number** 919888784233**Result** ✓ Passed

**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Notice** N/s/r tyre worn on inner edge

**MOT #7** 2014-10-14 11:36**MOT test number** 687217084296**Result** ✗ Failed

**Fail** Offside Front position lamp(s) not working (1.1.A.3b)

**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Notice** N/s/r tyre worn on inner edge

**Advice** Offside Front Suspension arm rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail** Nearside Rear brake caliper leaking (3.6.A.1)

**MOT #6** 2014-01-18 14:47**MOT test number** 738168414075**Result** ✓ Passed

**Notice** Offside front tyre wearing close to legal limit on inside edge.

**MOT #5** 2014-01-18 11:42**MOT test number** 119808914058**Result** ✗ Failed**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Offside front tyre wearing close to legal limit on inside edge.**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2013-02-11 14:20**MOT test number** 689802943098**Result** ✓ Passed**MOT #3** 2012-05-22 10:01**MOT test number** 368313442132**Result** ✓ Passed**MOT #2** 2011-05-27 09:19**MOT test number** 756967941169**Result** ✓ Passed**MOT #1** 2011-05-24 10:50**MOT test number** 236854441144**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-05-22
Last registration	2022-03-30
Complete history	<a href="#">See info</a>



Registration #1	2008-05-22	29 mi
Registration #2	2011-05-24	32.956 mi
Registration #3	2011-05-27	32.958 mi
Registration #4	2012-05-22	38.680 mi
Registration #5	2013-02-11	46.884 mi
Registration #6	2014-01-18	67.799 mi
Registration #7	2014-01-18	67.799 mi
Registration #8	2014-10-14	79.214 mi
Registration #9	2014-10-15	79.220 mi
Registration #10	2015-10-13	87.017 mi
Registration #11	2016-05-22	95.214 mi
Registration #12	2016-05-22	95.214 mi
Registration #13	2016-05-22	95.214 mi
Registration #14	2016-05-22	95.214 mi
Registration #15	2016-05-22	95.214 mi
Registration #16	2016-05-22	95.214 mi
Registration #17	2016-05-22	95.214 mi
Registration #18	2016-05-22	95.214 mi
Registration #19	2016-05-22	95.214 mi
Registration #20	2016-05-22	95.214 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1368 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Engine number	473928
---------------	--------