



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Black
Year of manufacture	2016
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 2

Date	2021-06-06
Pictures	35
Listing price	<a href="#">View report</a>



source: [yesauto.com](#)

Entry 1

Date	2021-05-27
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



## MOT history

MOT expiry date	2024-06-13
MOT pass rate	63 %
MOT passed	5
Failed MOT tests	3
Total advice items	10
Total items failed	1

MOT #8 2023-06-06 15:01

MOT test number 349854493070

Result ✓ Passed

Next expiry date 2024-06-13

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #7 2023-06-06 11:29

MOT test number 649894233880

Result ✗ Failed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**DANGEROUS** Offside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**DANGEROUS** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

MOT #6 2022-06-08 13:19

MOT test number 291316983310

Result ✓ Passed

**MOT #5** 2021-06-14 15:45**MOT test number** 926586332077**Result** ✓ Passed**MOT #4** 2020-10-07 15:26**MOT test number** 203396856222**Result** ✓ Passed**MOT #3** 2020-10-06 14:34**MOT test number** 256128691929**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #2** 2019-09-18 10:00**MOT test number** 122620710591**Result** ✓ Passed**MOT #1** 2019-09-18 10:00**MOT test number** 337794173895**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too far to the right (4.1.2 (a))



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 June 2024

✓  
**MOT**  
  
Expires:  
13 June 2024

Tax status	Valid until 1 June
Days left	33
MOT expiry date	13 June 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>XXXXXX</b>
Plate since	2019-06-29
Current registration	 <b>XXXXXX</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-09-30
Last registration	2023-06-06
Complete history	<a href="#">See info</a>



Registration #1	2016-09-30	29 mi
Registration #2	2019-09-18	27.441 mi
Registration #3	2019-09-18	27.441 mi
Registration #4	2020-10-06	31.363 mi
Registration #5	2020-10-07	31.364 mi
Registration #6	2020-10-07	31.364 mi
Registration #7	2020-10-07	31.364 mi
Registration #8	2020-10-07	31.364 mi
Registration #9	2020-10-07	31.364 mi
Registration #10	2020-10-07	31.364 mi
Registration #11	2020-10-07	31.364 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19MG7042LDD