



report date: 2024-03-29

General information

Make	VOLVO
Model	C70 T5 SE
Colour	Blue
Year of manufacture	2006
Top speed	146 mph
0 - 60 mph	7.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	220 BHP
Max. torque	320 Nm at 1.500 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	19.8 mpg
Consumption extra urban	39.2 mpg
Consumption combined	28.8 mpg
CO2 emission	234 g/km
CO2 label	L





Internet history

Entry 1

Date	2022-01-31
Pictures	32
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-25
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	17
Total items failed	9

MOT #20	2024-01-25 14:46
MOT test number	409050362670
Result	✓ Passed
Next expiry date	2025-01-25
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Inner Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #19	2023-01-13 09:43
MOT test number	543353673025
Result	✓ Passed
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Engine tray and under trays fitted at time of test

MOT #18	2022-01-10 14:52
MOT test number	583328651973
Result	✓ Passed

**MOT #17** 2021-12-23 14:31**MOT test number** 864638432466**Result** ✗ Failed**MAJOR** Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge 215/50r17 inner edge (5.2.3 (e))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**MOT #16** 2021-01-26 16:45**MOT test number** 511254761839**Result** ✓ Passed**MOT #15** 2020-01-22 16:18**MOT test number** 820495736233**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))**MOT #14** 2019-01-10 15:29**MOT test number** 851076871496**Result** ✓ Passed**MOT #13** 2018-01-18 11:32**MOT test number** 135479306738**Result** ✓ Passed

**MOT #12** 2017-01-20 10:50**MOT test number** 314262284765**Result** ✓ Passed**Advice** Offside Rear Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)**Advice** Nearside Front Suspension arm has slight play in a pin/bush rear bush (2.4.G.2)**MOT #11** 2015-12-01 14:34**MOT test number** 310208261980**Result** ✓ Passed**MOT #10** 2015-12-01 12:58**MOT test number** 471621308303**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #9** 2014-11-26 10:29**MOT test number** 416080734375**Result** ✓ Passed**Notice** Both rear tyres worn on inner edge**MOT #8** 2014-11-26 10:29**MOT test number** 498500334442**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim not tested (1.8.A.1c)**Notice** Both rear tyres worn on inner edge**Pass with rectification** Offside Headlamp not working on dipped beam (1.7.5a)

**MOT #7** 2013-11-12 10:01**MOT test number** 479296613443**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2012-11-21 11:18**MOT test number** 346836122348**Result** ✓ Passed**MOT #5** 2011-12-01 08:09**MOT test number** 459605331495**Result** ✓ Passed**MOT #4** 2011-11-30 10:19**MOT test number** 638914831335**Result** ✗ Failed**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #3** 2010-11-17 15:48**MOT test number** 930701120364**Result** ✓ Passed**MOT #2** 2009-11-26 16:46**MOT test number** 922670539366**Result** ✓ Passed



MOT #1	2009-11-26 09:57
MOT test number	703810839348
Result	✗ Failed
Fail	Nearside Registration plate lamp not working (1.1.5c)
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KR56AWJ
Plate since	2019-03-29
Current registration	KR56AWJ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2006-12-02
Last registration	2024-01-25
Complete history	See info



Registration #1	2006-12-02	13 mi
Registration #2	2009-11-26	19.298 mi
Registration #3	2009-11-26	19.298 mi
Registration #4	2010-11-17	23.118 mi
Registration #5	2011-11-30	27.844 mi
Registration #6	2011-12-01	27.844 mi
Registration #7	2012-11-21	31.556 mi
Registration #8	2013-11-12	36.472 mi
Registration #9	2014-11-26	39.826 mi
Registration #10	2015-12-01	47.729 mi
Registration #11	2015-12-01	47.729 mi
Registration #12	2016-01-20	51.557 mi
Registration #13	2016-01-20	51.557 mi
Registration #14	2016-01-20	51.557 mi
Registration #15	2016-01-20	51.557 mi
Registration #16	2016-01-20	51.557 mi
Registration #17	2016-01-20	51.557 mi
Registration #18	2016-01-20	51.557 mi
Registration #19	2016-01-20	51.557 mi
Registration #20	2016-01-20	51.557 mi
Registration #21	2016-01-20	51.557 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1987 mm
Height	1400 mm
Length	4582 mm
Wheel base	2640 mm
Kerb weight	1651 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	3942349