



General information

Make	VOLKSWAGEN
Model	BEETLE 60S EDITION TDI
Colour	White
Year of manufacture	2013
Top speed	122 mph
0 - 100 km/h	9.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	36.8 mpg
Consumption extra urban	53.5 mpg
Consumption combined	46.1 mpg
CO2 emission	134 g/km
CO2 label	E





Internet history

Entry 2

Date 2022-01-21

Pictures 26

Listing price [View report](#)



source: yesauto.com



Entry 1

Date 2022-01-18

Pictures 12

Listing price [View report](#)



source: cargurus.co.uk





MOT history

MOT expiry date	2025-03-01
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	31
Total items failed	3

MOT #11	2024-02-20 10:00
MOT test number	311708631765
Result	✓ Passed
Next expiry date	2025-03-01
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #10	2023-02-28 12:42
MOT test number	818843717506
Result	✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear tyre slightly worn on inner edge.
Advice	Rear Brake pad(s) wearing thin NSR (1.1.13 (a) (ii))
Advice	Brake disc worn, but not excessively Front brake discs lipped. (1.1.14 (a) (i))

**MOT #9**

2023-02-28 08:42

MOT test number

488116042088

Result**✗ Failed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Brake disc worn, but not excessively Front brake discs lipped. (1.1.14 (a) (i))
- Advice** Rear Brake pad(s) wearing thin NSR (1.1.13 (a) (ii))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Offside Rear tyre slightly worn on inner edge.

MOT #8

2022-03-02 14:11

MOT test number

511234992387

Result**✓ Passed**

- Advice** Acceleration not detected, no emission printout
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

2021-05-25 08:17

MOT test number

676312412028

Result**✓ Passed**

- Minor** Offside Front Upper Windscreen damaged but not adversely affecting driver's view small chip in screen (3.2 (a) (i))
- Advice** Emissions too clean to register

**MOT #6** 2020-05-11 11:57**MOT test number** 855232142129**Result** ✓ Passed**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2020-05-11 10:38**MOT test number** 506357250667**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2019-05-31 10:08**MOT test number** 857218654969**Result** ✓ Passed**Advice** Emissions too clean to register**Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view chip at bottom of screen (3.2 (a) (i))**MOT #3** 2018-05-22 09:01**MOT test number** 205063637727**Result** ✓ Passed**Minor** Offside Front Lower Windscreen damaged but not adversely affecting driver's view screen stone chip (3.2 (a) (i))**Advice** Emissions too clean to register**Minor** Nearside Front Windscreen damaged but not adversely affecting driver's view screen chip (3.2 (a) (i))



MOT #2

2017-06-03 09:09

MOT test number

457884644996

Result

✓ Passed

Advice

Emissions too clean to register

Advice

Rear unable to inspect both rear belts dog cage fitted filling up rear seats

Advice

Offside Front scrubbing on edge of tyre

Advice

Nearside Front scrubbing on edge of tyre

MOT #1

2016-05-17 09:09

MOT test number

514615633107

Result

✓ Passed

Advice

Emissions too clean to register



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
1 March 2025

Tax status	Valid until 1 February
Days left	277
MOT expiry date	1 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 VN13LFY
Plate since	2019-03-29
Current registration	 VN13LFY
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-06-04
Last registration	2024-02-20
Complete history	See info



Registration #1	2013-06-04	7 mi
Registration #2	2016-05-17	26.819 mi
Registration #3	2017-06-03	34.180 mi
Registration #4	2018-05-22	41.685 mi
Registration #5	2019-05-31	49.749 mi
Registration #6	2020-05-11	56.022 mi
Registration #7	2020-05-11	56.022 mi
Registration #8	2020-05-11	56.022 mi
Registration #9	2020-05-11	56.022 mi
Registration #10	2020-05-11	56.022 mi
Registration #11	2020-05-11	56.022 mi
Registration #12	2020-05-11	56.022 mi
Registration #13	2020-05-11	56.022 mi
Registration #14	2020-05-11	56.022 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	90%
Pedestrian	53%
Safety systems	86%
Overall rating	83%
Video	see crash video



Dimensions & weight

Width	1808 mm
Height	1473 mm
Length	4278 mm
Wheel base	2540 mm
Kerb weight	1482 kg
Max. allowed weight	1870 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	CFFBH54875