



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	CLK CLK200K AVANTGARDE
Colour	Black
Year of manufacture	2009
Top speed	144 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.8 mpg
Consumption extra urban	41.5 mpg
Consumption combined	31.7 mpg
CO2 emission	214 g/km
CO2 label	K






Internet history

Entry 1

Date	2022-01-08
Pictures	26
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-30
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	24
Total items failed	5

MOT #16	2023-10-24 08:26
MOT test number	963502041477
Result	✓ Passed
Next expiry date	2024-10-30

MOT #15	2022-10-31 16:01
MOT test number	768732738733
Result	✓ Passed

MOT #14	2021-09-09 09:01
MOT test number	894661212166
Result	✓ Passed

MOT #13	2020-09-19 07:41
MOT test number	994024691066
Result	✓ Passed

Advice

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2020-03-16 14:38
MOT test number	432770948640
Result	✓ Passed



MOT #11	2020-03-16 08:50
MOT test number	846139314551
Result	✗ Failed
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Front brake discs to small
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10	2019-03-13 09:53
MOT test number	493108046296
Result	✓ Passed
Advice	Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Engine cover / under tray fitted
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))
Advice	Front Exhaust mounting defective broken (6.1.2 (a))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MOT #9	2018-03-27 10:58
MOT test number	632729998287
Result	✓ Passed
Advice	Engine cover/under trays fitted

MOT #8	2017-03-02 13:42
MOT test number	179725424591
Result	✓ Passed
Advice	Under trays/sill covers fitted



MOT #7 2016-03-14 10:52

MOT test number 347595124163

Result ✓ Passed

- Advice** Rear exhaust supports corroded
- Advice** Under trays fitted

MOT #6 2015-03-26 09:51

MOT test number 759325785045

Result ✓ Passed

- Notice** Rear exhaust support corroded/system secure
- Notice** Under-trays fitted obscuring some underside components
- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Sill covers fitted

MOT #5 2014-03-14 13:45

MOT test number 405913474092

Result ✓ Passed

- Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)
- Notice** Exhaust system has various areas of corrosion particly where a hanger has become detached but the exhaust is still adequatly supported
- Advice** Nearside Front Front wheel bearing has slight play (2.5.A.3c)



MOT #4 2014-03-14 09:55

MOT test number 918193974096

Result ✗ Failed

Advice Nearside Front Front wheel bearing has slight play (2.5.A.3c)

Fail Offside Front coil spring broken (2.4.C.1a)

Advice Offside Front Front wheel bearing has slight play (2.5.A.3c)

Notice Exhaust system has various areas of corrosion particly where a hanger has become detached but the exhaust is still adequatly supported

MOT #3 2013-04-02 09:43

MOT test number 188862693094

Result ✓ Passed

MOT #2 2013-03-28 17:10

MOT test number 646017783022

Result ✗ Failed

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #1 2012-03-16 15:19

MOT test number 108536072493

Result ✓ Passed

Notice Front tyres slightly worn on edges

Notice N/s/f tyre outter side wall slightly damaged



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
30 October 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXX
Plate since	2019-03-29
Current registration	XXXXX
Plate since	2019-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-03-31
Last registration	2023-10-24
Complete history	See info



Registration #1	2009-03-31	16 mi
Registration #2	2012-03-16	26.711 mi
Registration #3	2013-03-28	35.511 mi
Registration #4	2013-04-02	35.513 mi
Registration #5	2014-03-14	42.072 mi
Registration #6	2014-03-14	42.072 mi
Registration #7	2015-03-26	47.962 mi
Registration #8	2016-03-14	51.863 mi
Registration #9	2017-03-02	55.410 mi
Registration #10	2018-03-02	59.310 mi
Registration #11	2018-03-02	59.310 mi
Registration #12	2018-03-02	59.310 mi
Registration #13	2018-03-02	59.310 mi
Registration #14	2018-03-02	59.310 mi
Registration #15	2018-03-02	59.310 mi
Registration #16	2018-03-02	59.310 mi
Registration #17	2018-03-02	59.310 mi
Registration #18	2018-03-02	59.310 mi

[More info >](#)



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1685 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531120793