



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1	
Date	2021-06-05
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-04-18
MOT pass rate	64 %
MOT passed	14
Failed MOT tests	8
Total advice items	51
Total items failed	22

MOT #22	2024-04-19 13:40
MOT test number	127092631432
Result	✓ Passed
Next expiry date	2025-04-18
Advice	Front Brake pipe corroded, covered in grease or other material x 2 (1.1.11 (c))

MOT #21	2023-02-15 08:58
MOT test number	419512323800
Result	✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #20	2022-02-17 15:55
MOT test number	629998756889
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #19**

2022-02-09 16:03

MOT test number

971794016956

Result**✗ Failed****Fail**

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail

Front Exhaust has a major leak of exhaust gases flexy pipe blowing (6.1.2 (a))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

Minor

Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Fail

Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice

Central Rear Coil spring corroded (5.3.1 (b) (i))

MOT #18

2021-01-26 10:45

MOT test number

814611601789

Result**✓ Passed****Advice**

Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))

Advice

Front Engine mounting damaged but not to excess (6.1.8 (a) (i))

MOT #17

2020-01-10 16:16

MOT test number

369445234363

Result**✓ Passed****Advice**

Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #16**

2020-01-10 10:06

MOT test number

618216365541

Result**✗ Failed**

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Offside Front Headlamp light intensity severely reduced (4.1.4 (a))

Fail Nearside Front Lower Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Offside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #15

2019-02-08 10:53

MOT test number

393518918186

Result**✓ Passed****MOT #14**

2019-02-08 10:53

MOT test number

921576436724

Result**✗ Failed**

Pass with rectification Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification Fuel cap/sealing device ineffective Temp one fitted (6.1.3 (b) (i))

MOT #13

2018-01-27 13:32

MOT test number

923736792477

Result**✓ Passed**

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #12** 2018-01-27 10:05**MOT test number** 949026052829**Result** ✗ Failed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Fuel cap/sealing device missing (7.2.4a)**MOT #11** 2017-01-20 11:43**MOT test number** 528601395397**Result** ✓ Passed**Advice** Bonnet safety catch seized**Advice** Offside Rear Tyre distorted**MOT #10** 2016-01-29 15:47**MOT test number** 729204496036**Result** ✓ Passed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #9** 2016-01-29 09:40**MOT test number** 914973785300**Result** ✗ Failed**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pipe slightly corroded across back axle (3.6.B.2c)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Front Brake pipe excessively corroded to rear x2 (3.6.B.2c)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #8** 2015-01-30 14:08**MOT test number** 188310435034**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Notice** Bonnet safty catch seized**MOT #7** 2015-01-30 10:22**MOT test number** 719540235077**Result** ✗ Failed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Notice** Bonnet safty catch seized**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)

**MOT #6** 2014-01-24 15:31**MOT test number** 178594224404**Result** ✓ Passed**Notice** Slight out of shape tyre n/s/r**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #5** 2014-01-24 10:25**MOT test number** 765564124035**Result** ✗ Failed**Fail** Offside Front coil spring broken (2.4.C.1a)**Advice** Nearside Rear Shock absorber has a light misting of oil (2.7.3)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Notice** Slight out of shape tyre n/s/r**MOT #4** 2013-02-01 08:45**MOT test number** 439302233034**Result** ✓ Passed**Notice** Exhaust rusting**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Front brake discs worn**Advice** Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.5b)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front tyres wearing on inner edges**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Rear brake discs corroded around edges

**MOT #3** 2012-01-28 09:03**MOT test number** 278388122014**Result** ✓ Passed**Notice** Front brake discs slightly worn**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Notice** Rear brake discs corroded around edges**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #2** 2012-01-28 09:03**MOT test number** 119188922478**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too low and too far to the right. (1.8)**Notice** Front brake discs slightly worn**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Notice** Rear brake discs corroded around edges**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #1** 2011-02-07 09:02**MOT test number** 167598031484**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 April 2025

Tax status	Valid until 1 June
Days left	34
MOT expiry date	18 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-06-29
Current registration	 XXXXXX
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2008-01-02
Last registration	2024-04-19
Complete history	See info



Registration #1	2008-01-02	8 mi
Registration #2	2011-02-07	45.886 mi
Registration #3	2012-01-28	57.710 mi
Registration #4	2013-02-01	74.454 mi
Registration #5	2014-01-24	93.001 mi
Registration #6	2014-01-24	93.001 mi
Registration #7	2015-01-30	105.116 mi
Registration #8	2015-01-30	105.116 mi
Registration #9	2016-01-29	116.555 mi
Registration #10	2016-01-29	116.556 mi
Registration #11	2017-01-20	127.344 mi
Registration #12	2018-01-27	135.682 mi
Registration #13	2019-01-27	151.277 mi
Registration #14	2019-01-27	151.277 mi
Registration #15	2019-01-27	151.277 mi
Registration #16	2019-01-27	151.277 mi
Registration #17	2019-01-27	151.277 mi
Registration #18	2019-01-27	151.277 mi
Registration #19	2019-01-27	151.277 mi
Registration #20	2019-01-27	151.277 mi
Registration #21	2019-01-27	151.277 mi
Registration #22	2019-01-27	151.277 mi
Registration #23	2019-01-27	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564