





report date: 2024-03-28

# General information

| Make                | CITROEN                               |
|---------------------|---------------------------------------|
| Model               | DISPATCH 1000 L1H1 ENTERPRISE P/V HDI |
| Colour              | Grey                                  |
| Year of manufacture | 2014                                  |
| Top speed           | 90 mph                                |
| Gearbox             | 5 speed Manual                        |

# Engine & fuel consumption

| Power                   | 89 BHP              |
|-------------------------|---------------------|
| Max. torque             | 180 Nm at 1.500 rpm |
| Engine capacity         | 1.560 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 35.8 mpg            |
| Consumption extra urban | 45.6 mpg            |
| Consumption combined    | 42.2 mpg            |
| CO2 emission            | 177 g/km            |
| CO2 label               | I                   |



CarCheck.co.uk page 1/13



report date: 2024-03-28

# Internet history

## Entry 1

Date 2021-11-03

Pictures 19

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

| MOT expiry date    | 2024-11-27 |
|--------------------|------------|
| MOT pass rate      | 58 %       |
| MOT passed         | 7          |
| Failed MOT tests   | 5          |
| Total advice items | 13         |
| Total items failed | 17         |

| MOT #12   |  | 2023-11-27 16:26 |
|---|--|------------------|
| MOT test  | number   | 207561033001     |
| Result  |  | ✓ Passed         |
| Next exp  | iry date   | 2024-11-27       |
| Advice  | Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))       |                  |
| Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i)) |  |                  |
| Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))                              |  |                  |
| Advice  | Offside Front Tyre worn close to legal limit/worn on edge worn on inside e | edge (5.2.3 (e)) |
| Advice  | Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))    |                  |

| MOT #11         | 2022-11-28 16:15 |
|-----------------|------------------|
| MOT test number | 979881663027     |
| Result          | ✓ Passed         |

| MOT #10                 |  | 2022-11-28 16:15 |
|-------------------------|--|------------------|
| MOT test number         |  | 109249288205     |
| Result                  |  | <b>×</b> Failed  |
| Pass with rectification | Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii)) |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-28


| MOT #9                 | 2021-11-26 15:55                 |
|------------------------|----------------------------------|
| MOT test number        | 473185396336                     |
| Result                 | ✓ Passed                         |
|                        |                                  |
| MOT #8                 | 2020-09-14 11:08                 |
| MOT test number        | 579821476722                     |
| Result                 | ✓ Passed                         |
|                        |                                  |
|                        |                                  |
| MOT #7                 | 2020-09-14 10:55                 |
| MOT #7 MOT test number | 2020-09-14 10:55<br>323830656675 |
|                        |                                  |
| MOT test number        | 323830656675                     |
| MOT test number Result | 323830656675                     |

| MOT #6          | 2019-09-12 15:19 |
|-----------------|------------------|
| MOT test number | 601003813727     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 4/13



report date: 2024-03-28




| MOT #4        |  | 2018-08-31 11:38 |
|---------------|--|------------------|
| MOT test r    | number   | 507045047303     |
| Result        |  | ✓ Passed         |
| Advice Advice | Nearside Rear Outer Road wheel slightly distorted (5.2.2 (c) (i))  Offside w/screen has chip in A zone |                  |

CarCheck.co.uk page 5/13



report date: 2024-03-28



| MOT #2                                   | 2017-09-11 07:44 |
|--|------------------|
| MOT test number                          | 133292975241     |
| Result                                   | ✓ Passed         |
| Advice Both front tyres outer edges worn |                  |

| MOT #1  | 2017-09-08 11:53 |
|---|------------------|
| MOT test number   | 746477051281     |
| Result  | <b>×</b> Failed  |
| Fail Offside Front Front suspension has excessive play in a lower suspension ball joint  Advice Both front tyres outer edges worn | (2.5.B.1a)       |

CarCheck.co.uk page 6/13



report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 August |
|------------------|----------------------|
| Days left        | 94                   |
| MOT expiry date  | 27 November 2024     |
| Full MOT history | See MOT history      |

## Tax calculation

| Vehicle class             | 39         |
|---------------------------|------------|
| Standard rate (12 months) | £ 275,00,- |
| Standard rate (6 months)  | £ 151,25,- |

CarCheck.co.uk page 7/13



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



| Owner history   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this CITROEN? How many owne have? Check it in the premium report and see all owner registrations. Download the full r |             |
| **********  |             |
|   |             |
| ***************************************   |             |
|   |             |
| ***************************************   |             |
| ***************************************   |             |
| Plate changes   | More info > |
| See in this check if this CITROEN had different number plates.  |             |
| Number of plates  |             |
| Current registration  | UK UK       |
| Plate since   |             |
| Current registration  | OK SIE      |
| Plate since   |             |
|   | More info > |

CarCheck.co.uk page 10/13



## Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

# Mileage check

Registration #14

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 14         |
| First mileage registration | 2014-09-26 |
| Last registration          | 2023-11-27 |
| Complete history           | See info   |



| Registration #1  | 2014-09-26 | 19 mi     |
|------------------|------------|-----------|
| Registration #2  | 2017-09-08 | 36.400 mi |
| Registration #3  | 2017-09-11 | 36.401 mi |
| Registration #4  | 2018-08-30 | 50.778 mi |
| Registration #5  | 2018-08-31 | 50.778 mi |
| Registration #6  | 2019-09-12 | 65.283 mi |
| Registration #7  | 2019-09-12 | 65.283 mi |
| Registration #8  |            | 71.777 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 71.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 71.777 es |
| Registration #13 |            | 11.777 es |

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 12/13



Dimensions & weight

| Width               | 1895 mm |
|---------------------|---------|
| Height              | 1942 mm |
| Length              | 4805 mm |
| Kerb weight         | 1673 kg |
| Max. allowed weight | 2661 kg |

# Additional information

| Fuel tank capacity | 80 I             |
|--------------------|------------------|
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 3                |
| Number of axles    | 2                |
| Engine number      | JBDF0042531      |

CarCheck.co.uk page 13/13