



report date: 2024-03-29

General information

Make	AUDI
Model	A4 TDI QUATTRO DPF S LINE
Colour	Grey
Year of manufacture	2007
Top speed	152 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	233 BHP
Max. torque	450 Nm at 1.400 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Diesel
Consumption city	25.9 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.2 mpg
CO2 emission	198 g/km
CO2 label	J





MOT history

MOT expiry date	2024-04-21
MOT pass rate	82 %
MOT passed	14
Failed MOT tests	3
Total advice items	29
Total items failed	8

MOT #17 2023-04-21 15:25

MOT test number 879244827915

Result ✓ Passed

Next expiry date 2024-04-21

- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both fronts (1.1.14 (a) (ii))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated Front arm (5.3.4 (b) (i))

MOT #16 2023-04-21 13:32

MOT test number 604945063182

Result ✗ Failed

- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated Front arm (5.3.4 (b) (i))
- Fail** Registration plate lamp inoperative in the case of a single lamp or all lamps All (4.7.1 (b) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Both fronts (1.1.14 (a) (ii))

**MOT #15** 2022-04-22 14:23**MOT test number** 996994056160**Result** ✓ Passed**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #14** 2022-04-20 11:39**MOT test number** 386541543375**Result** ✗ Failed**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Nearside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #13** 2021-05-27 17:09**MOT test number** 752647223868**Result** ✓ Passed**MOT #12** 2020-06-20 10:11**MOT test number** 189458016266**Result** ✓ Passed

**MOT #11** 2019-06-07 15:23**MOT test number** 610878075699**Result** ✓ Passed**MOT #10** 2018-06-26 10:31**MOT test number** 956838167621**Result** ✓ Passed**Advice** N/s/f track rod end gaitor deteriorating**MOT #9** 2017-03-16 09:54**MOT test number** 737387765621**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil front shock reduced damping effect (2.7.3)**Advice** Front tyres wearing at inner edges**Advice** Engine light on**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front disc lipped rear brake disc lipped**MOT #8** 2016-02-16 15:39**MOT test number** 629516156443**Result** ✓ Passed**Advice** Lip on front brake disc**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Front shock absorber damping effect reduced**Advice** Both sides front tyres wearing at inner edge

**MOT #7** 2015-01-23 10:43**MOT test number** 796613025098**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-12-12 09:38**MOT test number** 837636943308**Result** ✓ Passed**MOT #5** 2013-01-04 14:41**MOT test number** 656064603071**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2011-09-29 17:18**MOT test number** 707852971279**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #3** 2011-09-29 15:08**MOT test number** 277902771257**Result** ✗ Failed**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Notice** Nail in nearside rear tyre



MOT #2	2010-08-18 16:39
MOT test number	820250230266
Result	✓ Passed
MOT #1	2010-05-17 16:10
MOT test number	244497230474
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
29 February 2024

X

MOT

Expired:
21 April 2024

Tax status	Expired at 29 February 2024
Days left	60 days too late
MOT expiry date	21 April 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2007-05-23
Last registration	2023-04-21
Complete history	See info



Registration #1	2007-05-23	11 mi
Registration #2	2010-05-17	46.149 mi
Registration #3	2010-08-18	47.895 mi
Registration #4	2011-09-29	57.952 mi
Registration #5	2011-09-29	57.952 mi
Registration #6	2013-01-04	74.207 mi
Registration #7	2013-12-12	82.446 mi
Registration #8	2015-01-23	936.222 mi
Registration #9	2016-02-16	101.928 mi
Registration #10	2016-05-20	25.277 mi
Registration #11	2016-05-20	25.277 mi
Registration #12	2016-05-20	25.277 mi
Registration #13	2016-05-20	25.277 mi
Registration #14	2016-05-20	25.277 mi
Registration #15	2016-05-20	25.277 mi
Registration #16	2016-05-20	25.277 mi
Registration #17	2016-05-20	25.277 mi
Registration #18	2016-05-20	25.277 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1772 mm
Height	1427 mm
Length	4586 mm
Wheel base	2642 mm
Kerb weight	1610 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	ASB 066095