

Ford



### General information

| STYLE CLIMATE |
|---------------|
|               |
|               |
| 1             |
| onds          |
| Manual        |
| 1             |

### Engine & fuel consumption

| Power                   | 79 BHP              |
|-------------------------|---------------------|
| Max. torque             | 124 Nm at 3.500 rpm |
| Engine capacity         | 1.388 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 35.3 mpg            |
| Consumption extra urban | 54.3 mpg            |
| Consumption combined    | 45.6 mpg            |
| CO2 emission            | 154 g/km            |
| CO2 label               | G                   |







## Internet history

| Entry | 1 |
|-------|---|
|       |   |

Date Pictures 2021-10-05

17


Listing price

View report









source: autotrader.co.uk



## MOT history

| MOT expiry date    | 2024-10-19 |
|--------------------|------------|
| MOT pass rate      | 93 %       |
| MOT passed         | 14         |
| Failed MOT tests   | 1          |
| Total advice items | 11         |
| Total items failed | 1          |

| MOT #15   |  | 2023-09-27 13:34 |
|-----------|--|------------------|
| MOT test  | number   | 537851374362     |
| Result    |  | ✓ Passed         |
| Next expi | ry date  | 2024-10-19       |
| Advice    | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice    | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| МОТ #14  | 2023-09-21 09:05 |  |
|--|------------------|--|
| MOT test number  | 825954655209     |  |
| Result   | 🗙 Failed         |  |
| FailOffside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b)(ii)) |                  |  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))   |                  |  |

| MOT #13   | 2022-10-20 10:28 |
|---|------------------|
| MOT test number   | 656181759387     |
| Result  | ✓ Passed         |
| Advice Offside Track rod end ball joint has slight play (2.1.3 (b) (i)) |                  |





| 2021-10-12 14:09 |
|------------------|
| 837130556419     |
| ✓ Passed         |
|                  |
| 2021-03-23 13:59 |
| 625494745756     |
| ✓ Passed         |
|                  |

| 102825383192 |
|--------------|
| ✓ Passed     |
|              |
|              |

| MOT #9   |  | 2019-03-12 11:08 |
|----------|--|------------------|
| MOT test | number   | 584881858133     |
| Result   |  | ✓ Passed         |
| Advice   | Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #8  | 2018-03-02 14:32 |
|---|------------------|
| MOT test number                                 | 974473411349     |
| Result  | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin (3.5.1g) |                  |

| MOT #7          | 2017-03-13 12:58 |
|-----------------|------------------|
| MOT test number | 513809290030     |
| Result          | ✓ Passed         |





| MOT #6  | 2016-03-08 13:33 |
|---|------------------|
| MOT test number   | 652116699502     |
| Result  | ✓ Passed         |
| Advice Both rear and o/s/f tyres perishing and cracked. |                  |
| MOT #5  | 2015-03-04 16:47 |
| MOT test number   | 116123165031     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #4  | 2014-03-14 10:45 |
| MOT test number   | 416453674013     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #3  | 2013-03-01 11:18 |
| MOT test number   | 269120163031     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #2  | 2012-03-02 11:09 |
| MOT test number   | 927202462042     |
| Result  | ✓ Passed         |
|   |                  |
| MOT #1  | 2011-03-02 15:09 |
| MOT test number   | 485321961052     |
| Result  | ✓ Passed         |



YK08HMU report date: 2024-03-28

Tax & MOT check

| ✓<br>Taxed<br>Tax due:<br>1 October 2024 | ✓<br>MOT<br>Expires:<br>19 October 2024 |
|--|---|
| Tax status                               | Valid until 1 October                   |
| Days left                                | 155                                     |
| MOT expiry date                          | 19 October 2024                         |
| Full MOT history                         | See MOT history                         |

### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |  |       |
|----------|--|-------|
| Date     | F  |       |
| Category |  | ARME  |
| Туре     |  |       |
| Damage 2 |  | AMPLE |
|          | E E  |       |
| Date     |  | \$    |
| Category | AMP  |       |
| Туре     | No. Contraction of the second se |       |

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.000 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4        |





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second sec |             |
|--|-------------|
| ************   |             |
| ********   |             |
| *******  |             |
| ************   |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FORD had different number plates.  |             |
| Number of plates   | ,           |
| Carrent registration   |             |
| Plate since  |             |
| Carrent registration   |             |
| Plate since  |             |
|  |             |





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





## Mileage check

| Odometer                   | In miles        |
|----------------------------|-----------------|
| Mileage registrations      | 17              |
| First mileage registration | 2008-03-31      |
| Last registration          | 2023-09-27      |
| Complete history           | <u>See info</u> |



| Registration #1  | 2008-03-31 | 22 mi      |
|------------------|------------|------------|
| Registration #2  | 2011-03-02 | 15.819 mi  |
| Registration #3  | 2012-03-02 | 19.908 mi  |
| Registration #4  | 2013-03-01 | 23.995 mi  |
| Registration #5  | 2014-03-14 | 27.794 mi  |
| Registration #6  | 2015-03-04 | 31.902 mi  |
| Registration #7  | 2016-03-08 | 35.976 mi  |
| Registration #8  | 2017-03-13 | 40.027 mi  |
| Registration #9  | 2018-03-02 | 43.920 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
| Registration #12 |            | 11.777 esi |
| Registration #13 |            | 11.777 mi  |
| Registration #14 |            | 11.777 esi |
| Registration #15 |            | 11.777 mi  |
| Registration #16 |            | 11.777 est |
| Registration #17 |            | 11.777 mi  |
|                  |            |            |





#### Car features

| S0225  | Air conditioning |
|--------|------------------|
| \$0295 |                  |
| 50482  |                  |
| S0501  |                  |
| \$0566 |                  |
| S0567  |                  |
| S0569  |                  |

# Safety ratings

**NCAP** rating

Video

\*\*\*\* see crash video



| Dimensions & weight               |                       |
|-----------------------------------|-----------------------|
| Width                             | 1963 mm               |
| Height                            | 1543 mm               |
| Length                            | 4013 mm               |
| Wheel base                        | 2485 mm               |
| Kerb weight                       | 1199 kg               |
| Max. allowed weight               | 1605 kg               |
| Additional information            |                       |
| Fuel tank capacity                | 45                    |
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 5                     |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12          |

| Number of axles | 2       |
|-----------------|---------|
| Engine number   | 8A48618 |