



report date: 2024-03-28

General information

Make	VOLVO
Model	V70 D4 SE NAV
Colour	Blue
Year of manufacture	2015
Top speed	137 mph
0 - 60 mph	8.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	72.4 mpg
Consumption combined	67.3 mpg
CO2 emission	114 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-03-09
Pictures	2
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-22
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	10
Total items failed	2

MOT #9 2024-03-18 12:28

MOT test number 101004463872

Result ✓ Passed

Next expiry date 2025-03-22

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Minor Windscreen damaged but not adversely affecting driver's view 2 x stone chips (3.2 (a) (i))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm, worn uneven on inner edge (5.2.3 (e))

MOT #8 2024-03-18 12:28

MOT test number 462482401319

Result ✗ Failed

Minor Windscreen damaged but not adversely affecting driver's view 2 x stone chips (3.2 (a) (i))

Advice Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge 2mm, worn uneven on inner edge (5.2.3 (e))

**MOT #7** 2023-03-06 11:30**MOT test number** 737905929076**Result** ✓ Passed**Advice** Stone chip in windscreen**Advice** Rear brake pads low**MOT #6** 2022-03-23 09:58**MOT test number** 476625634036**Result** ✓ Passed**MOT #5** 2022-03-23 09:58**MOT test number** 760178984503**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #4** 2021-08-07 11:00**MOT test number** 630062508639**Result** ✓ Passed**MOT #3** 2020-08-04 11:07**MOT test number** 357055239384**Result** ✓ Passed**Advice** Under trays fitted**MOT #2** 2019-10-18 09:14**MOT test number** 506972944479**Result** ✓ Passed**Advice** Under covers fitted



MOT #1	2018-10-25 09:44
MOT test number	965244531940
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
22 March 2025

Tax status	Valid until 1 May
Days left	367
MOT expiry date	22 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	KN65LDY
Plate since	2019-09-28
Current registration	KN65LDY
Plate since	2019-09-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2015-09-28
Last registration	2024-03-18
Complete history	See info



Registration #1	2015-09-28	13 mi
Registration #2	2018-10-25	30.113 mi
Registration #3	2019-10-18	37.755 mi
Registration #4	2020-08-04	39.328 mi
Registration #5	2021-08-07	40.122 mi
Registration #6	2022-05-20	41.277 mi
Registration #7	2023-05-20	42.277 mi
Registration #8	2023-05-20	43.277 mi
Registration #9	2023-05-20	44.277 mi
Registration #10	2023-05-20	45.277 mi
Registration #11	2024-03-18	46.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	88%
Children	84%
Pedestrian	43%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2106 mm
Height	1547 mm
Length	4814 mm
Wheel base	2816 mm
Kerb weight	1722 kg
Max. allowed weight	2260 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1359411