






report date: 2024-03-29

## General information

Make	LAND ROVER
Model	DEFENDER TD HARD TOP
Colour	Silver
Year of manufacture	2011
Top speed	90 mph
0 - 60 mph	15.8 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	122 BHP
Max. torque	360 Nm at 2.000 rpm
Engine capacity	2.198 сс
Cylinders	4
Fuel type	Diesel
Consumption city	20.8 mpg
Consumption extra urban	29.1 mpg
Consumption combined	25.5 mpg



CarCheck.co.uk page 1/12



# Internet history

## Entry 1

Date 2022-01-03

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



✓ Passed

B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	torv.
101	C I	1115	IUI V
	•		tory

Result

MOT expiry date	2024-12-29
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	7
Total items failed	2

MOT #11	2023-12-20 17:02
MOT test number	486031168542
Result	✓ Passed
Next expiry date	2024-12-29

MOT #10		2022-12-20 10:53
MOT test	number	925769521145
Result		✓ Passed
Advice	Engine cover & under body cover panels fitted obscuring some testable compone	nts.

MOT #9	2021-12-30 15:32
MOT test number	852398867224
Result	✓ Passed
MOT #8	2021-03-18 15:30
MOT test number	222231890388
Result	<b>✓</b> Passed
MOT #7	2020-03-16 11:32
MOT test number	779694798437

CarCheck.co.uk page 3/12



MOT #6	2019-03-12 17:32

**MOT test number** 314480968799

**Result** ✓ Passed

**MOT #5** 2018-03-12 15:37

**MOT test number** 203497552212

**Result** ✓ Passed

MOT #4 2017-03-21 16:43

**MOT test number** 209046544611

**Result** ✓ Passed

MOT #3 2016-03-01 12:49

**MOT test number** 463333551133

MOT #2 2015-03-04 13:13

**MOT test number** 199443865458

Result \( \sqrt{Passed} \)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

Advice Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of

dirt (2.4.G.2)

CarCheck.co.uk page 4/12



MOT #1 2015-03-04 13:13

**MOT test number** 105373365001

Result X Failed

Pass with rectification Nearside Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)


Advice Offside Front Anti-roll bar linkage ball joint dust cover damaged, but preventing the ingress of dirt

(2.4.G.2)

CarCheck.co.uk page 5/12



## Tax & MOT check



MOT expiry date 29 December 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



## Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



## Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



# Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many o ROVER have? Check it in the premium report and see all owner registrations. Download t	
**************************************	
***************************************	
	More info >
Plate changes	
See in this check if this LAND ROVER had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



## Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this LAND ROVER is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2011-12-16
Last registration	2023-12-20
Complete history	See info



Registration #1	2011-12-16	8 mi
Registration #2	2015-03-04	12.591 mi
Registration #3	2016-03-01	15.436 mi
Registration #4	2017-03-21	23.222 mi
Registration #5	2018-03-12	27.184 mi
Registration #6	2019-03-12	32.336 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



## Dimensions & weight

Width	1790 mm
Height	2181 mm
Length	4625 mm
Kerb weight	1969 kg
Max. allowed weight	3050 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	111121222943DT224

CarCheck.co.uk page 12/12