



report date: 2024-03-29

General information

| | |
|---------------------|------------------------|
| Make | FORD |
| Model | FIESTA STYLE PLUS TDCI |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 101 mph |
| 0 - 60 mph | 14.4 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 67 BHP |
| Max. torque | 160 Nm at 1.750 rpm |
| Engine capacity | 1.399 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 53.3 mpg |
| Consumption extra urban | 80.7 mpg |
| Consumption combined | 67.3 mpg |
| CO2 emission | 110 g/km |
| CO2 label | B |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-07 |
| Pictures | 1 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2022-09-14 |
| MOT pass rate | 77 % |
| MOT passed | 10 |
| Failed MOT tests | 3 |
| Total advice items | 21 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #13 | 2021-09-15 14:46 |
| MOT test number | 634344957700 |
| Result | ✓ Passed |
| Next expiry date | 2022-09-14 |

| | |
|-----------------|--|
| MOT #12 | 2021-09-15 07:40 |
| MOT test number | 367606812533 |
| Result | ✗ Failed |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) |

| | |
|-----------------|--|
| MOT #11 | 2021-03-27 10:55 |
| MOT test number | 893103078669 |
| Result | ✓ Passed |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Wiper blades slight worn. |
| Advice | Offside Rear Inner Tyre slightly damaged/cracking or perishing wall (5.2.3 (d) (ii)) |

**MOT #10**

2020-03-31 10:44

MOT test number

678768974710

Result

✓ Passed

- Advice** Front Items removed from driver's view prior to test
- Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Brake hydraulic reservoir close to minimum mark (1.1.10 (d) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #9

2019-03-29 16:48

MOT test number

878905800498

Result

✓ Passed

- Advice** Items removed from driver's view prior to test
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #8

2019-03-29 16:48

MOT test number

395700493305

Result

✗ Failed

- Pass with rectification** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Pass with rectification** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Items removed from driver's view prior to test

MOT #7

2018-03-31 11:38

MOT test number

610698308568

Result

✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2017-04-03 11:16**MOT test number** 169351149579**Result** ✓ Passed**MOT #5** 2017-04-03 09:42**MOT test number** 281614331980**Result** ✗ Failed**Fail** Rear Registration plate lamp not working (1.1.C.1d)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #4** 2016-03-07 15:37**MOT test number** 190588744110**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2015-03-21 12:52**MOT test number** 478560985099**Result** ✓ Passed**MOT #2** 2014-03-03 15:51**MOT test number** 159162564018**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay



| | |
|-----------------|--|
| MOT #1 | 2013-03-22 15:17 |
| MOT test number | 367311883017 |
| Result | ✓ Passed |
| Notice | Clutch and brake pedal rubbers worn |
| Notice | Both rear tyres worn cracking and perished walls 195x50r15 82v firestone |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) |
| Notice | Rear number plate peeling |



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this FORD had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | PA53NOW |
| Plate since | 2024-03-29 |
| Current registration | PA53NOW |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2010-03-22 |
| Last registration | 2021-09-15 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2010-03-22 | 16 mi |
| Registration #2 | 2013-03-22 | 48.708 mi |
| Registration #3 | 2014-03-03 | 66.155 mi |
| Registration #4 | 2015-03-21 | 79.677 mi |
| Registration #5 | 2016-03-07 | 86.145 mi |
| Registration #6 | 2017-04-03 | 93.217 mi |
| Registration #7 | 2017-04-03 | 93.217 mi |
| Registration #8 | 2018-03-31 | 101.392 mi |
| Registration #9 | 2019-03-22 | 111.377 mi |
| Registration #10 | 2019-03-22 | 111.377 mi |
| Registration #11 | 2019-03-22 | 111.377 mi |
| Registration #12 | 2019-03-22 | 111.377 mi |
| Registration #13 | 2019-03-22 | 111.377 mi |
| Registration #14 | 2019-03-22 | 111.377 mi |
| Registration #15 | 2019-03-22 | 111.377 mi |

More info >



Car features

The FORD factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1973 mm |
| Height | 1481 mm |
| Length | 3950 mm |
| Kerb weight | 1141 kg |
| Max. allowed weight | 1535 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 40 l |
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats | 5 |
| Number of axles | 2 |

Engine number

9R21853