





report date: 2024-03-28

### General information

Make	FORD
Model	C-MAX ZETEC 110
Colour	Black
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	108 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/13



### Internet history

#### Entry 1

Date 2021-09-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



MOT history

MOT expiry date	2025-01-14
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	12
Total items failed	10

MOT #16	2023-12-20 14:09
MOT test number	646081504477
Result	✓ Passed
Next expiry date	2025-01-14

MOT #15	2023-12-20 14:04
MOT test number	564830606208
Result	<b>X</b> Failed
Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))	

MOT #14	2023-12-20 13:24
MOT test number	847890550947
Result	<b>X</b> Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))  Fail Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/13



MOT #13		2023-01-11 14:15
MOT test	number	149362231117
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #12	2022-01-15 19:04
MOT test number	367912981501
Result	✓ Passed
MOT #11	2021-09-15 15:57
MOT test number	472536385788
Result	<b>X</b> Failed
Fail Offside Stop lamp(s) not working (4.3.1 (a) (ii))	

MOT #10	2020-10-20 09:42
MOT test number	577776493467
Result	<b>✓</b> Passed
MOT #9	2019-04-09 14:33
MOT test number	218554602612
Result	<b>✓</b> Passed
MOT #8	2018-04-05 12:03
MOT test number	746372823990
Result	<b>✓</b> Passed
MOT #7	2017-03-29 14:32
MOT test number	468274421497
Result	<b>✓</b> Passed

CarCheck.co.uk page 4/13



**MOT #6** 2016-03-30 13:48

MOT test number 318919386578

**Result** ✓ Passed

**Advice** Offside Rear seatbelt not checked due to childseat

**Advice** Nearside Rear seatbelt not checked due to childseat

**MOT #5** 2015-04-06 18:01

MOT test number 179566195018

Result \sqrt{Passed}

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Child seat fitted not allowing full inspection of adult belt

MOT #4 2015-04-06 14:10

**MOT test number** 345536795038

Result × Failed

**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)

**Notice** Child seat fitted not allowing full inspection of adult belt

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Parking brake lever has no reserve travel (3.1.6b)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system

requires adjustment or repair. (3.7.B.5b)

CarCheck.co.uk page 5/13



MOT #3 2014-04-18 16:46 **MOT test number** 829888704167 Result ✓ Passed MOT #2 2014-02-12 16:12 **MOT test number** 366343744022 Result ✓ Passed MOT #1 2014-02-12 16:12 376073144034 **MOT test number** Result × Failed Pass with rectification Offside Headlamp aim too low (1.8) **Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)

CarCheck.co.uk page 6/13



# Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	14 January 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 7/13



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



## Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	TK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 10/13



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-29
Last registration	2023-12-20
Complete history	See info



Registration #1	2011-03-29	15 mi
Registration #2	2014-02-12	22.597 mi
Registration #3	2014-04-18	22.467 mi
Registration #4	2015-04-06	32.543 mi
Registration #5	2015-04-06	32.543 mi
Registration #6	2016-03-30	39.485 mi
Registration #7	2017-03-29	48.917 mi
Registration #8	2018-04-05	58.163 mi
Registration #9	2019-04-09	65.346 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.79 es

 $\quad \text{More info} \ \ >$ 

CarCheck.co.uk page 12/13



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1991 mm
Height	1447 mm
Length	4342 mm
Wheel base	2640 mm
Kerb weight	1413 kg
Max. allowed weight	1835 kg

## Additional information

Fuel tank capacity	55 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 13/13