



report date: 2024-03-28

General information

Make	CITROEN
Model	XSARA PICASSO SX 16V
Colour	Silver
Year of manufacture	2002
Top speed	118 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	117 BHP
Max. torque	159 Nm at 4.000 rpm
Engine capacity	1.749 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I





MOT history

MOT expiry date	2021-01-14
MOT pass rate	71 %
MOT passed	15
Failed MOT tests	6
Total advice items	46
Total items failed	35



MOT #21	2020-12-09 10:44
MOT test number	370191252727
Result	✗ Failed

- Fail** Offside Rear Brake pipe at imminent risk of failure or fracture (1.1.11 (a))
- Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Fail** Electronic braking system warning device indicates a fault (1.7 (b))
- Fail** Rear Exhaust has a major leak of exhaust gases box at welded joint (6.1.2 (a))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush (5.3.2 (c))
- Fail** Front Bonnet cannot be secured in the closed position (3.1 (b) (i))
- Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))
- Fail** Offside Front Anti-lock braking system component excessively damaged ring (1.6 (e))
- Fail** Offside Front Electronic stability control wheel speed sensor excessively damaged (7.12 (a))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

**MOT #20** 2020-01-13 11:54**MOT test number** 629037150766**Result** ✓ Passed**Advice** Rear axle corroded**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #19** 2019-01-09 15:20**MOT test number** 763059104601**Result** ✓ Passed**MOT #18** 2019-01-08 11:23**MOT test number** 521871089308**Result** ✗ Failed**Fail** Windscreen washer not working front (3.5 (a))**Fail** Exhaust carbon monoxide content after 2nd fast idle exceeds default limits (8.2.1.2 (b))**Fail** Horn not working (7.7 (a) (ii))**Fail** Tyre tread depth below requirements of 1.6mm o./s front (5.2.3 (e))**MOT #17** 2018-01-09 09:30**MOT test number** 734375802849**Result** ✓ Passed**MOT #16** 2017-01-06 09:32**MOT test number** 354095099316**Result** ✓ Passed

**MOT #15**

2016-01-12 13:32

**MOT test number**

713507642612

**Result**

✓ Passed

**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**MOT #14**

2015-01-05 12:23

**MOT test number**

786805105002

**Result**

✓ Passed

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** O/s/f wiper blad splitbut clean sufficiently**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Eml**MOT #13**

2014-01-14 16:32

**MOT test number**

896784714057

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Notice** Slight scratching to windscreen noted**Advice** Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Rear brakes noisy when applied

**MOT #12**

2014-01-14 11:22

**MOT test number**

946664514010

**Result**

✗ Failed

**Fail**

Exhaust emissions Lambda reading after 2nd fast idle outside specified limits (7.3.D.3)

**Advice**

Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Fail**

Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)

**Notice**

Engine management light on

**Fail**

Exhaust emissions hydrocarbon content after 2nd fast idle excessive (7.3.D.3)

**Notice**

Rear brakes noisy when applied

**Advice**

Nearside Front Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Fail**

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Fail**

Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)

**Notice**

Slight scratching to windscreen noted

**MOT #11**

2013-01-15 16:05

**MOT test number**

169825713093

**Result**

✓ Passed

**Notice**

Offside front tyre worn on inside edge.

**Notice**

Slight scratching to windscreen noted.

**Advice**

Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)



MOT #10 2013-01-15 09:34

MOT test number 515495513091

Result ✗ Failed

**Notice** Offside front tyre worn on inside edge.

**Fail** Nearside Front Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Notice** Slight scratching to windscreen noted.

**Advice** Nearside Front Bonded suspension unit deteriorated but can function as intended (2.4.F.3)

MOT #9 2012-01-11 15:18

MOT test number 356161312059

Result ✓ Passed

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Notice** Both front brake discs are worn.

**Notice** Rear brakes noisy when applied.

**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**Notice** Noted, slight scratching to windscreen.



**MOT #8**

2012-01-11 10:43

**MOT test number**

167241812424

**Result****✗ Failed****Notice** Rear brakes noisy when applied.**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Noted, slight scratching to windscreen.**Fail** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Both front brake discs are worn.**MOT #7**

2011-01-13 15:59

**MOT test number**

128013911431

**Result****✓ Passed****Notice** Rear brakes noisy when applied.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Noted, Slight scratching to windscreen.

**MOT #6** 2011-01-12 11:56**MOT test number** 825132711024**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Rear brakes noisy when applied.**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Notice** Noted, Slight scratching to windscreen.**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #5** 2010-01-15 10:38**MOT test number** 490765110007**Result** ✓ Passed**Notice** Rear brakes noisy when applied.**Notice** Offside front tyre wearing on inner edge.**MOT #4** 2009-01-12 15:45**MOT test number** 664862519065**Result** ✓ Passed**MOT #3** 2007-08-03 12:23**MOT test number** 950085017298**Result** ✓ Passed**Advice** Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**MOT #2** 2006-08-03 15:57**MOT test number** 211105916235**Result** ✓ Passed



MOT #1	2005-08-01 14:32
MOT test number	294233615276
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
7 January 2021

X

MOT

Expired:  
14 January 2021

Tax status	Expired at 7 January 2021
Days left	1209 days too late
MOT expiry date	14 January 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2023-03-28
Current registration	<b>XXXXXX</b>
Plate since	2023-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >





Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-06-08
Last registration	2020-12-09
Complete history	<a href="#">See info</a>



Registration #1	2002-06-08	17 mi
Registration #2	2005-08-01	26.479 mi
Registration #3	2006-08-03	33.475 mi
Registration #4	2007-08-03	40.274 mi
Registration #5	2009-01-12	46.633 mi
Registration #6	2010-01-15	55.222 mi
Registration #7	2011-01-12	62.086 mi
Registration #8	2011-01-13	62.086 mi
Registration #9	2012-01-11	68.383 mi
Registration #10	2012-01-11	68.383 mi
Registration #11	2013-01-15	74.521 mi
Registration #12	2013-01-15	74.521 mi
Registration #13	2013-01-15	74.521 mi
Registration #14	2013-01-15	74.521 mi
Registration #15	2013-01-15	74.521 mi
Registration #16	2013-01-15	74.521 mi
Registration #17	2013-01-15	74.521 mi
Registration #18	2013-01-15	74.521 mi
Registration #19	2013-01-15	74.521 mi
Registration #20	2013-01-15	74.521 mi
Registration #21	2013-01-15	74.521 mi
Registration #22	2013-01-15	74.521 mi

More info >



Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)

Dimensions & weight

Width	1752 mm
Height	1625 mm
Length	4267 mm
Wheel base	2760 mm
Kerb weight	1245 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	LT040619397