



report date: 2024-03-29

General information

Make	BMW
Model	730 730D SE
Colour	Silver
Year of manufacture	2008
Top speed	153 mph
0 - 60 mph	7.2 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	241 BHP
Max. torque	540 Nm at 1.750 rpm
Engine capacity	2.993 cc
Cylinders	6
Fuel type	Diesel
Consumption city	29.7 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	192 g/km
CO2 label	J







Internet history

Entry 1

Date	2022-01-05
Pictures	50
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-02
MOT pass rate	76 %
MOT passed	13
Failed MOT tests	4
Total advice items	41
Total items failed	11

MOT #17	2024-04-03 12:08
MOT test number	191807584306
Result	✓ Passed
Next expiry date	2025-04-02

MOT #16	2024-04-03 12:08
MOT test number	172343022477
Result	✗ Failed
Pass with rectification	Headlamp insecure (4.1.1 (c))
Pass with rectification	Bonnet cannot be secured in the closed position (3.1 (b) (i))

MOT #15	2023-03-01 13:13
MOT test number	523957561502
Result	✓ Passed
Advice	Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 2mm (5.2.3 (e))

MOT #14	2022-01-04 14:03
MOT test number	602137322563
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13**

2020-12-01 14:37

MOT test number

566042134269

Result

✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))**MOT #12**

2020-11-30 17:04

MOT test number

909638030172

Result

✗ Failed

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Central Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Offside Rear Tyre has ply or cords exposed 275/40/19 (5.2.3 (d) (ii))**Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))**Fail** Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Fail** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #11**

2019-11-01 15:45

MOT test number

256357464219

Result

✓ Passed

Advice Nearside front tyre worn on outer edge**Advice** Offside rear tyre badly worn on inner edge**Advice** Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))

**MOT #10**

2019-10-30 11:01

MOT test number

118391914661

Result

✗ Failed

Advice

Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))

Advice

Offside rear tyre badly worn on inner edge

Fail

Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))

Advice

Nearside front tyre worn on outer edge

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

MOT #9

2018-11-10 10:51

MOT test number

412546953823

Result

✓ Passed

Advice

Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice

Nearside front tyre worn on outer edge

Advice

Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

Advice

Child Seat fitted not allowing full inspection of adult belt

Advice

Brake disc worn, pitted or scored, but not seriously weakened Nearside and offside rear (1.1.14 (a) (ii))

MOT #8

2017-11-13 17:11

MOT test number

707250667611

Result

✓ Passed

Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #7**

2016-11-10 10:54

MOT test number

679976463500

Result

✓ Passed

Advice Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6**

2015-11-11 10:58

MOT test number

584195385284

Result

✓ Passed

Advice Both front tyre's worn on outside edge**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** O/s/r tyre worn on inside edge**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #5**

2015-11-11 10:58

MOT test number

853654742853

Result

✗ Failed

Advice Both front tyre's worn on outside edge**Pass with rectification** Offside Headlamp aim too low (1.8)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** O/s/r tyre worn on inside edge**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #4** 2014-10-01 10:32**MOT test number** 119464674226**Result** ✓ Passed

- Advice** Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Under-trays fitted obscuring some underside components
- Notice** Can not fully see front brake pads
- Notice** Wiper blades worn
- Advice** Coil spring corroded (2.4.C.1b)
- Advice** Front Tyre worn close to the legal limit (4.1.E.1)
- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Can not fully see rear brake pads or discs
- Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #3 2013-09-25 10:38**MOT test number** 415108063219**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Have carried out emissions test reading was 0.03 but was to clean for smoke meter to register

MOT #2 2012-09-28 09:58**MOT test number** 716822972215**Result** ✓ Passed**MOT #1** 2011-11-12 12:01**MOT test number** 398286811301**Result** ✓ Passed

- Notice** When the engine was diesel tested the emission data was 0% and therefore did not register under the test ,emission data was a pass / advise



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
2 April 2025

Tax status	Valid until 1 May
Days left	2
MOT expiry date	2 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this BMW? How many owners did this BMW have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this BMW had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-29
Current registration	
Plate since	2019-03-29

More info >



Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this BMW is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-11-01
Last registration	2024-04-03
Complete history	See info



Registration #1	2008-11-01	27 mi
Registration #2	2011-11-12	52.931 mi
Registration #3	2012-09-28	61.956 mi
Registration #4	2013-09-25	71.514 mi
Registration #5	2014-10-01	80.089 mi
Registration #6	2015-11-11	85.383 mi
Registration #7	2015-11-11	85.383 mi
Registration #8	2016-11-10	92.216 mi
Registration #9	2017-11-13	99.646 mi
Registration #10	2018-11-10	103.678 mi
Registration #11	2019-05-29	103.377 mi
Registration #12	2019-05-29	103.377 mi
Registration #13	2019-05-29	103.377 mi
Registration #14	2019-05-29	103.377 mi
Registration #15	2019-05-29	103.377 mi
Registration #16	2019-05-29	103.377 mi
Registration #17	2019-05-29	103.377 mi
Registration #18	2019-05-29	103.377 mi
Registration #19	2019-05-29	103.377 mi

More info >



Car features

The BMW factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete BMW factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1902 mm
Height	1488 mm
Length	5072 mm
Wheel base	3070 mm
Kerb weight	1940 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	28156967