



report date: 2024-03-29

General information

Make	MAZDA
Model	3 TS
Colour	Silver
Year of manufacture	2007
Top speed	113 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-02-01
Pictures	0
Listing price	View report

source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-08-29
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	30
Total items failed	8

MOT #18	2023-08-21 10:48
MOT test number	483445424138
Result	✓ Passed
Next expiry date	2024-08-29
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2023-08-21 10:48
MOT test number	595961107285
Result	✗ Failed
Pass with rectification	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Brake pedal wearing smooth (1.1.2 (c))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2022-08-30 10:54

MOT test number

340376414932

Result

✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

MOT #15

2022-08-30 10:54

MOT test number

177812785723

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Advice** Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Offside Rear Shock absorbers has a reduced damping effect (5.3.2 (d))
- Pass with rectification** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

MOT #14

2021-08-19 17:23

MOT test number

875237783866

Result

✓ Passed

- Advice** Tyre slightly damaged/cracking or perishing nearside front and offside front (5.2.3 (d) (ii))

**MOT #13** 2021-08-18 14:42**MOT test number** 888554651143**Result** ✗ Failed**Advice** Offside Rear Nail in tyre**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Tyre slightly damaged/cracking or perishing nearside front and offside front (5.2.3 (d) (ii))**Advice** Exhaust mounting defective (6.1.2 (a))**Fail** Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))**MOT #12** 2020-06-22 10:01**MOT test number** 830175631318**Result** ✗ Failed**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back eye bush (5.3.4 (a) (i))**Advice** Offside Front Driver's door hinge deteriorated but the door can still be readily opened and closed door check strap loose (6.2.3 (c) (i))**Fail** Nearside Front Lower Suspension arm pin or bush excessively worn back eye bush (5.3.4 (a) (i))**Fail** Rear Exhaust system insecure box bracket broken (6.1.2 (a))**Advice** Rear Brake pad(s) wearing thin very close to 1.5mm recommend to replace asap (1.1.13 (a) (ii))**MOT #11** 2019-06-21 08:56**MOT test number** 831001034004**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #10** 2018-06-13 10:32**MOT test number** 252621861258**Result** ✓ Passed

**MOT #9** 2017-03-06 15:56**MOT test number** 181463173705**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #8** 2016-03-09 12:07**MOT test number** 147888958826**Result** ✓ Passed**Advice** Front Valve stem slightly damaged Both, offside and nearside (4.1.D.1e)**Advice** Vehicle was presented for inspection in wet conditions**MOT #7** 2015-03-11 14:27**MOT test number** 729850575006**Result** ✓ Passed**MOT #6** 2014-03-12 12:08**MOT test number** 977221874045**Result** ✓ Passed**MOT #5** 2014-03-12 11:21**MOT test number** 369961174086**Result** ✗ Failed**Fail** Nearside Rear Tyre not fitted in accordance with side wall instructions (4.1.D.1f)**MOT #4** 2013-03-12 12:20**MOT test number** 548501873001**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components



MOT #3	2012-03-15 12:14
MOT test number	927355272020
Result	✓ Passed
<div>Notice Nail in nearside rear tyre</div>	

MOT #2	2011-03-17 12:00
MOT test number	665166771065
Result	✓ Passed

MOT #1	2010-03-05 14:52
MOT test number	193894660457
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
29 August 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	29 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-03-22
Last registration	2023-08-21
Complete history	See info



Registration #1	2007-03-22	14 mi
Registration #2	2010-03-05	11.399 mi
Registration #3	2011-03-17	21.035 mi
Registration #4	2012-03-15	31.424 mi
Registration #5	2013-03-12	41.965 mi
Registration #6	2014-03-12	49.145 mi
Registration #7	2014-03-12	49.145 mi
Registration #8	2015-03-11	57.843 mi
Registration #9	2016-03-09	64.840 mi
Registration #10	2017-03-06	72.212 mi
Registration #11	2018-03-06	80.000 mi
Registration #12	2019-03-06	88.000 mi
Registration #13	2020-03-06	96.000 mi
Registration #14	2021-03-06	104.000 mi
Registration #15	2022-03-06	112.000 mi
Registration #16	2023-03-06	120.000 mi
Registration #17	2024-03-06	128.000 mi
Registration #18	2025-03-06	136.000 mi
Registration #19	2026-03-06	144.000 mi
Registration #20	2027-03-06	152.000 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1465 mm
Length	4420 mm
Wheel base	2640 mm
Kerb weight	1320 kg
Max. allowed weight	1725 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z6 569538