





report date: 2024-03-29

### General information

Make	BMW
Model	316 316I SE
Colour	Silver
Year of manufacture	-
Top speed	124 mph
0 - 60 mph	11.9 seconds
Gearbox	5 speed automatic

### Engine & fuel consumption

Power	115 BHP
Max. torque	175 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.1 mpg
Consumption combined	35.3 mpg



CarCheck.co.uk page 1/12



# Internet history


### Entry 1

Date 2021-10-31

Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



#### **MOT** history

MOT #18	2021-01-06 10:38
MOT #18	2021-01-06 10:38

**MOT test number** 835144099074

Next expiry date 2022-01-22

**MOT #17** 2021-01-05 16:08

**MOT test number** 368565275148

**Result** X Failed

**DANGEROUS** Front Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))

**MAJOR** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MAJOR Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick both (1.1.13 (a) (ii))

**MOT #16** 2019-12-30 11:31

MOT test number 757382608604

**Result** ✓ Passed

**MOT #15** 2019-01-23 14:36

**MOT test number** 948831517778

Result 

Passed

Advice Oil leak, but not excessive (8.4.1 (a) (i))

CarCheck.co.uk page 3/12



**MOT #14** 2019-01-22 12:15

**MOT test number** 583348482593

Result × Failed

MAJOR Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))

MAJOR Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #13** 2017-11-13 10:46

MOT test number 747495175513

Result \rightarrow Passed

**MOT #12** 2016-12-15 15:24

MOT test number 610674314363

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #11** 2016-12-15 15:24

MOT test number 913118424737

Result × Failed

**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

CarCheck.co.uk page 4/12



**MOT #10** 2015-11-26 09:41

**MOT test number** 144713101437

MOT #9 2014-10-27 12:37

**MOT test number** 685430404330

**Result** ✓ Passed

**MOT #8** 2013-11-28 17:26

**MOT test number** 526552933321

Result \( \sqrt{Passed} \)

MOT #7 2013-11-27 16:42

**MOT test number** 709281633386

**Result** X Failed

**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #6 2012-10-12 09:53

**MOT test number** 395846682225

**Result** 
✓ Passed

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #5 2011-10-14 11:07

MOT test number 697167281227

Result \( \sqrt{Passed} \)

**Advice** Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

MOT #4 2010-03-16 11:35

MOT test number 313175970020

CarCheck.co.uk page 5/12



MOT #3 2009-03-16 12:56

**MOT test number** 683785679067

**Result** 
✓ Passed

MOT #2 2008-02-22 09:20

**MOT test number** 554793958054

Result Passed

**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #1 2006-10-20 08:37

**MOT test number** 221633696204

**Result** ✓ Passed

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this BMW. See if, where and when this BMW had damage and the car repair costs. We also check if this BMW was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra BMW salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this BMW in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



$\alpha$	ner	hict	001
UVV	пег	msi	$\mathbf{o}\mathbf{r}$
		11100	<b>U</b> 1

For how long did the current and previous owner(s) have this BMW? How many owners d Check it in the premium report and see all owner registrations. Download the full report <u>l</u>	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this BMW had different number plates.	
Number of plates	,
Current registration	NK NK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this BMW is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this BMW has been settled.

If not, and you buy this BMW then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this BMW is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



# Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2002-11-01
Last registration	2021-01-06
Complete history	See info



Registration #1	2002-11-01	29 mi
Registration #2	2006-10-20	27.986 mi
Registration #3	2008-02-22	31.996 mi
Registration #4	2009-03-16	35.443 mi
Registration #5	2010-03-16	39.578 mi
Registration #6	2011-10-14	44.109 mi
Registration #7	2012-10-12	46.340 mi
Registration #8	2013-11-27	50.959 mi
Registration #9	2013-11-28	50.959 mi
Registration #10	2014-10-27	52.829 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		10.777 es

More info >

CarCheck.co.uk page 11/12



### Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1932 mm
Height	1415 mm
Length	4471 mm
Wheel base	2725 mm
Kerb weight	1415 kg

## Additional information

Fuel tank capacity	63 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Engine number	A595G796

CarCheck.co.uk page 12/12