



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	CLK CLK320 CDI SPORT
Colour	Grey
Year of manufacture	2009
Top speed	153 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.7 mpg
CO2 emission	205 g/km
CO2 label	K





Internet history

Entry 2

Date	2021-08-10
Pictures	12
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-07-03
Pictures	23
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-04-05
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	23
Total items failed	3

MOT #15	2024-03-30 11:31
MOT test number	797365236123
Result	✓ Passed
Next expiry date	2025-04-05
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-03-11 10:09
MOT test number	608197070970
Result	✓ Passed

MOT #13	2022-03-26 12:36
MOT test number	206647979406
Result	✓ Passed

**MOT #12** 2021-04-06 14:49**MOT test number** 969709137005**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Parking brake just made 16% efficiency
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened all brake discs (1.1.14 (a) (ii))

**MOT #11** 2020-03-17 15:10**MOT test number** 856458504690**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #10** 2020-03-16 10:33**MOT test number** 940427373429**Result** ✗ Failed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Minor** Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-02-15 16:44**MOT test number** 416660692413**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #8** 2018-02-09 20:04**MOT test number** 808424501280**Result** ✓ Passed**MOT #7** 2017-03-08 16:51**MOT test number** 633097452874**Result** ✓ Passed**MOT #6** 2016-04-29 10:10**MOT test number** 138510214748**Result** ✓ Passed**Advice** Engine covers fitted**Advice** Undertrays fitted**MOT #5** 2015-05-01 10:23**MOT test number** 526191025197**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2014-03-26 17:28**MOT test number** 338395084083**Result** ✓ Passed



MOT #3	2013-04-26 09:46
MOT test number	226176713131
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Nearside front and rear tyre sidewall damage
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #2	2012-04-13 16:10
MOT test number	619274102196
Result	✓ Passed

MOT #1	2012-04-13 16:10
MOT test number	447184602174
Result	✗ Failed
Pass with rectification	Nearside Front Headlamp aim too low (1.8)
Pass with rectification	Front registration plate missing (6.3.1a)
Pass with rectification	Offside Front Headlamp aim too low (1.8)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 October 2024

✓  
**MOT**  
**Expires:**  
5 April 2025

<b>Tax status</b>	Valid until 1 October
<b>Days left</b>	156
<b>MOT expiry date</b>	5 April 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-05-29
Last registration	2024-03-30
Complete history	<a href="#">See info</a>



Registration #1	2009-05-29	9 mi
Registration #2	2012-04-13	40.209 mi
Registration #3	2013-04-26	43.012 mi
Registration #4	2014-03-26	45.322 mi
Registration #5	2015-05-01	50.128 mi
Registration #6	2016-04-29	52.881 mi
Registration #7	2017-03-08	56.234 mi
Registration #8	2018-02-09	56.273 mi
Registration #9	2019-02-15	71.988 mi
Registration #10	2020-02-15	75.277 mi
Registration #11	2021-02-15	75.277 mi
Registration #12	2022-02-15	75.277 mi
Registration #13	2023-02-15	75.277 mi
Registration #14	2024-02-15	75.277 mi
Registration #15	2025-02-15	75.277 mi
Registration #16	2026-02-15	75.277 mi
Registration #17	2027-02-15	75.277 mi

More info >



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1660 kg
Max. allowed weight	2115 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	64291040717818