





report date: 2024-03-28

## General information

| Make                | MINI                |  |
|---------------------|---------------------|--|
| Model               | ONE COOPER HIGHGATE |  |
| Colour              | White               |  |
| Year of manufacture | 2014                |  |
| Top speed           | 123 mph             |  |
| 0 - 60 mph          | 9.8 seconds         |  |
| Gearbox             | 6 speed Manual      |  |

## Engine & fuel consumption

| Power                   | 120 BHP             |
|-------------------------|---------------------|
| Max. torque             | 160 Nm at 4.250 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 39.2 mpg            |
| Consumption extra urban | 57.7 mpg            |
| Consumption combined    | 49.6 mpg            |
| CO2 emission            | 133 g/km            |
| CO2 label               | E                   |



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

## Entry 3

Date 2021-09-16

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

#### Entry 2

| Date | 2021-07-31 |
|------|------------|
|------|------------|

Pictures 21

Listing price <u>View report</u>









source: yesauto.com

Entry 1

Date 2021-05-24

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

# MOT history

| MOT expiry date    | 2025-01-10 |
|--------------------|------------|
| MOT pass rate      | 75 %       |
| MOT passed         | 6          |
| Failed MOT tests   | 2          |
| Total advice items | 8          |
| Total items failed | 4          |

| MOT #8  | 2023-12-28 13:44 |  |
|---|------------------|--|
| MOT test number   | 954542574021     |  |
| Result  | ✓ Passed         |  |
| Next expiry date  | 2025-01-10       |  |
| Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i)) |                  |  |

| MOT #7   |   | 2023-01-11 15:56    |
|--|---|---------------------|
| MOT test   | number  | 564749392946        |
| Result   |   | ✓ Passed            |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))      |                     |
| Minor  | Registration plate lamp inoperative in the case of multiple lamps or light sour | ces (4.7.1 (b) (i)) |
| Advice Front Tyre slightly damaged/cracking or perishing both front (also wearing on edges) (5.2.3 (d) (ii)) |   | n edges) (5.2.3 (d) |

| MOT #6                  |  | 2022-01-07 09:31 |
|-------------------------|--|------------------|
| MOT test number         |  | 480649416239     |
| Result                  |  | ✓ Passed         |
|                         |  |                  |
| MOT #5                  |  | 2022-01-07 09:31 |
| MOT test number         |  | 777971012179     |
| Result                  |  | <b>×</b> Failed  |
| Pass with rectification | Offside Front Position lamp not working (4.2.1 (a) (ii)) |                  |

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #4 2021-03-23 11:43

**MOT test number** 670263809311

**Result** ✓ Passed

MOT #3 2021-03-23 11:43

**MOT test number** 629242657524

Result X Failed

**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))

Pass with rectification Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))

**Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))

MOT #2 2019-10-04 08:54

MOT test number 753255595772

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #1 2018-02-27 13:48

MOT test number 855767895633

Result \( \sqrt{Passed} \)

Advice Nearside Front Tyre worn close to the legal limit both inner and outer edges worn (4.1.E.1)

**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit both inner and outer edges worn (4.1.E.1)

CarCheck.co.uk page 4/11



report date: 2024-03-28

## Tax & MOT check



| Tax status       | Valid until 1 January |
|------------------|-----------------------|
| Days left        | 248                   |
| MOT expiry date  | 10 January 2025       |
| Full MOT history | See MOT history       |

## Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | E          |
| Single payment (12 months)              | £ 180,00,- |
| Single six month payment                | £ 99,00,-  |
| Total payable by 12 monthly instalments | £ 189,00,- |

CarCheck.co.uk page 5/11



report date: 2024-03-28

## Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| $\sim$   |         |    |      |    |
|----------|---------|----|------|----|
| -( )v    | vner    | hi | ะะก  | ı۲ |
| $\sim$ v | V I C I |    | ,,,, |    |

| For how long did the current and previous owner(s) have this MINI? How many owners did Check it in the premium report and see all owner registrations. Download the full report I  |           | e? |
|--|-----------|----|
|  |           |    |
| manage of the same |           |    |
| ***************************************  |           |    |
|  |           |    |
| *********  |           |    |
|  |           |    |
| ***************************************  |           |    |
|  | More info | >  |
| Plate changes  |           |    |
| See in this check if this MINI had different number plates.  |           |    |
| Number of plates   |           | 9  |
| Current registration   | NK NE     |    |
| Plate since  |           |    |
| Current registration   | OK NE     |    |
| Plate since  |           |    |
|  | More info | >  |

CarCheck.co.uk page 8/11



report date: 2024-03-28

## Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2014-06-04 |
| Last registration          | 2023-12-28 |
| Complete history           | See info   |



| Registration #1  | 2014-06-04 | 21 mi     |
|------------------|------------|-----------|
| Registration #2  | 2018-02-27 | 27.417 mi |
| Registration #3  | 2019-10-04 | 36.875 mi |
| Registration #4  | 2021-03-23 | 41.463 mi |
| Registration #5  | 2021-03-23 | 41.463 mi |
| Registration #6  |            | 11.777 es |
| Registration #7  |            | 11.777 es |
| Registration #8  |            | 11.117 es |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.117 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

# Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 50501 |                  |
| 50566 |                  |
| 50567 |                  |
| 50569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1683 mm |
|---------------------|---------|
| Height              | 1414 mm |
| Length              | 3723 mm |
| Wheel base          | 2467 mm |
| Kerb weight         | 1165 kg |
| Max. allowed weight | 1595 kg |

# Additional information

| Fuel tank capacity                | 40 I                  |
|-----------------------------------|-----------------------|
| Fuel delivery                     | Multi-Point Injection |
| Number of doors                   | 2                     |
| Number of seats<br>CarCheck.co.uk | 4 page 11/1           |

Number of axles2Engine numberA309J692