



report date: 2024-03-29

General information

Make	CITROEN
Model	C5 HDI VTR PLUS
Colour	Blue
Year of manufacture	2009
Top speed	122 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	155 g/km
CO2 label	G





MOT history

MOT expiry date	2021-07-16
MOT pass rate	53 %
MOT passed	9
Failed MOT tests	8
Total advice items	39
Total items failed	32

MOT #17	2020-07-17 16:36
MOT test number	931543674703
Result	✓ Passed
Next expiry date	2021-07-16
Minor	Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Front Rear bush slightly worn
Advice	Slight oil leak
Advice	Anti-roll bar linkage ball joint has slight play Both nearside (5.3.4 (a) (i))

**MOT #16**

2020-07-17 11:21

MOT test number

609456959904

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Anti-roll bar linkage ball joint has slight play Both nearside (5.3.4 (a) (i))
- Advice** Nearside Front Rear bush slightly worn
- Fail** Offside Front Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Front Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Slight oil leak
- Fail** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #15

2019-07-18 15:55

MOT test number

816085648165

Result**✓ Passed**

- Advice** Engine oil leaks
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))

**MOT #14**

2018-06-29 14:55

MOT test number

923087958579

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Back of undertray fitted with cable tie**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #13**

2018-06-27 11:14

MOT test number

129636395569

Result

✗ Failed

Fail Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Offside Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Power steering fluid reservoir empty (2.1.5 (b) (ii))**Advice** Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Back of undertray fitted with cable tie**Fail** Power steering component leaking steering rack (2.1.5 (a))



MOT #12	2017-07-03 15:54
MOT test number	451122301827
Result	✓ Passed
Advice	Gearbox mounting defective

MOT #11	2017-06-29 11:38
MOT test number	278700843654
Result	✗ Failed
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Offside Rear Seat belt locking mechanism does not secure or release (5.2.5a)
Advice	Gearbox mounting defective
Fail	Offside Front position lamp(s) not working (1.1.A.3b)

MOT #10	2016-06-22 15:34
MOT test number	299470644920
Result	✓ Passed

MOT #9	2016-06-20 11:22
MOT test number	554724599066
Result	✗ Failed
Fail	Horn not working (1.6.2a)
Fail	Offside Registration plate lamp not working (1.1.C.1d)
Fail	Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Nearside Front Steering rack gaiter split (2.2.D.2d)



MOT #8	2015-06-26 15:08
MOT test number	298097175420
Result	✓ Passed
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)

MOT #7	2015-06-24 10:07
MOT test number	325315575183
Result	✗ Failed
Advice	Offside Front Anti-roll bar linkage rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Advice	Offside Front wheel bearing has slight play (2.5.A.3c)
Fail	Power steering pipe(s) or hose(s) leaking (2.3.3b)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #6	2014-06-26 15:18
MOT test number	638937774170
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #5	2014-06-26 11:04
MOT test number	255747574497
Result	✗ Failed
Fail	Power steering fluid level below minimum (2.3.1)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2013-06-26 17:30**MOT test number** 767757673137**Result** ✓ Passed**MOT #3** 2013-06-26 11:59**MOT test number** 335977773122**Result** ✗ Failed**Fail** Power steering component(s) leaking (2.3.3b)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #2** 2012-06-27 12:14**MOT test number** 965299172174**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1

2012-06-27 10:16

MOT test number

188589172146

Result

✗ Failed

Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail

Offside Windscreen washer provides insufficient washer liquid (8.2.3)

Notice

Slight scoring on both rear brake discs

Fail

Offside Headlamp not working on dipped beam (1.7.5a)

Fail

Offside Headlamp aim not tested (1.8.A.1c)

Fail

Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)

Fail

Nearside Headlamp not working on dipped beam (1.7.5a)

Notice

Nail in nearside rear tyre

Fail

Nearside Headlamp aim not tested (1.8.A.1c)

Fail

Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)



Tax & MOT check

✕
Untaxed

Tax expired:
4 November 2020

✕
MOT

Expired:
16 July 2021

Tax status

Expired at 4 November 2020

Days left

1273 days too late

MOT expiry date

16 July 2021

Full MOT history

[See MOT history](#)

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-06-25
Last registration	2020-07-17
Complete history	See info



Registration #1	2009-06-25	28 mi
Registration #2	2012-06-27	64.545 mi
Registration #3	2012-06-27	64.545 mi
Registration #4	2013-06-26	79.317 mi
Registration #5	2013-06-26	79.317 mi
Registration #6	2014-06-26	99.093 mi
Registration #7	2014-06-26	99.093 mi
Registration #8	2015-06-24	117.250 mi
Registration #9	2015-06-26	117.274 mi
Registration #10	2016-06-26	135.317 mi
Registration #11	2016-06-26	135.317 mi
Registration #12	2017-06-26	153.317 mi
Registration #13	2017-06-26	153.317 mi
Registration #14	2018-06-26	171.317 mi
Registration #15	2018-06-26	171.317 mi
Registration #16	2019-06-26	189.317 mi
Registration #17	2019-06-26	189.317 mi
Registration #18	2020-07-17	207.317 mi

More info >



Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)

Dimensions & weight

Width	1853 mm
Height	1471 mm
Length	4829 mm
Wheel base	2750 mm
Kerb weight	1655 kg
Max. allowed weight	2276 kg

Additional information

Fuel tank capacity	71 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	DYXH4018926