





report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD TYPE-V
Dur Green	
Year of manufacture	2002
Top speed	131 mph
0 - 60 mph	9.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	206 Nm at 4.700 rpm
Engine capacity	2.254 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.7 mpg
Consumption extra urban	40.4 mpg
Consumption combined	32.1 mpg
CO2 emission	209 g/km
CO2 label	K



CarCheck.co.uk page 1/15



report date: 2024-03-29

Internet history

Entry 2

Date 2021-07-05

Pictures 6

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date	2021-06-28

Pictures 7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/15



MOT history

MOT expiry date	2021-07-07	
MOT pass rate	65 %	
MOT passed	15	
Failed MOT tests	8	
Total advice items	31	
Total items failed	17	

MOT #23		2020-07-08 11:29
MOT test	number	519767452563
Result		✓ Passed
Next expi	ry date	2021-07-07
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #22		2020-07-08 11:29
MOT test number		138229643842
Result		x Failed
Pass with rectificat	Offside Parking brake inoperative on one side (1.4.1 (a))	
Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
Advice Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))		
Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))		
Advice Offside Rea	ar Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/15



report date: 2024-03-29

MOT #21

MOT test number

Result

Advice Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT test number

Result

Pass with rectification

Offside Parking brake inoperative on one side (1.4.1 (a))

Advice

Nearside Front Service brake binding but not excessively (1.2.1 (f))

MOT #19

MOT test number

Result

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #18

MOT test number

Result

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Pass with rectification

Offside Headlamp not working on dipped beam (1.7.5a)

 MOT #17
 2017-03-02 12:44

 MOT test number
 861796948978

 Result
 ✓ Passed

CarCheck.co.uk page 4/15



report date: 2024-03-29

MOT test number

Result

Pass with rectification

Nearside Front front brake binding (3.7.B.1)

Pass with rectification

Offside Front front brake binding (3.7.B.1)

MOT test number
627325871892

Result

Advice Underbody light rust in places

Advice Light rust exhaust joints and front/rear brake disc surfaces

Advice Plastic trim fitted underbody

Advice Power steering rack o/s gaitor damp

2016-03-22 11:04 **MOT #14** 698471561694 **MOT** test number Result × Failed **Advice** Light rust exhaust joints and front/rear brake disc surfaces Fail Offside Rear Registration plate lamp not working (1.1.C.1d) Fail Offside Front Subframe mounting prescribed area is excessively corroded inner wing (2.4.A.3) **Advice** Plastic trim fitted underbody **Advice** Power steering rack o/s gaitor damp Fail Nearside Front Headlamp not working on dipped beam (1.7.5a) Fail Offside Front Steering rack gaiter split (2.2.D.2d) Advice Underbody light rust in places

CarCheck.co.uk page 5/15



report date: 2024-03-29

MOT #13

MOT test number

Fesult

Notice

Under-trays fitted obscuring some underside components

2015-02-13 13:08

555204045042

✓ Passed

MOT test number
625354645057

Result

Pass with rectification
Offside Front position lamp(s) not working (1.1.A.3b)

Pass with rectification
Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification
Nearside Rear Stop lamp not working (1.2.1b)

Notice
Under-trays fitted obscuring some underside components

MOT #11

MOT test number 659718444000

Result Passed

Notice N/s o/s outer sills plastic trim fitted

Notice Rear brake discs rusted

2014-02-17 10:46 **MOT #10 MOT** test number 476408244043 Result × Failed **Notice** N/s o/s outer sills plastic trim fitted Fail Offside rear brake binding (3.7.B.1) Fail Offside Front Steering rack gaiter split (2.2.D.2d) **Notice** Rear brake discs rusted Nearside front brake binding (3.7.B.1) Fail

CarCheck.co.uk page 6/15



Fail

Fail

Result

RV02BVA

report date: 2024-03-29

✓ Passed

MOT #9		2013-02-09 10:23
MOT test n	umber	839950743048
Result		✓ Passed
Notice	Nail in offside front tyre	
Advice	Offside Rear rear brake grabbing slightly (3.7.A.5b)	

MOT #8		2012-02-04 09:39
MOT test	number	845375832007
Result		✓ Passed
Notice	Chips in windscreen	
Notice	Clutch fluid level at minimum	

MOT #7	2011-02-04 14:59
MOT test number	588545131077
Result	✓ Passed
MOT #6	2011-02-02 12:09
MOT test number	645783631049
Result	X Failed

2010-02-08 15:19
112949030458

Nearside Windscreen washer provides insufficient washer liquid (8.2.3)

Offside Rear position lamp(s) not working (1.1.A.3b)

CarCheck.co.uk page 7/15



MOT #4		2009-08-17 11:53
MOT test	number	823469429210
Result		√ Passed
Notice	Headlamp masks/converters fitted	

Notice Headlamp masks/converters fitted	
MOT #3	2008-11-01 09:39
MOT test number	934656308325
Result	✓ Passed
MOT #2	2007-10-31 15:13
MOT test number	194424907352
Result	✓ Passed
MOT #1	2006-08-14 09:44
MOT test number	693016426289
Result	✓ Passed

CarCheck.co.uk page 8/15



Tax & MOT check

Tax expired: 6 June 2021



х мот

Expired: 7 July 2021

Tax status	Expired at 6 June 2021
Days left	1059 days too late
MOT expiry date	7 July 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 9/15



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 10/15



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 11/15



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
HARMAN CO. C.	

THE PARTY OF THE P	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Wombers of states	
Mariner or press	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 12/15



report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 13/15



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2002-03-06
Last registration	2020-07-08
Complete history	See info



Registration #1	2002-03-06	15 mi
Registration #2	2006-08-14	26.766 mi
Registration #3	2007-10-31	34.199 mi
Registration #4	2008-11-01	39.608 mi
Registration #5	2009-08-17	43.820 mi
Registration #6	2010-02-08	47.909 mi
Registration #7	2011-02-02	57.412 mi
Registration #8	2011-02-04	57.448 mi
Registration #9	2012-02-04	64.594 mi
Registration #10	2013-02-09	72.182 mi
Registration #11	2014-02-17	73.829 mi
Registration #12	2014-02-17	73.829 mi
Registration #13	2015-02-13	74.891 mi
Registration #14		11.777 es
Registration #15		D.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		19.777 es
negistration // Es		
Registration #24		11.177 mg



Safety ratings

NCAP	rating					
110/11			- ×	•	Prof.	

Video <u>see crash video</u>



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm

Additional information

Fuel tank capacity	65 I
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of axles	2
Engine number	F23Z5E400896

CarCheck.co.uk page 15/15