



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN TDI SE 5STR
Colour	Grey
Year of manufacture	2009
Top speed	110 mph
0 - 60 mph	13.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	156 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-08-29
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-04
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	15
Total items failed	9

MOT #16	2023-08-02 07:28
MOT test number	294506461201
Result	✓ Passed
Next expiry date	2024-08-04

MOT #15	2023-07-27 08:04
MOT test number	253104590818
Result	✗ Failed
Fail	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
Fail	Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))

MOT #14	2022-08-01 08:07
MOT test number	434255743773
Result	✓ Passed

MOT #13	2022-07-29 10:34
MOT test number	905927555896
Result	✗ Failed
Fail	Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))
Fail	Central Rear Seat belt not functioning as intended twisted (7.1.2 (c))

**MOT #12** 2021-08-05 15:26**MOT test number** 434126955816**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**Advice** N/s rear shock absorber upper casing loose**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**Advice** Undertray not fully secure (8.1.1 (b) (i))**MOT #11** 2021-08-04 08:53**MOT test number** 838924554169**Result** ✗ Failed**Advice** Undertray not fully secure (8.1.1 (b) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge wearing on inner edge (5.2.3 (e))**Advice** N/s rear shock absorber upper casing loose**Fail** Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on inner edge (5.2.3 (e))**MOT #10** 2020-07-27 13:51**MOT test number** 652730939044**Result** ✓ Passed**MOT #9** 2019-07-12 08:58**MOT test number** 924031841323**Result** ✓ Passed

**MOT #8** 2018-07-13 07:48**MOT test number** 156109642062**Result** ✓ Passed**MOT #7** 2018-07-05 08:33**MOT test number** 275519762819**Result** ✗ Failed**Fail** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2017-07-22 11:56**MOT test number** 190118527703**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin wearing low visually through road wheels (3.5.1g)**Advice** 3rd row passenger seats/belts not inspected**Advice** Offside Rear coil spring corroded (2.4.C.1b)**MOT #5** 2016-07-04 08:51**MOT test number** 250926300041**Result** ✓ Passed**MOT #4** 2015-07-16 12:02**MOT test number** 907267095111**Result** ✓ Passed



MOT #3	2014-07-03 12:50
MOT test number	387594284123
Result	✓ Passed
MOT #2	2013-08-02 12:08
MOT test number	546864313228
Result	✓ Passed
MOT #1	2012-07-16 13:35
MOT test number	988778992173
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
4 August 2024

Tax status	Valid until 1 September
Days left	126
MOT expiry date	4 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2019-01-01
Current registration	XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2009-09-02
Last registration	2023-08-02
Complete history	See info



Registration #1	2009-09-02	29 mi
Registration #2	2012-07-16	19.084 mi
Registration #3	2013-08-02	29.419 mi
Registration #4	2014-07-03	37.182 mi
Registration #5	2015-07-16	43.910 mi
Registration #6	2016-07-04	53.306 mi
Registration #7	2017-07-22	61.506 mi
Registration #8	2018-07-05	69.415 mi
Registration #9	2018-07-13	69.472 mi
Registration #10	2019-06-20	75.377 mi
Registration #11	2019-06-20	75.377 mi
Registration #12	2019-06-20	75.377 mi
Registration #13	2019-06-20	75.377 mi
Registration #14	2019-06-20	75.377 mi
Registration #15	2019-06-20	75.377 mi
Registration #16	2019-06-20	75.377 mi
Registration #17	2019-06-20	75.377 mi
Registration #18	2019-06-20	75.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	


View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2066 mm
Height	1635 mm
Length	4391 mm
Wheel base	2677 mm
Kerb weight	1498 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Engine number	BXE 733752