





General information

Make	VOLKSWAGEN
Model	GOLF LUNA (80BHP)
Colour	Silver
Year of manufacture	2008
Top speed	102 mph
0 - 60 mph	15.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	79 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.3 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.2 mpg
CO2 emission	169 g/km
CO2 label	Н







Internet history

Entry 1	
Date	2021-02-06
Pictures	10
Listing price	View report









source: autoonline.co.uk



MOT history

MOT expiry date	2024-02-16
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	25
Total items failed	2

MOT #16	2023-02-17 07:09	
MOT test number	980694567334	
Result	✓ Passed	
Next expiry date 2024-02		
Advice Suspension component corroded but not seriously weakened rear subframe (5.3.3 (b) (i))		

MOT #15		2021-10-06 16:14
MOT test	number	544967350614
Result		✓ Passed
Advice	Central Gearbox mounting defective	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	





MOT #14		2021-10-06 12:36
MOT test	number	981319171716
Result		🗙 Failed
MAJOR	Front Exhaust has a major leak of exhaust gases flexi (6.1.2 (a))	
MAJOR	Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)))
Advice	Central Gearbox mounting defective	
MAJOR	Windscreen washer provides insufficient washer liquid (3.5 (a))	
Advice	Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear Tyre slightly damaged/cracking or perishing both sides (5.2.3 (d) (ii))	

MOT #13	2020-08-04 07:56
MOT test number	813588456701
Result	✓ Passed
Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #12	2019-07	7-16 16:37
MOT test	number 9431	67971232
Result		✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.3 (d) (ii))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.3 (d) (ii))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.3 (d) (ii))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.3 (d) (ii))	





MOT #11		2019-07-15 10:23
MOT test	number	479052640951
Result		🗙 Failed
Advice	Offside Front Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.3	(d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.3	(d) (ii))
MAJOR	Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice	Nearside Front Tyre slightly damaged/cracking or perishing 195/65x15h (5.2	.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing 195/65x15h (5.2.	3 (d) (ii))

MOT #10	2018-07-19 15:43
MOT test number	648295087799
Result	✓ Passed

MOT #9		2018-07-19 10:57
MOT test	number	731421949332
Result		🗙 Failed
MAJOR	Offside Rear Service brake excessively binding (1.2.1 (f))	

MOT #8	2017-11-14 09:10
MOT test number	208857236320
Result	✓ Passed
MOT #7	2016-09-27 08:50
MOT test number	582386249247
Result	✓ Passed



SY58MPE report date: 2024-03-29

МОТ #6	2015-09-30 12:37
MOT test number	479799303043
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
MOT #5	2015-09-30 09:35
MOT test number	948738881884
Result	🗙 Failed
Advice Front Brake pad(s) wearing thin (3.5.1g)	
Fail Offside Rear Tyre has a tear, caused by separation or partial failure of its structu	re (4.1.D.1b)
FailNearside Rear Tyre has a tear, caused by separation or partial failure of its structure 195/65r15(4.1.D.1b)	

МОТ #4	2014-07-22 09:57
MOT test number	905543504214
Result	✓ Passed
Notice N/s/f tyre perished	
Notice O/s/f tyre perished	

MOT #3	2013-08-01 15:52
MOT test number	389813313294
Result	✓ Passed

MOT #2	2012-09-10 15:36
MOT test number	998864052223
Result	✓ Passed

MOT #1	2011-09-13 11:56
MOT test number	165336951225
Result	✓ Passed



Tax & MOT check

X Untaxed Tax expired: 16 February 2024	X MOT 16 February 2024
Tax status	Expired at 16 February 2024
Days left	74 days too late
MOT expiry date	16 February 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CAT ON
Date	*
Category	AMP
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ANALY AND A ANALY ANY ANY ANY ANY ANY ANY ANY ANY ANY AN	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate sites	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-09-23
Last registration	2023-02-17
Complete history	<u>See info</u>



Registration #1	2008-09-23	17 mi
Registration #2	2011-09-13	17.753 mi
Registration #3	2012-09-10	23.410 mi
Registration #4	2013-08-01	29.278 mi
Registration #5	2014-07-22	31.283 mi
Registration #6	2015-09-30	33.717 mi
Registration #7	2015-09-30	33.717 mi
Registration #8	2016-09-27	35.330 mi
Registration #9	2017-11-14	37.143 mi
Registration #10		11.777 est
Registration #11		11.777 esi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 mi
Registration #17		11.777 mi
Registration #18		11.117 est





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1759 mm
Height	1580 mm
Length	4206 mm
Wheel base	2578 mm
Kerb weight	1468 kg
Max. allowed weight	1900 kg
Additional information	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	BUD 446735