



**YF59KCO**

report date: 2024-03-28

General information

Make	MAZDA
Model	3 TS
Colour	White
Year of manufacture	2010
Top speed	117 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-02-01
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-12-02
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	31
Total items failed	5

MOT #14	2023-11-23 14:44
MOT test number	854934035180
Result	✓ Passed
Next expiry date	2024-12-02

MOT #13	2023-11-21 08:11
MOT test number	777134522143
Result	✗ Failed
Fail	Emissions unable to be completed (8.2.1.2 (d))
Fail	Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))

MOT #12	2022-12-03 08:52
MOT test number	158965195892
Result	✓ Passed

MOT #11	2021-12-02 13:42
MOT test number	743571938937
Result	✓ Passed

**MOT #10** 2021-01-03 16:51**MOT test number** 200442560760**Result** ✓ Passed**MOT #9** 2019-06-10 11:35**MOT test number** 812207907598**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Chip in windscreen
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 1.8mm (5.2.3 (e))

**MOT #8** 2018-06-12 16:56**MOT test number** 340742031754**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive Both side inner sill (5.3.6 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Front wipers smearing
- Advice** Oil leak, but not excessive mist of oil on Engine (8.4.1 (a) (i))

**MOT #7** 2018-06-12 08:39**MOT test number** 509551028582**Result** ✗ Failed**Advice** Front wipers smearing**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Oil leak, but not excessive mist of oil on Engine (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive Both side inner sill (5.3.6 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #6** 2017-06-02 16:40**MOT test number** 493440285953**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #5** 2017-06-01 14:13**MOT test number** 509122241673**Result** ✗ Failed**Fail** Front Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)**MOT #4** 2016-05-31 10:51**MOT test number** 989480909842**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #3** 2015-06-01 16:37**MOT test number** 167672655164**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #2** 2014-05-22 11:36**MOT test number** 716382044137**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**MOT #1** 2013-06-11 12:04**MOT test number** 545382263198**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Notice** Nearside front tyre perished and cracked - cords NOT exposed.



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
2 December 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	278
<b>MOT expiry date</b>	2 December 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	<b>YF59KCO</b>
Plate since	2019-09-28
Current registration	<b>YF59KCO</b>
Plate since	2019-09-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-02-22
Last registration	2023-11-23
Complete history	<a href="#">See info</a>



Registration #1	2010-02-22	15 mi
Registration #2	2013-06-11	15.468 mi
Registration #3	2014-05-22	31.977 mi
Registration #4	2015-06-01	51.317 mi
Registration #5	2016-05-31	57.460 mi
Registration #6	2017-06-01	65.825 mi
Registration #7	2017-06-02	65.846 mi
Registration #8	2018-06-12	76.704 mi
Registration #9	2019-05-20	76.704 mi
Registration #10	2019-05-20	76.704 mi
Registration #11	2019-05-20	76.704 mi
Registration #12	2019-05-20	76.704 mi
Registration #13	2019-05-20	76.704 mi
Registration #14	2019-05-20	76.704 mi
Registration #15	2019-05-20	76.704 mi
Registration #16	2019-05-20	76.704 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4580 mm
Wheel base	2640 mm
Kerb weight	1235 kg
Max. allowed weight	1745 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	Z6 862414