





report date: 2024-03-28

General information

Make	PEUGEOT
Model	407 HDI SW SR
Colour	Silver
Year of manufacture	2010
Top speed	126 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1


Date 2021-12-03

Pictures 7

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-12-10
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	15
Total items failed	6

MOT #14	2023-12-05 07:46
MOT test number	313741509968
Result	✓ Passed
Next expiry date	2024-12-10

MOT #13	2022-11-29 08:24
MOT test number	427731941699
Result	✓ Passed

MOT #12	2021-11-26 09:10
MOT test number	920582932956
Result	✓ Passed
Advice Both headlamps poor condition	

MOT #11	2020-12-11 16:53
MOT test number	551302823249
Result	✓ Passed
Advice Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #10 2020-12-11 09:40 842896363445 **MOT** test number Result × Failed Fail Nearside Rear Service brake excessively binding (1.2.1 (f)) **Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Nearside Front Position lamp not working (4.2.1 (a) (ii)) Fail Offside Rear Service brake excessively binding (1.2.1 (f)) Fail

MOT #9

MOT test number

891109862550

Result

Minor

(i))

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b)

 MOT #8
 2018-03-29 08:38

 MOT test number
 223980458953

 Result
 ✓ Passed

MOT #7 2017-04-18 16:09
MOT test number 887034168683

Result

Passed

MOT #6 2017-04-18 10:33

MOT test number 895457017866

Result X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 4/13



report date: 2024-03-28

✓ Passed

MOT #5 2016-04-12 10:28

MOT test number 678586844248

Result ✓ Passed

Advice Engine cover and undertray fitted not allowing full inspection of some components

MOT #4 2015-04-15 09:16

MOT test number 336735305131

Result

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Engine covers fitted obscuring some components in the engine bay

Notice Under-trays fitted obscuring some underside components

MOT #3 2015-04-02 11:02

MOT test number 115522295431

Result × Failed

Notice Under-trays fitted obscuring some underside components

Fail Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Notice Engine covers fitted obscuring some components in the engine bay

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-04-25 09:36

MOT test number 325645214125

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #1

MOT test number

769905383099

Result

Notice Under-trays fitted obscuring some underside components

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 July
Days left	63
MOT expiry date	10 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-03-30
Last registration	2023-12-05
Complete history	See info



Registration #1	2010-03-30	23 mi
Registration #2	2013-03-26	26.697 mi
Registration #3	2014-04-25	30.955 mi
Registration #4	2015-04-02	34.842 mi
Registration #5	2015-04-15	34.956 mi
Registration #6	2016-04-12	40.306 mi
Registration #7	2017-04-18	46.845 mi
Registration #8	2017-04-18	46.845 mi
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		11.777 ms
Registration #16		10.777 au

More info >

page 12/13 CarCheck.co.uk



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1494 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1612 kg
Max. allowed weight	2195 kg

Additional information

Fuel tank capacity	66 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 13/1

Number of axles 2

Engine number DYXH4103212