





report date: 2024-03-28

#### General information

Make	FIAT
Model	TIPO MULTIJET EASY PLUS
Colour	Red
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	118 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	64.2 mpg
Consumption extra urban	85.6 mpg
Consumption combined	76.4 mpg
CO2 emission	98 g/km
CO2 label	Α



CarCheck.co.uk page 1/12



Internet history

Entry 2

Date 2022-05-27

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2022-05-10

Pictures 30

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-04
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	13
Total items failed	2

MOT #6	2023-10-02 14:51
MOT test number	246302852031
Result	<b>✓</b> Passed
Next expiry date	2024-10-04

MOT #5	2022-10-05 12:52
MOT test number	694465797771
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



Advice

Advice

**AY17NYW** 

report date: 2024-03-28

**MOT #4** 2022-03-08 15:27 **MOT** test number 455092798199 Result ✓ Passed **Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #3

MOT test number

Result

Advice Both front tyres starting to wear on edges.

2021-03-10 10:07

274363111349

✓ Passed

Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #2

MOT test number

215980160260

Result

Pass with rectification

Windscreen washer provides insufficient washer liquid (3.5 (a))

Pass with rectification

Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice

Both front tyres starting to wear on edges.

CarCheck.co.uk page 4/12



MOT #1 2020-03-10 09:58

**MOT test number** 406876191750

**Result** ✓ Passed

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 October
Days left	156
MOT expiry date	4 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



AY17NYW

report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



AY17NYW

report date: 2024-03-28

#### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
*********	
***************************************	
***********	
***************************************	
***************************************	
***************************************	
Plate changes	More info >
See in this check if this FIAT had different number plates.	
Number of plates	
Current registration	UK UK
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-07
Last registration	2023-10-02
Complete history	See info



Registration #1	2017-03-07	16 mi
Registration #2	2020-03-10	27.392 mi
Registration #3	2021-03-10	31.009 mi
Registration #4	2021-03-10	31.009 mi
Registration #5		11.777 esi
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		

More info >

CarCheck.co.uk page 11/12



**AY17NYW** 

report date: 2024-03-28

## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Adult	82%
Children	60%
Pedestrian	62%
Safety systems	57%
Overall rating	68%
Video	see crash video



# Dimensions & weight

Width	1792 mm
Height	1495 mm
Length	4368 mm
Wheel base	2638 mm
Kerb weight	1370 kg
Max. allowed weight	1795 kg

# Additional information

Fuel tank capacity	50 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 pa	ge 12/12

Number of axles 2

Engine number 7973051