



YE080AG

report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 L LWB P/V 90
Colour	White
Year of manufacture	2008
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	220 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



MOT history

MOT expiry date	2022-04-15
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	33
Total items failed	30

MOT #212021-04-16 07:57

MOT test number692118892480

Result✓ Passed

Next expiry date2022-04-15

- AdviceNearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceOffside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceOffside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- AdviceNearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- AdviceOil leak
- AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #20**

2021-03-30 08:49

MOT test number

887787634381

Result**✗ Failed**

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Rear Exhaust system insecure (6.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Advice OIL LEAK

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail Offside Front Direction indicator not working (4.4.1 (a) (ii))

Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Fail Offside Front Headlamp not working on main beam (4.1.1 (a) (ii))

MOT #19

2019-07-03 15:14

MOT test number

782503858585

Result**✓ Passed**

**MOT #18**

2019-07-01 14:08

MOT test number

155573895765

Result

✗ Failed

Fail Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Fail Nearside Rear Outer Vehicle structure corroded to the extent that the rigidity of the assembly is significantly reduced sill (6.1.1 (c) (i))

MOT #17

2018-05-17 13:00

MOT test number

368394436417

Result

✓ Passed

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

Advice Offside rear tyre is perished from outer sidewall

Advice Nearside Front Drag link end ball joint has slight play (2.2.B.1f)

Advice Oil leak

MOT #16

2017-06-02 10:23

MOT test number

725440698823

Result

✓ Passed

Advice Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)

**MOT #15** 2017-06-02 08:41**MOT test number** 836515513193**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**MOT #14** 2016-06-09 11:19**MOT test number** 231476813034**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #13** 2016-06-07 10:31**MOT test number** 925154737300**Result** ✗ Failed**Fail** Nearside Stop lamp emits other than a steady red light (1.2.1e)**Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Front Exhaust system not adequately supported (7.1.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Nearside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**MOT #12** 2015-06-04 12:32**MOT test number** 806355455195**Result** ✓ Passed

**MOT #11** 2015-06-04 11:29**MOT test number** 358445055135**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear Stop lamp not working (1.2.1b)**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Front Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**MOT #10** 2014-06-03 16:06**MOT test number** 707694454190**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-06-03 16:06**MOT test number** 209614354170**Result** ✗ Failed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**MOT #8** 2013-06-04 15:26**MOT test number** 817815453145**Result** ✓ Passed

**MOT #7** 2013-06-04 15:26**MOT test number** 405925353187**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #6** 2012-06-02 11:23**MOT test number** 975014152107**Result** ✓ Passed**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #5** 2012-04-12 15:06**MOT test number** 187303402196**Result** ✓ Passed**Notice** Nsf tyre has object rolling around inside**Notice** Front wipers smearing slightly not affecting view of road**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Notice** Nsf tyre getting close to limit also has chunks out of outer sidewall no cords showing**MOT #4** 2012-04-12 15:06**MOT test number** 389563602130**Result** ✗ Failed**Notice** Nsf tyre getting close to limit also has chunks out of outer sidewall no cords showing**Pass with rectification** Nearside Rear Stop lamp not working (1.2.1b)**Notice** Nsf tyre has object rolling around inside**Notice** Front wipers smearing slightly not affecting view of road**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #3	2011-05-13 12:54
MOT test number	968043731171
Result	✓ Passed

MOT #2	2011-05-09 11:38
MOT test number	587269421196
Result	✗ Failed
<div><div>Fail</div> Nearside Front Front wheel bearing rough when rotated (2.5.A.2)</div>	
<div><div>Advice</div> Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div>	
<div><div>Fail</div> Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div>	

MOT #1	2011-01-19 09:33
MOT test number	656789011009
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
30 September 2021

✕
MOT

Expired:
15 April 2022

Tax status

Expired at 30 September

Days left

943 days too late

MOT expiry date

15 April 2022

Full MOT history

[See MOT history](#)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	YE08OAG
Plate since	2019-03-28
Current registration	YE08OAG
Plate since	2019-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2008-05-22
Last registration	2021-04-16
Complete history	See info



Registration #1	2008-05-22	20 mi
Registration #2	2011-01-19	87.570 mi
Registration #3	2011-05-09	98.866 mi
Registration #4	2011-05-13	99.217 mi
Registration #5	2012-04-12	136.268 mi
Registration #6	2012-06-02	72.138 mi
Registration #7	2013-06-04	79.825 mi
Registration #8	2014-06-03	89.103 mi
Registration #9	2015-06-04	98.665 mi
Registration #10	2015-06-04	98.665 mi
Registration #11	2016-06-04	98.665 mi
Registration #12	2017-06-04	98.665 mi
Registration #13	2018-06-04	98.665 mi
Registration #14	2019-06-04	98.665 mi
Registration #15	2020-06-04	98.665 mi
Registration #16	2021-06-04	98.665 mi
Registration #17	2022-06-04	98.665 mi
Registration #18	2023-06-04	98.665 mi
Registration #19	2024-06-04	98.665 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	8R08832