



HSI8JWF

report date: 2024-03-29

General information

| | |
|---------------------|-------------------|
| Make | SUZUKI |
| Model | CELERIO SZ4 |
| Colour | White |
| Year of manufacture | 2018 |
| Top speed | 97 mph |
| Gearbox | 5 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|--------------------|
| Power | 67 BHP |
| Max. torque | 90 Nm at 3.500 rpm |
| Engine capacity | 998 cc |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 54.3 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |






Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-01-29 |
| Pictures | 22 |
| Listing price | View report |



source: yesauto.com



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-08-30 |
| MOT pass rate | 100 % |
| MOT passed | 3 |
| Failed MOT tests | 0 |
| Total advice items | 5 |
| Total items failed | 0 |

| | |
|------------------|--|
| MOT #3 | 2023-08-26 08:43 |
| MOT test number | 229943714793 |
| Result | ✓ Passed |
| Next expiry date | 2024-08-30 |
| Advice | Nearside Rear Tyre worn close to legal limit/worn on edge at 3mm (5.2.3 (e)) |
| Advice | Offside Rear Seat belt slightly damaged webbing damaged, on limit! (7.1.2 (b) (i)) |

| | |
|-----------------|--|
| MOT #2 | 2022-08-24 12:09 |
| MOT test number | 188071212127 |
| Result | ✓ Passed |
| Advice | Offside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

| | |
|-----------------|---|
| MOT #1 | 2021-08-27 12:28 |
| MOT test number | 835168358344 |
| Result | ✓ Passed |
| Advice | Offside Rear Seat belt slightly damaged (7.1.2 (b) (i)) |



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
30 August 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 February |
| Days left | 277 |
| MOT expiry date | 30 August 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--------------------------------------|------------|
| Vehicle class | 48 |
| Band | E |
| First licence fee (12 months) | £ 165,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2019-03-29 |
| Current registration | |
| Plate since | 2019-03-29 |

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 5 |
| First mileage registration | 2018-08-31 |
| Last registration | 2023-08-26 |
| Complete history | See info |



| | | |
|-----------------|------------|-----------|
| Registration #1 | 2018-08-31 | 26 mi |
| Registration #2 | | |
| Registration #3 | 2021-08-27 | 15.861 mi |
| Registration #4 | | |
| Registration #5 | | |

More info >



Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★☆ |
| Adult | 61% |
| Children | 74% |
| Pedestrian | 68% |
| Safety systems | 38% |
| Overall rating | 60% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1600 mm |
| Height | 1540 mm |
| Length | 3600 mm |
| Wheel base | 2425 mm |
| Kerb weight | 885 kg |
| Max. allowed weight | 1260 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 35 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | K10BS1079983 |