





report date: 2024-03-29

## General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Grey
Year of manufacture	2014
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 сс
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E



CarCheck.co.uk page 1/12



## Internet history

## Entry 1

Date 2021-09-08

Pictures 44

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-10-16
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	12
Total items failed	2

MOT #9	2023-10-17 12:28
MOT test number	771899853991
Result	✓ Passed
Next expiry date	2024-10-16

MOT #8	2022-09-23 10:53
MOT test number	383270166859
Result	✓ Passed
Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #7	2021-09-27 16:21
MOT test number	449298893707
Result	✓ Passed
MOT #6	2021-09-25 10:56
MOT test number	839843395837
Result	<b>X</b> Failed
<b>DANGEROUS</b> Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	
MAJOR Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
MAJOR Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	

CarCheck.co.uk page 3/12



DL14UAG

report date: 2024-03-29

MOT #5 2020-10-14 15:51

**MOT test number** 541999340509

Result \rightarrow Passed

Advice Offside Rear tyre Uneven Ware, Starting To Misshape

MOT #4 2019-06-06 10:50

**MOT test number** 342865417527

Result \( \sqrt{Passed} \)

**Advice** Both front tyres nearing 2mm wear markers

MOT #3 2019-06-06 07:58

**MOT test number** 393395614418

Result X Failed

Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))

**DANGEROUS** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Both front tyres nearing 2mm wear markers

Pass with rectification Nearside Front Headlamp aim too low (4.1.2 (a))

**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #2 2018-06-08 12:49

**MOT test number** 209815778520

Result 

Passed

CarCheck.co.uk page 4/12



**MOT #1** 2017-06-09 08:19

**MOT test number** 617090630839

**Result** ✓ Passed

Advice

Nearside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 5/12



### Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	16 October 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1

Date	
Category	

Damage 2

**Type** 

Damage 2 Date

Category

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here.	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
***************************************	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	IK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-06-04
Last registration	2023-10-17
Complete history	See info



Registration #1	2014-06-04	27 mi
Registration #2	2017-06-09	25.472 mi
Registration #3	2018-06-08	33.963 mi
Registration #4	2019-06-06	42.197 mi
Registration #5	2019-06-06	42.199 mi
Registration #6	2020-10-14	50.801 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		19.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



# Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

## Additional information

Fuel tank capacity	54
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19EF8057LDD

CarCheck.co.uk page 12/12