



report date: 2024-03-28

General information

Make	VAUXHALL
Model	VECTRA VVT EXCLUSIV
Colour	Silver
Year of manufacture	2008
Top speed	126 mph
0 - 60 mph	10.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	167 Nm at 3.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-04-28
Pictures	12
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2024-07-20
MOT pass rate	54 %
MOT passed	13
Failed MOT tests	11
Total advice items	89
Total items failed	15

MOT #24	2023-07-21 15:17
MOT test number	694069795649
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #23	2023-07-21 10:24
MOT test number	304651260313
Result	✗ Failed
MAJOR	Offside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Nearside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
Advice	Nearside Front Tyre slightly damaged/cracking or perishing 2mm 215/50R17 (5.2.3 (d) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a) (ii))
MAJOR	Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Nail in tyre



MOT #22

2022-07-21 11:11

MOT test number

951521725500

Result

✓ Passed

- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Advice

Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice

Exhaust has a minor leak of exhaust gases rear box joint (6.1.2 (a))
- Advice

Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Advice

Rear Coil spring corroded both rear (5.3.1 (b) (i))
- Advice

Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- Advice

Brake pipe corroded, covered in grease or other material front to rear pipes covered in grease (1.1.11 (c))

**MOT #21**

2022-07-19 08:14

MOT test number

214958068379

Result**✗ Failed**

- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Rear Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- MAJOR** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- MAJOR** Brake pipe excessively corroded front to rear at joints (1.1.11 (c))
- Advice** Exhaust has a minor leak of exhaust gases rear box joint (6.1.2 (a))
- MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Advice** Rear Coil spring corroded both rear (5.3.1 (b) (i))
- Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- MAJOR** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #20** 2022-04-01 09:30**MOT test number** 231898510913**Result** ✗ Failed

- MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Parking brake inoperative on one side (1.4.1 (a))
- MAJOR** Nearside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- MAJOR** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- MAJOR** Nearside Front Brake pipe excessively corroded (1.1.11 (c))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- MAJOR** Nearside Rear Brake hose ferrule excessively corroded (1.1.12 (f) (i))
- MAJOR** Offside Front Brake hose ferrule excessively corroded (1.1.12 (f) (i))

MOT #19 2021-03-25 15:00**MOT test number** 377212237125**Result** ✓ Passed

- Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #18**

2020-04-01 13:38

MOT test number

472466835887

Result

✓ Passed

- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Brake hose has slight corrosion to ferrule both fronts (1.1.12 (f) (i))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))

MOT #17

2020-04-01 11:11

MOT test number

360828627419

Result

✗ Failed

- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- MAJOR** Offside Headlamp not working on main beam (4.1.1 (a) (ii))
- Advice** Offside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- MAJOR** Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii))
- Advice** Brake hose has slight corrosion to ferrule both fronts (1.1.12 (f) (i))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Track rod end ball joint has slight play (2.1.3 (b) (i))
- MAJOR** Offside Inner Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #16**

2019-04-02 15:23

MOT test number

632908087106

Result

✓ Passed

Advice Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both rears (5.3.4 (a) (i))**Advice** Offside Play in steering rack inner joint(s)**MOT #15**

2019-04-01 14:22

MOT test number

302695438093

Result

✗ Failed

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Anti-roll bar pin or bush worn but not resulting in excessive movement both rears (5.3.4 (a) (i))**MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**MOT #14**

2018-03-29 14:49

MOT test number

748728015693

Result

✓ Passed

MOT #13

2018-03-29 14:41

MOT test number

342863378381

Result

✗ Failed

Fail Nearside Rear coil spring broken (2.4.C.1a)**Advice** Anti-roll bar has slight play in a pin/bush both rears(d)bushes (2.4.G.2)

**MOT #12** 2018-03-29 11:48**MOT test number** 336622917278**Result** ✗ Failed**Fail** Nearside Rear coil spring broken (2.4.C.1a)**Advice** Anti-roll bar has slight play in a pin/bush both rears(d)bushes (2.4.G.2)**MOT #11** 2017-04-11 10:02**MOT test number** 125121339199**Result** ✓ Passed**Advice** Brake pipe slightly corroded both centre to rears and nsf (3.6.B.2c)**Advice** Offside Front play in tie rod**MOT #10** 2017-04-11 10:02**MOT test number** 100047171520**Result** ✗ Failed**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front play in tie rod**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Brake pipe slightly corroded both centre to rears and nsf (3.6.B.2c)**MOT #9** 2016-03-30 10:47**MOT test number** 275107718383**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8**

2016-03-30 08:10

MOT test number

770648727943

Result

✗ Failed

Fail Offside Front position lamp(s) not working (1.1.A.3b)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Fail** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Offside Headlamp aim too low (1.8)**MOT #7**

2015-04-11 09:31

MOT test number

667731605168

Result

✓ Passed

Advice Offside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**MOT #6**

2014-03-25 14:45

MOT test number

315224084072

Result

✓ Passed

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Notice** Osr tyre sidewall cracked**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #5** 2014-03-24 16:01**MOT test number** 198143584450**Result** ✗ Failed**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Osr tyre sidewall cracked**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2013-03-22 16:50**MOT test number** 208761683038**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Eml light on**MOT #3** 2013-03-19 16:52**MOT test number** 776358473060**Result** ✗ Failed**Fail** Offside Front coil spring fractured (2.4.C.1a)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Notice** Eml light on**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Fail** Brakes imbalanced across an axle (3.7.B.5b)



MOT #2	2011-11-11 11:44
MOT test number	436275311419
Result	✓ Passed

MOT #1	2010-11-16 16:28
MOT test number	782800420319
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 October 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 October
Days left	154
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2008-08-15
Last registration	2023-07-21
Complete history	See info



Registration #1	2008-08-15	16 mi
Registration #2	2010-11-16	30.551 mi
Registration #3	2011-11-11	70.738 mi
Registration #4	2013-03-19	79.989 mi
Registration #5	2013-03-22	79.989 mi
Registration #6	2014-03-24	84.198 mi
Registration #7	2014-03-25	84.198 mi
Registration #8	2015-04-11	84.586 mi
Registration #9	2016-03-30	88.126 mi
Registration #10	2016-03-30	88.126 mi
Registration #11	2017-04-11	91.369 mi
Registration #12	2017-04-11	91.369 mi
Registration #13	2018-03-29	96.437 mi
Registration #14	2019-05-20	95.377 mi
Registration #15	2019-05-20	95.377 mi
Registration #16	2019-05-20	95.377 mi
Registration #17	2019-05-20	95.377 mi
Registration #18	2019-05-20	95.377 mi
Registration #19	2019-05-20	95.377 mi
Registration #20	2019-05-20	95.377 mi
Registration #21	2019-05-20	95.377 mi
Registration #22	2019-05-20	95.377 mi
Registration #23	2019-05-20	95.377 mi
Registration #24	2019-05-20	95.377 mi
Registration #25	2019-05-20	95.377 mi
Registration #26	2019-05-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2036 mm
Height	1460 mm
Length	4596 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1885 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	20KV4564