





report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER LL35 BUSINESS DCI LUTON
Colour	White
Year of manufacture	-
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	310 Nm at 1.500 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	1.0 mpg
Consumption extra urban	1.0 mpg
Consumption combined	35.8 mpg



CarCheck.co.uk page 1/10



report date: 2024-03-29

Internet history

entry 1	E	n	tr	У	1
---------	---	---	----	---	---

Life y 1	
Date	2022-06-17
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/10



report date: 2024-03-29

MOT history

MOT #4	2022-11-30 15:45
MOT test number	753894870173
Result	√ Passed
Next expiry date	2023-11-29

MOT #3 2022-11-24 16:34

MOT test number 695531417810

Result X Failed

Fail Front Power steering malfunctioning on start up no power steering/not smooth in operation (2.1.5 (a))

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Front Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. 41% front brake inbalance (1.2.1 (b) (i))

Fail Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #2 2022-07-22 11:01

MOT test number 107360101254

Advice Front Lower undertray fitted inspection inpaired

Advice Slight ressistance to power steering

Advice Trigger point not met on diesel test

CarCheck.co.uk page 3/10



report date: 2024-03-29

MOT #1 2022-07-14 15:52

MOT test number 129774039260

Result × Failed Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g)) Minor Nearside Rear Brake hose slightly chafed not in holder (1.1.12 (b) (i)) Offside Rear Rear fog lamp not working (4.5.1 (a) (ii)) Fail **Advice** Nearside Rear brake bind/unable to view tyre correctly Nearside Rear Service brake excessively fluctuating (1.2.1 (e)) Fail Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii)) Front Lower undertray fitted inspection inpaired **Advice** Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) **Advice** Nearside Rear brake binding Fail Nearside Rear Service brake excessively binding could be handbrake binding (1.2.1 (f)) **Advice** Offside door striker catch poor Fail Front Power steering malfunctioning not smooth on lock to lock/or in operation (2.1.5 (a)) Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) Fail

Advice Front number plate poor

Fail Rear Other passenger door catch insecure doors will not latch (6.2.3 (c) (ii))

Advice Trigger point not met on diesel test

CarCheck.co.uk page 4/10



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/10



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 6/10



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

THE STREET STREET	
	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 7/10



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 8/10



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-09-04
Last registration	2022-11-30
Complete history	See info



Registration #1	2019-09-04	13 mi
Registration #2		11.777 es
Registration #3	2022-07-14	46.871 mi
Registration #4		11.777 es
Registration #5		11.777 es
Devictuation #C		

Registration #6

More info >

CarCheck.co.uk page 9/10



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2470 mm
Height	2264 mm
Length	6180 mm
Kerb weight	2149 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	3
Number of axles	2
Engine number	C129034

CarCheck.co.uk page 10/10