



report date: 2024-03-28

General information

Make	NISSAN
Model	NOTE VISIA
Colour	White
Year of manufacture	2014
Top speed	104 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	80 BHP
Max. torque	110 Nm at 4.000 rpm
Engine capacity	1.198 cc
Cylinders	3
Fuel type	Petrol
Consumption city	49.6 mpg
Consumption extra urban	68.9 mpg
Consumption combined	60.1 mpg
CO2 emission	109 g/km
CO2 label	B





Internet history

Entry 1

Date	2021-02-03
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

**MOT history**

MOT expiry date	2025-02-24
MOT pass rate	62 %
MOT passed	8
Failed MOT tests	5
Total advice items	32
Total items failed	14

MOT #13 2024-02-15 16:45**MOT test number** 876739547406**Result** ✓ Passed**Next expiry date** 2025-02-24**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2024-02-15 12:51**MOT test number** 388056859697**Result** ✗ Failed**Fail** Reversing lamp inoperative (4.6.1 (a))**Fail** Offside Front Service brake excessively fluctuating (1.2.1 (e))**Fail** Offside Front Anti-roll bar ball joint excessively worn drop link (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Service brake binding but not excessively (1.2.1 (f))

**MOT #11**

2023-02-20 16:12

MOT test number

671641996643

Result

✓ Passed

Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #10**

2023-02-20 09:12

MOT test number

793062940383

Result

✗ Failed

Advice Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))**MOT #9**

2022-02-24 11:33

MOT test number

831862570772

Result

✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both wishbone front bushes (5.3.4 (a) (i))

**MOT #8** 2022-02-24 11:33**MOT test number** 846685836356**Result** ✗ Failed**Pass with rectification** Headlamp aim too high both front (4.1.2 (a))**Advice** Suspension arm pin or bush worn but not resulting in excessive movement both wishbone front bushes (5.3.4 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))**Advice** Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))**MOT #7** 2021-02-15 13:27**MOT test number** 371896070845**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #6** 2021-02-15 13:27**MOT test number** 261221790923**Result** ✗ Failed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Pass with rectification** Nearside Front Direction indicator not working (4.4.1 (a) (ii))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #5** 2020-02-14 16:39**MOT test number** 497216050334**Result** ✓ Passed

**MOT #4** 2019-02-25 10:19**MOT test number** 530969179092**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #3** 2018-02-24 10:34**MOT test number** 192031610856**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn corroded slight (3.5.1i)**Advice** Nearside Front Macpherson strut worn but not seriously weakened Macpherson strut has slight movement in the upper support bearing assembly - slight movement worn sliding bush gland slight movement at the upper attachment - complete macpherson strut mount bearing (2.4.G.1)**Advice** Parking brake lever has little reserve travel it would appear that the braking system requires adjustment or repair. (3.1.6b)**Advice** Front Brake pad(s) wearing thin near limit - limited required soon (3.5.1g)



MOT #2

2018-02-24 10:34

MOT test number

275472763225

Result

✗ Failed

Advice Nearside Front Macpherson strut worn but not seriously weakened Macpherson strut has slight movement in the upper support bearing assembly - slight movement worn sliding bush gland slight movement at the upper attachment - complete macpherson strut mount bearing (2.4.G.1)

Pass with rectification Central Rear Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Windscreen washer provides insufficient washer liquid front and rear - all (8.2.3)

Advice Parking brake lever has little reserve travel it would appear that the braking system requires adjustment or repair. (3.1.6b)

Advice Front Brake pad(s) wearing thin near limit - limited required soon (3.5.1g)

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Offside Front Windscreen wiper not operating over a large enough area to give an adequate view removal of plastic shield required - replacement wiper maybe required (8.2.1c)

Pass with rectification Nearside Rear Rear position lamp(s) not working (1.1.A.3b)

Advice Front brake disc worn, pitted or scored, but not seriously weakened worn corroded slight (3.5.1i)

MOT #1

2017-01-23 11:39

MOT test number

335965293025

Result

✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
24 February 2025

Tax status	Valid until 1 May
Days left	366
MOT expiry date	24 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2014-01-08
Last registration	2024-02-15
Complete history	See info



Registration #1	2014-01-08	10 mi
Registration #2	2017-01-23	60.419 mi
Registration #3	2018-02-24	80.528 mi
Registration #4	2018-02-24	80.528 mi
Registration #5	2019-02-25	94.713 mi
Registration #6	2020-02-14	101.989 mi
Registration #7	2020-02-20	101.989 mi
Registration #8	2021-02-15	107.797 mi
Registration #9	2021-02-20	107.797 mi
Registration #10	2021-02-20	107.797 mi
Registration #11	2021-02-20	107.797 mi
Registration #12	2021-02-20	107.797 mi
Registration #13	2021-02-20	107.797 mi
Registration #14	2021-02-20	107.797 mi
Registration #15	2021-02-20	107.797 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	82%
Pedestrian	58%
Safety systems	70%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1695 mm
Height	1530 mm
Length	4100 mm
Wheel base	2600 mm
Kerb weight	1036 kg
Max. allowed weight	1510 kg

Additional information

Fuel tank capacity	41 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	065236R