





### General information

| Make                | HYUNDAI           |
|---------------------|-------------------|
| Model               | I40 CRDI STYLE    |
| Colour              | Silver            |
| Year of manufacture | 2013              |
| Top speed           | 122 mph           |
| 0 - 60 mph          | 11.6 seconds      |
| Gearbox             | 6 speed automatic |

## Engine & fuel consumption

| Power                   | 134 BHP             |
|-------------------------|---------------------|
| Max. torque             | 325 Nm at 2.500 rpm |
| Engine capacity         | 1.685 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 37.2 mpg            |
| Consumption extra urban | 55.4 mpg            |
| Consumption combined    | 47.1 mpg            |
| CO2 emission            | 159 g/km            |
| CO2 label               | G                   |







# Internet history

| Entry | 1 |
|-------|---|
| Date  |   |

Pictures

2021-12-03

12

Listing price

View report



source: cargurus.co.uk



### MOT history

| MOT expiry date    | 2025-01-02 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 11         |
| Failed MOT tests   | 0          |
| Total advice items | 10         |
| Total items failed | 0          |

| MOT #11          | 2024-01-03 13:17 |
|------------------|------------------|
| MOT test number  | 837280478548     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-01-02       |

| MOT #10   | 2023-11-03 14:52 |
|---|------------------|
| MOT test number   | 739140385291     |
| Result  | ✓ Passed         |
| Advice Front Tyre worn close to legal limit/worn on edge both wearing on edges (5 | 5.2.3 (e))       |

| MOT #9   | 2022-11-14 14:39 |
|--|------------------|
| MOT test number  | 449919377942     |
| Result   | ✓ Passed         |
| Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b)) |                  |

| MOT #8          | 2022-10-20 09:58 |
|-----------------|------------------|
| MOT test number | 472220842953     |
| Result          | ✓ Passed         |





| MOT #7   | 2022-07-15 14:47                 |
|--|----------------------------------|
| MOT test number  | 982356574322                     |
| Result   | ✓ Passed                         |
| Advice Tyre worn close to legal limit/worn on edge both front inners (5.2.3 (e)) |                                  |
|  |                                  |
| MOT #6   | 2021-07-16 09:47                 |
| MOT test number  | 2021-07-16 09:47<br>251824961170 |
|  |                                  |
| MOT test number  | 251824961170                     |

| MOT #5   | 2020-07-24 07:38    |
|--|---------------------|
| MOT test number  | 661722320012        |
| Result   | ✓ Passed            |
| Advice Offside Headlamp light intensity slightly reduced   |                     |
| Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamp (4.7.1 (b) (i)) | os or light sources |

| MOT #4          | 2019-07-12 11:04 |
|-----------------|------------------|
| MOT test number | 308652126195     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #3          | 2018-07-13 10:33 |

|  | 2010-07-13 10.33 |
|--|------------------|
| MOT test number  | 263451569335     |
| Result   | ✓ Passed         |
| Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) |                  |



| GX63GCY                 |
|-------------------------|
| report date: 2024-03-28 |

| MOT #2                                 | 2017-07-27 15:47 |
|--|------------------|
| MOT test number                        | 886357340462     |
| Result                                 | ✓ Passed         |
| Advice All four tyres perished/cracked |                  |
| MOT #1                                 | 2016-08-31 10:49 |
| MOT #1                                 | 484628914815     |
|  |                  |
| Result                                 | ✓ Passed         |
| Advice All tyres perised               |                  |



Tax & MOT check

| √<br>Taxed                         | √<br>MOT                          |
|------------------------------------|-----------------------------------|
| <b>Tax due:</b><br>1 November 2024 | <b>Expires:</b><br>2 January 2025 |
| Tax status                         | Valid until 1 November            |
| Days left                          | 186                               |
| MOT expiry date                    | 2 January 2025                    |
| Full MOT history                   | See MOT history                   |

## Tax calculation

| Vehicle class                           | 49         |
|---|------------|
| Band                                    | G          |
| Single payment (12 months)              | £ 240,00,- |
| Single six month payment                | £ 132,00,- |
| Total payable by 12 monthly instalments | £ 252,00,- |





#### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |         |
|----------|---------|
| Date     | FERRE   |
| Category | Lamp    |
| Туре     |         |
| Damage 2 | AMPLE   |
| Damage 2 | e et al |
| Date     | *       |
| Category | AMP     |
| Туре     |         |

#### Extra HYUNDAI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4.11.111 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 11 711 |





### Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| xxxxxxxx   |             |
|--|-------------|
| *********  |             |
| And a second sec |             |
| *******  |             |
| *********  |             |
| ********   |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this HYUNDAI had different number plates.   |             |
| Number of plates   | ,           |
| Current registration   |             |
| Plate since  |             |
| Current registration   |             |
| Plate since  |             |





#### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





# Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 13         |
| First mileage registration | 2013-09-04 |
| Last registration          | 2024-01-03 |
| Complete history           | See info   |



| Registration #1  | 2013-09-04 | 22 mi      |
|------------------|------------|------------|
| Registration #2  | 2016-08-31 | 10.157 mi  |
| Registration #3  | 2017-07-27 | 13.239 mi  |
| Registration #4  | 2018-07-13 | 27.003 mi  |
| Registration #5  | 2019-07-12 | 42.896 mi  |
| Registration #6  | 2020-07-24 | 59.146 mi  |
| Registration #7  | 2021-07-16 | 69.560 mi  |
| Registration #8  |            | 11.777 esi |
| Registration #9  |            | 11.777 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
| Registration #12 |            | 11.777 est |
| Registration #13 |            |            |





## Car features

| 50225 | Air conditioning |
|-------|------------------|
| 50295 |                  |
| 50482 |                  |
| 60501 |                  |
| 0566  |                  |
| 0567  |                  |
| 60569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 92%             |
| Children       | 86%             |
| Pedestrian     | 43%             |
| Safety systems | 86%             |
| Overall rating | 80%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1815 mm          |
| Height                            | 1470 mm          |
| Length                            | 4740 mm          |
| Wheel base                        | 2770 mm          |
| Kerb weight                       | 1601 kg          |
| Max. allowed weight               | 2100 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 70               |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 4                |
| Number of seats<br>CarCheck.co.uk | 5 page 12/12     |

#### **Engine number**

D4FDDU281758