



report date: 2024-03-28

General information

Make	VAUXHALL
Model	MERIVA TECH LINE
Colour	Red
Year of manufacture	2014
Top speed	110 mph
0 - 60 mph	14.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	130 Nm at 4.000 rpm
Engine capacity	1.398 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg
CO2 emission	140 g/km
CO2 label	E






Internet history

Entry 1

Date	2021-08-02
Pictures	26
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-01-19
MOT pass rate	73 %
MOT passed	8
Failed MOT tests	3
Total advice items	17
Total items failed	7

MOT #11	2024-01-05 12:15
MOT test number	709462883744
Result	✓ Passed
Next expiry date	2025-01-19
Advice	Nearside Oil leak, but not excessive Driveshaft oil seal (8.4.1 (a) (i))
Advice	Oil leak, but not excessive Engine (8.4.1 (a) (i))
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))

MOT #10	2023-01-18 11:45
MOT test number	251875933881
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt
Minor	Nearside Obligatory mirror slightly damaged (3.3 (b) (i))
Minor	Nearside Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #9** 2022-01-19 09:16**MOT test number** 665537560430**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Oil leak, but not excessive gearbox area (8.4.1 (a) (i))

MOT #8 2021-01-20 16:24**MOT test number** 886767328151**Result** ✓ Passed**MOT #7** 2021-01-07 16:36**MOT test number** 902739852779**Result** ✗ Failed

- Fail** Power steering component leaking steering rack (2.1.5 (a))
- Fail** Exhaust has a major leak of exhaust gases Flexi section (6.1.2 (a))
- Fail** Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))
- Fail** Electronic power steering not working (2.6 (c))
- Fail** Emissions not tested (8.2.1.2 (d))

MOT #6 2020-04-06 10:21**MOT test number** 134768253988**Result** ✓ Passed

**MOT #5** 2019-04-05 10:47**MOT test number** 500434065375**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2019-04-05 09:48**MOT test number** 361282749046**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2018-04-05 08:08**MOT test number** 880229941371**Result** ✓ Passed**MOT #2** 2017-08-22 09:34**MOT test number** 143328278758**Result** ✓ Passed**Advice** Front Exhaust has a minor leak of exhaust gases flexi joint (7.1.2)**MOT #1** 2017-08-22 09:34**MOT test number** 401702391155**Result** ✗ Failed**Advice** Front Exhaust has a minor leak of exhaust gases flexi joint (7.1.2)**Pass with rectification** Nearside Headlamp aim too high (1.8)



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
19 January 2025

Tax status	Valid until 1 March
Days left	305
MOT expiry date	19 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 EX64KVC
Plate since	2019-06-29
Current registration	 EX64KVC
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-09-01
Last registration	2024-01-05
Complete history	See info



Registration #1	2014-09-01	20 mi
Registration #2	2017-08-22	50.845 mi
Registration #3	2017-08-22	50.845 mi
Registration #4	2018-04-05	57.882 mi
Registration #5	2019-04-05	68.460 mi
Registration #6	2019-04-05	68.460 mi
Registration #7	2020-04-06	80.802 mi
Registration #8	2020-04-06	80.802 mi
Registration #9	2020-04-06	80.802 mi
Registration #10	2020-04-06	80.802 mi
Registration #11	2020-04-06	80.802 mi
Registration #12	2020-04-06	80.802 mi
Registration #13	2020-04-06	80.802 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	77%
Pedestrian	55%
Safety systems	86%
Overall rating	80%
Video	see crash video



Dimensions & weight

Width	1994 mm
Height	1615 mm
Length	4300 mm
Wheel base	2644 mm
Kerb weight	1376 kg
Max. allowed weight	1905 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	B14XER -19EF8057LDD