





General information

Make	RENAULT
Model	KANGOO ML19 DCI
Colour	White
Year of manufacture	2010
Top speed	91 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP	0 < 101 A
Max. torque	160 Nm at 1.700 rpm	0 < 101 A 101 - 120 B
Engine capacity	1.461 cc	121 - 140 E
Cylinders	4	141 - 165 F G
Fuel type	Diesel	166 - 185
Consumption city	47.9 mpg	186 - 225
Consumption extra urban	56.5 mpg	225+ L
Consumption combined	53.3 mpg	





Internet history


Entry 1

Date Pictures 2021-07-30

10

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-01
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	9
Total items failed	5

MOT #14		2023-06-02 14:54
MOT test	number	378849219751
Result		Passed
Next expiry date 2024-06-0		
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11	L (c))
Advice	Nearside Front Macpherson strut corroded but not seriously weakened (5.3.3	(b) (i))

MOT #13	2022-12-08 15:51
MOT test number	193325829680
Result	✓ Passed

MOT #12	2021-11-26 12:48
MOT test number	810194789964
Result	✓ Passed

MOT #11	. 2	2020-11-24 14:50
MOT test	number	472666700644
Result		✓ Passed
Minor	Nearside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	





MOT #10		2019-12-02 10:50
MOT test	number	867841437804
Result		✓ Passed
Advice Advice corroded	Rear Brake disc worn, pitted or scored, but not seriously weakened both Nearside Rear Brake pipe corroded, covered in grease or other material r 1.1.11 (c))	
MOT #9		2018-12-03 12:09

MOT #9	2018-12-03 12:09
MOT test number	291617874203
Result	✓ Passed

MOT #8		2018-12-03 09:32
MOT test	number	981034203756
Result		🗙 Failed
MAJOR	Offside Brake pipe excessively corroded front to rear (1.1.11 (c))	

MOT #7	2017-12-08 16:01
MOT test number	476309647482
Result	✓ Passed

MOT #6	2017-12-08 10:58
MOT test number	983433949668
Result	× Failed
Fail Offside Registration plate lamp not working (1.1.C.1d)	
Pass with rectificationCentral Stop lamp not working (1.2.1b)	

MOT #5	2016-12-09 17:03
MOT test number	156288498289
Result	✓ Passed



NV60CUG	
report date: 2024-03-28	8

MOT #4	2016-12-09 14:10
MOT test number	202877628796
Result	🗙 Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)	
Advice Offside front tyre worn close to legal limit	
Fail Offside Rear Registration plate lamp not working (1.1.C.1d)	
Fail Offside Rear coil spring broken (2.4.C.1a)	
Advice Both rear repeaters showing signs of white	

MOT #3		2015-11-30 10:04
MOT test	number	825307298079
Result		✓ Passed
Advice Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)		


MOT #2	2014-12-08 12:27
MOT test number	445302544465
Result	✓ Passed

MOT #1	2013-11-28 15:12
MOT test number	736092133332
Result	✓ Passed



NV60CUG report date: 2024-03-28

Tax & MOT check







Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FER I
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6.00.000
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Rule sizes	





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



NV60CUG report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2010-12-13
Last registration	2023-06-02
Complete history	See info



Registration #1	2010-12-13	19 mi
Registration #2	2013-11-28	26.211 mi
Registration #3	2014-12-08	35.176 mi
Registration #4	2015-11-30	41.336 mi
Registration #5	2016-12-09	54.682 mi
Registration #6	2016-12-09	54.686 mi
Registration #7	2017-12-08	68.223 mi
Registration #8	2017-12-08	68.223 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		10.000 est
Registration #15		11.777 mi

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
\$0566	
\$0567	
50569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1829 mm
Height	1844 mm
Length	4213 mm
Wheel base	2690 mm
Kerb weight	1268 kg
Max. allowed weight	1918 kg
Additional information	
Fuel delivery	Direct Injection
Number of seats	2
Number of axles	2
Engine number Carcheck.co.uk	D084893 page 12/12