



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	B-CLASS B180 CDI SE
Colour	Silver
Year of manufacture	2006
Top speed	111 mph
0 - 60 mph	11.8 seconds
Gearbox	1 speed CVT

Engine & fuel consumption



Power	107 BHP
Max. torque	250 Nm at 2.600 rpm
Engine capacity	1.992 cc
Cylinders	4
Fuel type	Diesel
Consumption city	38.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	157 g/km
CO2 label	G





Internet history

Entry 1	
Date	2021-06-19
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-08-30
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	38
Total items failed	16

MOT #20	2023-08-15 07:28
MOT test number	675740526990
Result	✓ Passed
Next expiry date	2024-08-30
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19**

2023-08-01 09:50

MOT test number

903814148738

Result

✗ Failed

- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Front Windscreen wiper does not clear the windscreen effectively both front wiper blades (3.4 (b) (ii))
- Fail** Nearside Front Suspension arm ball joint excessively worn bolt in ball joint (5.3.4 (a) (i))
- Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Fail** Offside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing tyre badly perished and worn out of shape inner edge (5.2.3 (d) (ii))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Fail** Exhaust emissions exceed manufacturer's specified limit limit 1.2 (8.2.2.2 (a))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened evidence of disc previously been hot through brake bind (1.1.14 (a) (ii))
- Fail** Offside Front Suspension arm ball joint excessively worn bolt in ball joint (5.3.4 (a) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing tyre badly perished and worn out of shape inner edge (5.2.3 (d) (ii))

MOT #18

2022-08-23 16:46

MOT test number

484313347395

Result

✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #17**

2022-08-23 11:31

MOT test number

671293344452

Result**✗ Failed****Pass with rectification** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Pass with rectification** Offside Front Outer Prop shaft joint constant velocity boot no longer prevents the ingress of dirt clip missing (6.1.7 (g) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Nail in tyre has 2 x nails in tread**Pass with rectification** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Front Inner Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MOT #16**

2021-08-25 13:13

MOT test number

225017822249

Result**✓ Passed****MOT #15**

2020-08-27 16:14

MOT test number

724960749017

Result**✓ Passed****Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Nearside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #14** 2019-08-29 14:42**MOT test number** 428954267447**Result** ✓ Passed**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #13** 2019-08-29 14:42**MOT test number** 319814947442**Result** ✗ Failed**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Rear Stop lamp(s) all not working (4.3.1 (a) (iii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #12** 2018-08-31 11:26**MOT test number** 564653106444**Result** ✓ Passed**Advice** Offside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))**Advice** Nearside Front Shock absorbers has slight external damage to the casing (5.3.2 (b))

**MOT #11** 2017-08-29 15:37**MOT test number** 399159213219**Result** ✓ Passed**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Slight misting of fluid near fuel filler**MOT #10** 2016-08-30 16:02**MOT test number** 703616533787**Result** ✓ Passed**MOT #9** 2015-08-29 13:59**MOT test number** 409121845224**Result** ✓ Passed**Advice** Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Track rod end ball joint has slight play (2.2.B.1f)**MOT #8** 2014-08-30 18:42**MOT test number** 845292244297**Result** ✓ Passed**MOT #7** 2013-08-02 12:00**MOT test number** 678724513234**Result** ✓ Passed**Advice** Nearside Outer Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #6** 2012-07-27 15:05**MOT test number** 438939702201**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**MOT #5** 2012-07-24 16:23**MOT test number** 338746102237**Result** ✗ Failed**Fail** Nearside Front coil spring fractured (2.4.C.1a)**Notice** Under-trays fitted obscuring some underside components**MOT #4** 2011-05-13 14:58**MOT test number** 587133231180**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2010-05-05 14:58**MOT test number** 642365920180**Result** ✓ Passed**MOT #2** 2009-04-24 11:17**MOT test number** 241544719164**Result** ✓ Passed**MOT #1** 2009-04-15 11:28**MOT test number** 844695409168**Result** ✗ Failed**Fail** Offside Rear Rear wheel bearing rough when rotated (2.6.1)



Tax & MOT check

X

Untaxed

Tax expired:
1 October 2023

✓

MOT

Expires:
30 August 2024

Tax status	Expired at 1 October 2023
Days left	211 days too late
MOT expiry date	30 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 SY06YKG
Plate since	2024-03-28
Current registration	 SY06YKG
Plate since	2024-03-28

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-05-17
Last registration	2023-08-15
Complete history	See info



Registration #1	2006-05-17	9 mi
Registration #2	2009-04-15	17.919 mi
Registration #3	2009-04-24	18.016 mi
Registration #4	2010-05-05	22.990 mi
Registration #5	2011-05-13	28.218 mi
Registration #6	2012-07-24	33.912 mi
Registration #7	2012-07-27	33.912 mi
Registration #8	2013-08-02	36.415 mi
Registration #9	2014-08-30	37.917 mi
Registration #10	2015-08-29	42.055 mi
Registration #11	2016-08-30	51.570 mi
Registration #12	2017-08-30	55.570 mi
Registration #13	2018-08-30	59.570 mi
Registration #14	2019-08-30	63.570 mi
Registration #15	2020-08-30	67.570 mi
Registration #16	2021-08-30	71.570 mi
Registration #17	2022-08-30	75.570 mi
Registration #18	2023-08-15	79.570 mi
Registration #19	2023-08-15	83.570 mi
Registration #20	2023-08-15	87.570 mi
Registration #21	2023-08-15	91.570 mi
Registration #22	2023-08-15	95.570 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1777 mm
Height	1603 mm
Length	4270 mm
Wheel base	2778 mm
Kerb weight	1435 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	54 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64094030254845