





General information

Make	ΤΟΥΟΤΑ
Model	C-HR DYNAMIC
Colour	White
Year of manufacture	2017
Top speed	105 mph
0 - 60 mph	11.0 seconds
Gearbox	5 speed CVT

Engine & fuel consumption

Power	121 BHP
Max. torque	305 Nm at 3.600 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	80.7 mpg
Consumption extra urban	68.9 mpg
Consumption combined	74.3 mpg
CO2 emission	87 g/km
CO2 label	A





Internet history	
Entry 1	
Date	2021-06-09
Pictures	1
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-16
MOT pass rate	71 %
MOT passed	5
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #7	2024-03-15 16:41
MOT test number	236243880992
Result	✓ Passed
Next expiry date	2025-03-16
Advice Offside Front Tyre slightly damaged slight damage to sidewall and cut	t in tread (5.2.3 (d) (ii))
Minor Nearside Front Lower Suspension arm ball joint dust cover severely det (5.3.4 (b) (i))	teriorated covered in grease
Advice Nearside Rear Tyre slightly damaged slight damage to sidewall and cu	uts in tread (5.2.3 (d) (ii))
Advice Front Lower Suspension arm pin or bush worn but not resulting in exc suspension arm rear bushes cracked (5.3.4 (a) (i))	essive movement both
Minor (b) (i)) Nearside Registration plate lamp inoperative in the case of multiple lam	mps or light sources (4.7.1
Advice Offside Rear Tyre slightly damaged/cracking or perishing badly cracket tread (5.2.3 (d) (ii))	ed + perished and cuts in
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or	r cords (5.2.3 (d) (i))

MOT #6		2023-03-16 14:57
MOT test	number	217894096833
Result		✓ Passed
Advice	Nearside Front Lower ball joint dust cover covered in grease	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #5		2023-03-16 14:57
MOT test number		886742978584
Result		🗙 Failed
Pass with rectification	Offside Headlamp aim too high (4.1.2 (a))	
Advice Nearside Front Lower ball joint dust cover covered in grease		
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		

MOT #4	2022-03-17 10:27
MOT test number	890257130407
Result	✓ Passed

MOT #3	2021-03-03 15:50
MOT test	: number 140390794496
Result	✓ Passed
Minor	Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #2	2021-03-02 09:46	
MOT test number	477646107907	
Result	🗙 Failed	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		
Minor Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #1	2020-03-10 09:50
MOT test number	166973986733
Result	✓ Passed
Advice Offside Front washer jet not working	



Tax & MOT check

✓	✓
Taxed	MOT
Tax due:	Expires:
1 June 2024	16 March 2025
Tax status	Valid until 1 June
Days left	33
MOT expiry date	16 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	D
First licence fee (12 months)	£ 120,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-





Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERRE
Category	Lamp
Туре	
Damage 2	AMPLI
Damage 2	E Stand
Date	*
Category	AMP
Туре	

Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

ana	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-04-21
Last registration	2024-03-15
Complete history	<u>See info</u>



Registration #1	2017-04-21	14 mi
Registration #2	2020-03-10	16.522 mi
Registration #3	2021-03-02	22.020 mi
Registration #4	2021-03-03	22.052 mi
Registration #5		11.777 esi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 esi

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
\$0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	95%
Children	77%
Pedestrian	76%
Safety systems	78%
Overall rating	84%
Video	see crash video



Dimensions & weight	
Width	1795 mm
Height	2640 mm
Length	4360 mm
Wheel base	2640 mm
Kerb weight	1420 kg
Max. allowed weight	1860 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	2ZRV420722