





report date: 2024-03-28

## General information

Make	HYUNDAI
Model	IX20 ACTIVE
Colour	Blue
Year of manufacture	2014
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	4 speed automatic

## Engine & fuel consumption

Power	123 BHP
Max. torque	156 Nm at 4.200 rpm
Engine capacity	1.591 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	154 g/km
CO2 label	G



CarCheck.co.uk page 1/12



# Internet history

## Entry 1


Date 2021-09-02

Pictures 35

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



# MOT history

MOT expiry date	2024-10-25
MOT pass rate	90 %
MOT passed	9
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #10		2023-10-25 10:01
MOT test	number	832093083286
Result		✓ Passed
Next expi	ry date	2024-10-25
Advice	Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c)	))
Advice	Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #9	2022-10-26 11:15
MOT test number	616320470289
Result	✓ Passed
Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))	

MOT #8	2021-09-21 11:21
MOT test number	598388949315
Result	✓ Passed

CarCheck.co.uk page 3/12



**MOT #7** 2021-09-21 09:41

MOT test number 798415888125

Result X Failed

Fail Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #6 2021-03-25 10:34

MOT test number 946840389188

Result \(\sqrt{Passed}\)

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords 205/55/16 (5.2.3 (d) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))

**MOT #5** 2020-03-30 09:22

MOT test number 598362961586

Result \rightarrow Passed

**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened x2 (1.1.14 (a) (ii))

MOT #4 2019-03-26 11:09

MOT test number 753923239623

Result \rightarrow Passed

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing 205/55/16 (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 205/55/16 (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge 205/55/16 (5.2.3 (e))

MOT #3 2018-04-03 11:00

**MOT test number** 581315743133

**Result** ✓ Passed

CarCheck.co.uk page 4/12



MOT #2	2018-01-30 13:52
MOT test number	870450088255
Result	<b>✓</b> Passed
MOT #1	2017-02-03 16:40
MOT test number	349246175865
Result	✓ Passed

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 October
Days left	155
MOT expiry date	25 October 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



### Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report <a href="https://example.com/here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



### Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	
*********	
***************************************	
************	
*********	
***************************************	
************	
Plate changes	More info >
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Correct registration	NK SIE
Plate since	
Current registration	NK SIE
Plate since	
	More info

CarCheck.co.uk page 9/12



### Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-01-15
Last registration	2023-10-25
Complete history	See info



Registration #1	2014-01-15	12 mi
Registration #2	2017-02-03	13.378 mi
Registration #3	2018-01-30	20.999 mi
Registration #4	2018-04-03	21.497 mi
Registration #5	2019-03-26	25.032 mi
Registration #6	2020-03-30	29.198 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

# Safety ratings

NCAP rating	****
Adult	89%
Children	85%
Pedestrian	64%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1600 mm
Length	4100 mm
Wheel base	2615 mm
Kerb weight	1294 kg
Max. allowed weight	1730 kg

# Additional information

Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

**Engine number** G4FCEZ336660