





General information

Make	PEUGEOT
Model	206 VERVE E4
Colour	Silver
Year of manufacture	-
Top speed	106 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	74 BHP
Max. torque	120 Nm at 3.400 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	31.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	44.1 mpg





Internet history

Entry	1
Date	

Pictures

2021-06-04

32

Listing price

View report



source: autotrader.co.uk



MOT history

MOT #19	2022-03-18 13:25
MOT test number	509936997906
Result	✓ Passed
Next expiry date	2023-03-19
Advice Play in steering rack inner joint(s) both	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Rear fuel pipe clip broken	
Advice Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or (i))	light sources (4.7.1 (b)
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



GP06VVX report date: 2024-03-28

MOT #18 20	22-03-16 12:23
MOT test number	202758517010
Result	🗙 Failed
Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))	
Fail Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
FailNearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress(b) (ii))	of dirt (5.3.4
Advice Play in steering rack inner joint(s) both	
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	
Advice Front Registration plate deteriorated but not likely to be misread damaged (0.1 (b))	
Advice Rear fuel pipe clip broken	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	
Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sour (i))	ces (4.7.1 (b)
FailOffside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of(ii))	dirt (5.3.4 (b)

MOT #17	2021-03-17 10:17
MOT test number	567879891431
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (6.1.2 (a))	

MOT #16	2020-03-20 14:35
MOT test	number 661101502615
Result	✓ Passed
Advice Nearside Rear Direction indicator slightly affected by the operation of another lamp (4.4.3 (b))	
Advice	Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))





MOT #15	2019-03-01 15:04	
MOT test number	535920647757	
Result	✓ Passed	
MOT #14	2019-03-01 15:04	
MOT test number	976342548237	
Result	× Failed	
Pass with rectification	Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Pass with rectification	Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #13	2018-02-23 15:08
MOT test number	408834381788
Result	✓ Passed

MOT #12	2018-02-23 11:24
MOT test number	365249064885
Result	🗙 Failed
Fail Rear Exhaust system not adequately supported (7.1.1)	
FailNearside Front position lamp(s) not working (1.1.A.3b)	
Fail Rear fog lamp not working (1.3.2b)	

MOT #11	2017-03-06 12:13
MOT test	number 899168108334
Result	✓ Passed
Advice Offside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Advice	Nearside Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)





MOT #10	2016-01-11 18:05
MOT test number	770381959007
Result	✓ Passed
MOT #9	2014-12-05 18:16
MOT test number	819809534386
Result	✓ Passed
MOT #8	2014-01-20 08:42
MOT test number	116110024077
Result	✓ Passed
MOT #7	2013-01-19 08:31
MOT test number	206429813034
Result	✓ Passed
MOT #6	2012-01-24 11:17
MOT test number	989364422063
Result	✓ Passed
MOT #5	2011-01-12 14:09
MOT test number	819562211072
Result	✓ Passed
MOT #4	2010-07-07 11:33
MOT test number	281938780484
Result	✓ Passed



GP06VVX report date: 2024-03-28

MOT #3		2010-07-07 11:33
MOT test number		271048380438
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too low (1.8)	
Pass with rectification	Offside Headlamp aim too low (1.8)	

MOT #2	2009-07-10 11:20
MOT test number	673631399173
Result	✓ Passed
MOT #1	2009-07-10 11:20
MOT test number	942821399117
Result	× Failed
Pass with rectification by more than 40mm outside	Windscreen has a sticker or other obstruction encroaching into the swept area zone 'A' (8.3.1e)
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Pass with rectification	Nearside Headlamp aim too high (1.8)
Pass with rectification	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)





Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. DEM PE
Туре	
Damage 2	AMPL
Date	ALL I
Category	ant.
Туре	

Extra PEUGEOT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



GP06VVX report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-07-21
Last registration	2022-03-18
Complete history	See info



Registration #2 2009-07-10 18.046 m Registration #3 2010-07-07 22.159 m Registration #4 2011-01-12 24.785 m Registration #5 2012-01-24 27.579 m Registration #6 2013-01-19 28.948 m Registration #7 2014-01-20 30.415 m Registration #8 2014-12-05 31.301 m Registration #9 2016-01-11 35.545 m			
Registration #3 2010-07-07 22.159 m Registration #4 2011-01-12 24.785 m Registration #5 2012-01-24 27.579 m Registration #6 2013-01-19 28.948 m Registration #6 2014-01-20 30.415 m Registration #7 2014-01-20 30.415 m Registration #8 2014-12-05 31.301 m Registration #9 2016-01-11 35.545 m Registration #10 2017-03-06 38.914 m Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T Registration #16 T T Registration #17 T T Registration #18 T T	Registration #1	2006-07-21	28 mi
Registration #4 2011-01-12 24.785 m Registration #5 2012-01-24 27.579 m Registration #6 2013-01-19 28.948 m Registration #7 2014-01-20 30.415 m Registration #7 2014-01-20 30.415 m Registration #8 2014-01-20 30.415 m Registration #8 2016-01-11 35.545 m Registration #10 2017-03-06 38.914 m Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T Registration #16 T T Registration #18 T T	Registration #2	2009-07-10	18.046 mi
Registration #5 2012-01-24 27.579 m Registration #6 2013-01-19 28.948 m Registration #7 2014-01-20 30.415 m Registration #8 2014-01-20 30.415 m Registration #8 2014-12-05 31.301 m Registration #9 2016-01-11 35.545 m Registration #10 2017-03-06 38.914 m Registration #11 T T Registration #12 T T Registration #13 T T Registration #14 T T Registration #15 T T Registration #16 T T Registration #17 T T Registration #18 T T	Registration #3	2010-07-07	22.159 mi
Registration #6 2013-01-19 28.948 mi Registration #7 2014-01-20 30.415 mi Registration #8 2014-12-05 31.301 mi Registration #9 2016-01-11 35.545 mi Registration #10 2017-03-06 38.914 mi Registration #10 2017-03-06 38.914 mi Registration #11 Image: Contract of the state of the	Registration #4	2011-01-12	24.785 mi
Registration #7 2014-01-20 30.415 m Registration #8 2014-12-05 31.301 m Registration #9 2016-01-11 35.545 m Registration #10 2017-03-06 38.914 m Registration #11 Image: Constraint of the second sec	Registration #5	2012-01-24	27.579 mi
Registration #8 2014-12-05 31.301 ml Registration #9 2016-01-11 35.545 ml Registration #10 2017-03-06 38.914 ml Registration #11 2017-03-06 38.914 ml Registration #11 2017-03-06 38.914 ml Registration #11 2017-03-06 38.914 ml Registration #12 2017 2017 Registration #13 2017 2017 Registration #14 2017 2017 Registration #15 2017 2017 Registration #16 2017 2017 Registration #17 2017 2017 Registration #18 2017 2017	Registration #6	2013-01-19	28.948 mi
Registration #92016-01-1135.545 mRegistration #102017-03-0638.914 mRegistration #112017-03-0638.914 mRegistration #122017-03-0638.914 mRegistration #132017-03-0638.914 mRegistration #142017-03-0638.914 mRegistration #152017-03-0638.914 mRegistration #162017-03-0638.914 mRegistration #172017-03-0638.914 mRegistration #182017-03-0638.914 m	Registration #7	2014-01-20	30.415 mi
Registration #102017-03-0638.914 millionRegistration #11Control of the second sec	Registration #8	2014-12-05	31.301 mi
Registration #11Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18	Registration #9	2016-01-11	35.545 mi
Registration #12Registration #13Registration #14Registration #15Registration #16Registration #17Registration #18	Registration #10	2017-03-06	38.914 mi
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	Registration #11		11.707 est
Registration #14 Registration #15 Registration #16 Registration #17 Registration #18	Registration #12		11.777 esi
Registration #15 Registration #16 Registration #17 Registration #18	Registration #13		11.707 est
Registration #16 Registration #17 Registration #18	Registration #14		11.777 est
Registration #17 Registration #18	Registration #15		11.777 est
Registration #18	Registration #16		11.777 est
	Registration #17		11.777 mi
Registration #19	Registration #18		11.777 est
	Registration #19		11.777 est





Car features

S0225	Air conditioning
S0295	
50482	
\$0501	
50566	
\$0567	
S0569	

Safety ratings

NCAP rating

Video

**** see crash video



Dimensions & weight	
Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	1025 kg
Max. allowed weight	1450 kg
Additional information	
Fuel tank capacity	50 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 13/13

Number of axles	2
Engine number	FST65298536