




report date: 2024-03-29

General information

Make	SUZUKI
Model	IGNIS SZ-T DUALJET
Colour	White
Year of manufacture	2018
Top speed	105 mph
0 - 60 mph	11.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	120 Nm at 4.400 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	68.9 mpg
Consumption combined	61.4 mpg
CO2 emission	104 g/km
CO2 label	B





Internet history

Entry 2

Date	2023-05-08
Pictures	0
Listing price	View report

source: [carcraft.co.uk](#)

Entry 1

Date	2021-02-04
Pictures	1
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-11-15
MOT pass rate	67 %
MOT passed	4
Failed MOT tests	2
Total advice items	15
Total items failed	2

MOT #6	2023-11-16 16:27
MOT test number	106859052486
Result	✓ Passed
Next expiry date	2024-11-15

MOT #5	2023-06-06 09:13
MOT test number	528790144316
Result	✓ Passed

MOT #4	2022-08-24 13:42
MOT test number	749047754548
Result	✓ Passed

**MOT #3**

2022-07-19 14:25

MOT test number

463923673807

Result**✗ Failed****Advice** Offside Front Tyre worn close to legal limit/worn on edge 2.8mm (5.2.3 (e))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #2**

2021-07-12 09:27

MOT test number

667647902971

Result**✓ Passed****Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



MOT #12021-07-12 09:26

MOT test number461315324234

Result

Failed

Pass with rectificationOffside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

AdviceOffside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

AdviceOffside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

AdviceNearside Rear Child Seat fitted not allowing full inspection of adult belt

AdviceNearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

AdviceNearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
15 November 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	15 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
First licence fee (12 months)	£ 185,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2018-07-26
Last registration	2023-11-16
Complete history	See info



Registration #1	2018-07-26	12 mi
Registration #2	2019-07-12	7.506 mi
Registration #3	2021-07-12	7.506 mi
Registration #4	2021-07-12	7.506 mi
Registration #5	2022-07-19	10.924 mi
Registration #6	2023-07-12	10.924 mi
Registration #7	2023-07-12	10.924 mi
Registration #8	2023-07-12	10.924 mi
Registration #9	2023-07-12	10.924 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	87%
Children	79%
Pedestrian	77%
Safety systems	60%
Overall rating	78%
Video	see crash video



Copyright © 2016 Euro NCAP

Dimensions & weight

Width	1690 mm
Height	1595 mm
Length	3700 mm
Wheel base	2435 mm
Kerb weight	885 kg
Max. allowed weight	1330 kg

Additional information

Fuel tank capacity	32 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K12C-5248274