



TOYOTA

GU56TWV


report date: 2024-03-29

General information

Make	TOYOTA
Model	RAV-4
Colour	Black
Year of manufacture	2006
Gearbox	-

Engine & fuel consumption

Engine capacity	1.998 cc
Fuel type	Petrol
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-10-30
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk





## MOT history

MOT expiry date	2022-11-03
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	48
Total items failed	16

MOT #18 2021-10-21 07:36

MOT test number 526463592897

Result ✓ Passed

Next expiry date 2022-11-03

- Advice** Ns front lower drop link boot is perishing
- Advice** Rear Coil spring corroded Both (5.3.1 (b) (i))
- Advice** Rear bumper is damaged
- Advice** Central Exhaust has a minor leak of exhaust gases Silencer corroded and leaking (6.1.2 (a))
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement Trail arm bushes are perishing (5.3.4 (a) (i))
- Minor** Offside Rear Rear fog lamp insecure (4.5.1 (c) (i))

MOT #17 2020-10-26 13:21

MOT test number 476996902712

Result ✓ Passed

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge edges (5.2.3 (e))

**MOT #16** 2019-10-25 08:35**MOT test number** 790271074179**Result** ✓ Passed**Advice** Rear no plate mounting is loose**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear bumper is damaged**MOT #15** 2019-10-24 07:35**MOT test number** 337294796396**Result** ✗ Failed**Fail** Offside Body component damaged and likely to cause injury Mirror cover missing (6.2.1 (a) (i))**Advice** Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Rear no plate mounting is loose**Fail** Nearside Front Bumper insecure (6.1.4 (a) (i))**Advice** Rear bumper is damaged**MOT #14** 2018-10-25 07:29**MOT test number** 712334675000**Result** ✓ Passed**Advice** Front bumper damage**Minor** Driver's view to the front outside the swept area of the windscreen wipers restricted by an obstruction (3.1 (a) (i))**Advice** Nock in steering coloum**Advice** O\s front mirrow cover missing

**MOT #13** 2017-10-26 07:33**MOT test number** 270202364422**Result** ✓ Passed**Advice** FRONT SUSPENSION ARMS REAR MOUNTS SPLITTING**Advice** REAR COIL SPRINGS CORRODING**MOT #12** 2017-10-26 07:33**MOT test number** 571041230502**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**Advice** FRONT SUSPENSION ARMS REAR MOUNTS SPLITTING**Advice** REAR COIL SPRINGS CORRODING**MOT #11** 2016-10-20 15:45**MOT test number** 628294078538**Result** ✓ Passed**Advice** V S C system fault in words illuminated**Advice** Eml on**Advice** Rear coil springs are very corroded

**MOT #10** 2016-10-20 09:23**MOT test number** 203431569250**Result** ✗ Failed**Advice** Rear coil springs are very corroded**Advice** V S C system fault in words illuminated**Fail** Exhaust emissions carbon monoxide content after 2nd fast idle excessive (7.3.D.3)**Advice** Eml on**Fail** Exhaust emissions carbon monoxide content at idle excessive (7.3.D.4)**MOT #9** 2015-10-07 14:03**MOT test number** 237751956100**Result** ✓ Passed**MOT #8** 2015-10-07 08:19**MOT test number** 886956133362**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #7** 2014-10-09 08:56**MOT test number** 516562984288**Result** ✓ Passed**Notice** Both front lower arm bushes perished**Notice** All 4 tyres cracked on sidewalls



MOT #6 2014-10-08 09:28

MOT test number 335931184207

Result ✗ Failed

**Fail** Nearside Rear Anti-roll bar linkage fractured (2.4.G.1)

**Fail** Parking brake lever has no reserve travel (3.1.6b)

**Notice** All 4 tyres cracked on sidewalls

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Slight knock felt at steering wheel

**Pass with rectification** Offside Front Headlamp aim too low (1.8)

**Pass with rectification** Offside Front Front position lamp(s) not working (1.1.A.3b)

**Fail** Offside Rear Anti-roll bar linkage fractured (2.4.G.1)

**Notice** Brake fluid level on minimum

**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Notice** Both front lower arm bushes perished

**Pass with rectification** Nearside Front Headlamp aim too low (1.8)

**Pass with rectification** Nearside Front Front position lamp(s) not working (1.1.A.3b)

MOT #5 2013-11-04 09:19

MOT test number 417968403396

Result ✓ Passed

**Notice** Front brake discs worn

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Rear brake discs rusty

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2013-11-04 09:19**MOT test number** 319038303318**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Notice** Rear brake discs rusty**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Front brake discs worn**MOT #3** 2012-10-09 12:16**MOT test number** 957063882215**Result** ✓ Passed**MOT #2** 2011-10-03 11:19**MOT test number** 349266671253**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #1** 2010-04-22 12:27**MOT test number** 254432210164**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)





Tax & MOT check

✕  
Untaxed

Tax expired:  
30 October 2021

✕  
MOT

Expired:  
3 November 2022

Tax status	Expired at 30 October 2021
Days left	911 days too late
MOT expiry date	3 November 2022
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2006-10-24
Last registration	2021-10-21
Complete history	<a href="#">See info</a>



Registration #1	2006-10-24	25 mi
Registration #2	2010-04-22	33.708 mi
Registration #3	2011-10-03	44.448 mi
Registration #4	2012-10-09	60.761 mi
Registration #5	2013-11-04	71.527 mi
Registration #6	2014-10-08	76.209 mi
Registration #7	2014-10-09	76.209 mi
Registration #8	2015-10-07	82.097 mi
Registration #9	2015-10-07	82.097 mi
Registration #10	2016-10-20	88.845 mi
Registration #11	2016-10-20	88.845 mi
Registration #12	2016-10-20	88.845 mi
Registration #13	2016-10-20	88.845 mi
Registration #14	2016-10-20	88.845 mi
Registration #15	2016-10-20	88.845 mi
Registration #16	2016-10-20	88.845 mi
Registration #17	2016-10-20	88.845 mi
Registration #18	2016-10-20	88.845 mi
Registration #19	2016-10-20	88.845 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats 5

Engine number NOT KNOWN