



report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Black
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	12.4 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	144 BHP
Max. torque	185 Nm at 4.000 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	44.1 mpg
Consumption combined	34.4 mpg
CO2 emission	198 g/km
CO2 label	J






Internet history

Entry 1

Date	2021-12-20
Pictures	23
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-07
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	55
Total items failed	9

MOT #19	2024-01-06 12:15
MOT test number	603345413823
Result	✓ Passed
Next expiry date	2025-01-07

MOT #18	2024-01-06 12:15
MOT test number	502271570498
Result	✗ Failed
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
Pass with rectification	Front Windscreen washer provides insufficient washer liquid (3.5 (a))
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #17	2023-01-05 11:53
MOT test number	372175018248
Result	✓ Passed
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #16	2022-01-08 08:39
MOT test number	987901125848
Result	✓ Passed

**MOT #15** 2021-02-19 11:15**MOT test number** 254531167431**Result** ✓ Passed**Advice** Nearside Rear Brake disc slightly corroded.**Advice** Offside Rear Brake disc slightly corroded.**MOT #14** 2020-02-15 08:45**MOT test number** 363938456568**Result** ✓ Passed**Advice** Exhaust heat shield insecure**MOT #13** 2020-02-14 11:55**MOT test number** 546467766016**Result** ✗ Failed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Exhaust heat shield insecure**DANGEROUS** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened both (1.1.14 (a) (ii))

**MOT #12**

2019-02-14 09:59

MOT test number

708914647471

Result

✓ Passed

- Advice** Offside Rear child seat fitted preventing complete inspection of an adult seat belt.
- Advice** Rear Brake pad(s) wearing thin both o/s & n/s (1.1.13 (a) (ii))
- Advice** Undertray fitted preventing thorough inspection of under vehicle components
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened both o/s & n/s (1.1.14 (a) (ii))
- Advice** Corrosion to suspension components.

MOT #11

2018-01-29 15:08

MOT test number

819529420941

Result

✓ Passed

- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both o/s + n/s (3.5.1i)
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Under trays fitted preventing through inspection of under vehicle components.
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Front Upper Macpherson strut has slight movement in the upper support bearing assembly both o/s + n/s (2.5.B.1b)
- Advice** Corrosion to suspension components

**MOT #10**

2018-01-29 10:56

MOT test number

520814328113

Result

✗ Failed

- Fail** Front Inner Brake pad(s) less than 1.5 mm thick both o/s + n/s (3.5.1g)
- Fail** Nearside Rear Inner Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
- Advice** Under trays fitted preventing through inspection of under vehicle components.
- Advice** Front Upper Macpherson strut has slight movement in the upper support bearing assembly both o/s + n/s (2.5.B.1b)
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Fail** Offside Rear Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both o/s + n/s (3.5.1i)
- Advice** Corrosion to suspension components
- Advice** Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #9

2017-02-16 13:59

MOT test number

287363585267

Result

✓ Passed

- Advice** Child seats fitted not allowing full inspection of an adult belt
- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)
- Advice** Oil leak
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2016-02-15 12:29**MOT test number** 174702997075**Result** ✓ Passed

- Advice** Front Tyre worn close to the legal limit bothside (4.1.E.1)
- Advice** Parking brake lever has little reserve travel (3.1.6b)
- Advice** Front Brake pad(s) wearing thin bothside (3.5.1g)
- Advice** Nearside Front Lower Suspension arm synthetic bush deteriorated but not resulting in excessive movement rear (2.4.G.2)

MOT #7 2015-02-16 10:26**MOT test number** 617267445035**Result** ✓ Passed

- Notice** Engine covers fitted obscuring some components in the engine bay
- Notice** Under-trays fitted obscuring some underside components
- Notice** Child seat fitted not allowing full inspection of adult belt

MOT #6 2014-02-15 13:49**MOT test number** 157776344497**Result** ✓ Passed**MOT #5** 2013-02-12 17:14**MOT test number** 186763443071**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components
- Notice** Vehicle's internal headlight adjuster altered to recheck lights
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Engine covers fitted obscuring some components in the engine bay

**MOT #4**

2013-02-12 12:31

MOT test number

148953343062

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Offside rear tyre slightly perished/cracked around the outer edge
- Notice** Offside rear tyre bald around the inner edge
- Notice** Offside rear tyre has a small chunk missing from the outer wall, however no cords or ply exposed
- Notice** Engine covers fitted obscuring some components in the engine bay
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Notice** Nearside rear tyre slightly perished/cracked around the outer edge
- Notice** Nearside rear tyre bald around the inner edge
- Notice** Offside rear tyre has a cut in the tread on the inside edge, however not deep enough to reach the ply or cords
- Notice** Under-trays fitted obscuring some underside components
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Notice** Vehicle's internal headlight adjuster altered to recheck lights

MOT #3

2012-02-11 12:43

MOT test number

915432142098

Result**✓ Passed**

- Notice** Offside rear tyre worn inner wall



MOT #2	2012-02-11 11:51
MOT test number	165902942413
Result	✗ Failed
Notice	Offside rear tyre worn inner wall
Notice	Nearside front tyre worn inner wall
Fail	Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #1	2011-02-03 16:01
MOT test number	107284831439
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
7 January 2025

Tax status	Valid until 1 August
Days left	94
MOT expiry date	7 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-01-29
Last registration	2024-01-06
Complete history	See info



Registration #1	2008-01-29	15 mi
Registration #2	2011-02-03	13.486 mi
Registration #3	2012-02-11	18.245 mi
Registration #4	2012-02-11	18.245 mi
Registration #5	2013-02-12	20.430 mi
Registration #6	2013-02-12	20.430 mi
Registration #7	2014-02-15	23.890 mi
Registration #8	2015-02-16	27.378 mi
Registration #9	2016-02-15	29.752 mi
Registration #10	2017-02-16	32.988 mi
Registration #11	2018-01-29	35.514 mi
Registration #12	2019-01-29	35.514 mi
Registration #13	2019-01-29	35.514 mi
Registration #14	2019-01-29	35.514 mi
Registration #15	2019-01-29	35.514 mi
Registration #16	2019-01-29	35.514 mi
Registration #17	2019-01-29	35.514 mi
Registration #18	2019-01-29	35.514 mi
Registration #19	2019-01-29	35.514 mi
Registration #20	2019-01-29	35.514 mi
Registration #21	2019-01-29	35.514 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4505 mm
Wheel base	2750 mm
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	LF10510608