



RENAULT

 **K9DBA**


report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE SCENIC EXPRESSION + 16V SCENIC
Colour	Green
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	11.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	148 Nm at 3.750 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg





Internet history

Entry 1

Date	2021-09-22
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)

**MOT history**

MOT #22	2022-01-06 16:50
MOT test number	459612814543
Result	✓ Passed
Next expiry date	2023-01-05
MOT #21	2020-12-02 13:19
MOT test number	284804127828
Result	✓ Passed
MOT #20	2019-12-13 12:31
MOT test number	461620602090
Result	✓ Passed
MOT #19	2018-12-20 13:04
MOT test number	710762105557
Result	✓ Passed
MOT #18	2017-12-22 11:18
MOT test number	757799879572
Result	✓ Passed
MOT #17	2016-12-13 11:07
MOT test number	669425022615
Result	✓ Passed
MOT #16	2015-12-17 08:12
MOT test number	319466966543
Result	✓ Passed

**MOT #15** 2015-12-16 14:22**MOT test number** 979904610494**Result** ✗ Failed**Fail** Hazard warning switch faulty (1.4.B.1d)**MOT #14** 2014-12-01 13:02**MOT test number** 648225334399**Result** ✓ Passed**MOT #13** 2013-12-20 11:49**MOT test number** 806544853382**Result** ✓ Passed**MOT #12** 2012-12-21 09:56**MOT test number** 857416752331**Result** ✓ Passed**MOT #11** 2011-12-22 15:00**MOT test number** 949006051381**Result** ✓ Passed**Notice** Rear number plate starting to deteriorate**Notice** Excessive corrosion to rear lateral cross bar across floor pans**Notice** Nearsaide and offside front tyres wearing on inner edges

**MOT #10**

2011-12-22 10:03

MOT test number

357176051346

Result**✗ Failed**

- Notice** Brake fluid level low
- Notice** Nearsaide and offside front tyres wearing on inner edges
- Notice** Front brake discs pitted and corroded
- Fail** Front brake application uneven (3.7.B.2)
- Notice** Coolant level low
- Notice** Nearside front brake binding slightly
- Notice** Excessive corrosion to rear lateral cross bar across floor pans
- Fail** Offside Outer Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)
- Notice** Rear brake discs pitted and corroded
- Fail** Front brakes release unevenly (3.7.B.4)
- Notice** Rear number plate starting to deteriorate

MOT #9

2010-12-20 13:04

MOT test number

584414050346

Result**✓ Passed**

- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Notice** Rear suspension lateral bar corroded to excess
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)

**MOT #8** 2010-12-20 10:06**MOT test number** 203854650339**Result** ✗ Failed**Notice** Rear suspension lateral bar corroded to excess**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Front constant velocity joint gaiter insecurely mounted to its housing (2.5.C.1a)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2009-12-17 10:46**MOT test number** 414471759493**Result** ✓ Passed**MOT #6** 2008-12-12 14:53**MOT test number** 700067248309**Result** ✓ Passed**MOT #5** 2007-12-22 10:44**MOT test number** 743936057347**Result** ✓ Passed**MOT #4** 2006-12-28 14:01**MOT test number** 801072766317**Result** ✓ Passed**MOT #3** 2006-12-28 14:01**MOT test number** 611162066308**Result** ✗ Failed**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)



MOT #2	2005-12-29 15:37
MOT test number	801413565384
Result	✓ Passed

MOT #1	2005-12-29 14:37
MOT test number	513153665357
Result	✗ Failed
Fail	Offside Rear Lower Mechanical brake component has restricted free movement (3.5.1k)
Fail	Offside Front Lower Mechanical brake component has restricted free movement (3.5.1k)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	 *****
Plate since	2023-03-28
Current registration	 *****
Plate since	2023-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-01-02
Last registration	2022-01-06
Complete history	See info



Registration #1	2002-01-02	23 mi
Registration #2	2005-12-29	21.837 mi
Registration #3	2005-12-29	21.837 mi
Registration #4	2006-12-28	26.319 mi
Registration #5	2007-12-22	29.811 mi
Registration #6	2008-12-12	33.592 mi
Registration #7	2009-12-17	37.957 mi
Registration #8	2010-12-20	40.748 mi
Registration #9	2010-12-20	40.748 mi
Registration #10	2011-12-22	44.082 mi
Registration #11	2011-12-22	44.082 mi
Registration #12	2012-12-21	45.670 mi
Registration #13	2013-12-20	45.670 mi
Registration #14	2013-12-20	45.670 mi
Registration #15	2013-12-20	45.670 mi
Registration #16	2013-12-20	45.670 mi
Registration #17	2013-12-20	45.670 mi
Registration #18	2013-12-20	45.670 mi
Registration #19	2013-12-20	45.670 mi
Registration #20	2013-12-20	45.670 mi
Registration #21	2013-12-20	45.670 mi
Registration #22	2013-12-20	45.670 mi
Registration #23	2013-12-20	45.670 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★★

Video [see crash video](#)

Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1250 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D672680