



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	207 SPORT
Colour	Black
Year of manufacture	2010
Top speed	115 mph
0 - 60 mph	12.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 cc
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E





## MOT history

MOT expiry date	2020-05-28
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	22
Total items failed	13

MOT #12	2020-06-04 15:26
MOT test number	971981269590
Result	✓ Passed
Next expiry date	2021-06-03

MOT #11	2020-05-28 10:37
MOT test number	479954637138

Result	✗ Failed
--------	----------

- Fail** Nearside Rear Position lamp lens seriously defective (4.2.1 (b))
- Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))
- Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Fail** Nearside Rear Body component damaged and likely to cause injury light unit (6.2.1 (a) (i))
- Fail** Front Exhaust system insecure (6.1.2 (a))
- Advice** Exhaust shield loose

**MOT #10**

2019-05-23 14:58

**MOT test number**

552762279931

**Result**

✓ Passed

**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2019-05-23 08:07

**MOT test number**

542114939231

**Result**

✗ Failed

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Rear Body component damaged and likely to cause injury light cluster damaged (6.2.1 (a) (i))**Advice** Front Exhaust mounting defective (6.1.2 (a))**Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #8**

2018-05-03 09:53

**MOT test number**

600575397439

**Result**

✓ Passed

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear The tyre is cracking slightly

**MOT #7** 2018-05-03 09:27**MOT test number** 984354710104**Result** ✗ Failed

**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Nearside Rear The tyre is cracking slightly

**MOT #6** 2017-05-16 10:41**MOT test number** 838905955998**Result** ✓ Passed

**Advice** Offside Rear Slight cracking on tyre side wall and tread

**Advice** Nearside Front Tyre worn on outer edge

**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #5** 2017-05-16 09:35**MOT test number** 789571674615**Result** ✗ Failed

**Fail** Nearside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Advice** Offside Rear Slight cracking on tyre side wall and tread

**Advice** Nearside Front Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**Fail** Rear Exhaust system not adequately supported (7.1.1)

**Advice** Nearside Front Tyre worn on outer edge

**Fail** Offside Front Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

**Fail** Front Exhaust system not adequately supported (7.1.1)



MOT #4	2016-05-26 10:01
MOT test number	768859471986
Result	✓ Passed
MOT #3	2015-07-07 09:38
MOT test number	335978285194
Result	✓ Passed
MOT #2	2014-06-11 12:43
MOT test number	196522864179
Result	✓ Passed
MOT #1	2013-06-17 15:18
MOT test number	116808063111
Result	✓ Passed
<div><div>Notice</div>Items removed from driver's view prior to test</div> <div><div>Notice</div>Exhaust mounting braket snapped</div>	



Tax & MOT check

X

Untaxed

Tax expired:  
28 February 2021

X

MOT

Expired:  
28 May 2020

Tax status	Expired at 28 February 2021
Days left	1157 days too late
MOT expiry date	28 May 2020
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >





Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2010-06-30
Last registration	2020-06-04
Complete history	<a href="#">See info</a>



Registration #1	2010-06-30	18 mi
Registration #2	2013-06-17	15.249 mi
Registration #3	2014-06-11	18.567 mi
Registration #4	2015-07-07	20.482 mi
Registration #5	2016-05-26	23.845 mi
Registration #6	2017-05-16	30.657 mi
Registration #7	2017-05-16	30.657 mi
Registration #8	2019-05-20	35.277 mi
Registration #9	2019-05-20	35.277 mi
Registration #10	2019-05-20	35.277 mi
Registration #11	2019-05-20	35.277 mi
Registration #12	2019-05-20	35.277 mi
Registration #13	2019-05-20	35.277 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1972 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1234 kg
Max. allowed weight	1643 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	FGAR0808671