



report date: 2024-03-28

General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2021-07-01
Pictures	6
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-12
Pictures	6
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)

**MOT history**

<b>MOT #13</b>	2021-09-03 14:38
<b>MOT test number</b>	892016473178
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2022-09-02

<b>MOT #12</b>	2020-08-01 10:41
<b>MOT test number</b>	708097653979
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Coil spring corroded (5.3.1 (b) (i))

<b>MOT #11</b>	2020-08-01 10:41
<b>MOT test number</b>	998027256178
<b>Result</b>	✗ Failed
<b>Advice</b>	Rear Coil spring corroded (5.3.1 (b) (i))
<b>Pass with rectification</b>	Windscreen washer provides insufficient washer liquid (3.5 (a))

<b>MOT #10</b>	2019-02-15 11:51
<b>MOT test number</b>	594338914105
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Front tyre worn low on inside edge
<b>Advice</b>	Nearside Front tyre worn low on inside edge

**MOT #9**

2018-02-21 17:04

**MOT test number**

345193747049

**Result**

✓ Passed

**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Offside Front tyre worn low on inside edge

**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement rear bush (2.4.G.2)

**Advice** Nearside Front tyre worn low on inside edge

**MOT #8**

2017-03-03 15:26

**MOT test number**

119109630330

**Result**

✓ Passed

**Advice** Both rear tyres are worn close to the legal limit and are badly wearing on inside edges.

**MOT #7**

2017-03-03 09:56

**MOT test number**

721006396385

**Result**

✗ Failed

**Fail** Nearside Rear Seat belt locking mechanism does not secure or release (5.2.5a)

**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Pass with rectification** Offside Headlamp aim too low (1.8)

**Advice** Both rear tyres are worn close to the legal limit and are badly wearing on inside edges.

**Fail** Offside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)

**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #6**

2016-05-27 10:34

**MOT test number**

993416385884

**Result**

✓ Passed

**MOT #5** 2016-05-27 10:34**MOT test number** 493391535673**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)**MOT #4** 2015-06-03 10:23**MOT test number** 497724655155**Result** ✓ Passed**Notice** Oil leak/ over filled**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #3** 2014-05-19 10:38**MOT test number** 677359834169**Result** ✓ Passed**MOT #2** 2013-05-13 13:48**MOT test number** 158833933142**Result** ✓ Passed**MOT #1** 2012-05-29 17:32**MOT test number** 228500752180**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	ND09LXR
Plate since	2019-03-28
Current registration	ND09LXR
Plate since	2019-03-28

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-06-04
Last registration	2021-09-03
Complete history	<a href="#">See info</a>



Registration #1	2009-06-04	17 mi
Registration #2	2012-05-29	52.445 mi
Registration #3	2013-05-13	63.480 mi
Registration #4	2014-05-19	75.086 mi
Registration #5	2015-06-03	90.129 mi
Registration #6	2016-05-27	105.476 mi
Registration #7	2016-05-27	105.476 mi
Registration #8	2017-03-03	115.175 mi
Registration #9	2018-03-03	125.175 mi
Registration #10	2019-03-03	135.175 mi
Registration #11	2020-03-03	145.175 mi
Registration #12	2021-03-03	155.175 mi
Registration #13	2022-03-03	165.175 mi
Registration #14	2023-03-03	175.175 mi
Registration #15	2024-03-03	185.175 mi
Registration #16	2025-03-03	195.175 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C73512