



TOYOTA

R0560UY

report date: 2024-03-28

General information

Make	TOYOTA
Model	COROLLA VERSO D-4D T2
Colour	Silver
Year of manufacture	-
Top speed	122 mph
0 - 60 mph	9.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	310 Nm at 2.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg






Internet history

Entry 1

Date	2021-10-28
Pictures	5
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #15	2020-09-28 15:49
MOT test number	560781757196
Result	✓ Passed
Next expiry date	2021-09-30
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Handbrake lever travel on limit
Advice	Engine cover and under trays fitted
Advice	Nearside registration lens deteriorated
Advice	Offside door mirror slightly insecure

MOT #14	2019-09-30 13:13
MOT test number	898970725892
Result	✓ Passed

MOT #13	2018-09-27 10:04
MOT test number	257411964227
Result	✓ Passed

MOT #12	2017-09-30 13:31
MOT test number	968463747880
Result	✓ Passed

MOT #11	2016-09-14 13:10
MOT test number	932694694402
Result	✓ Passed
Advice	Both front tyres wearing on edges
Advice	Nearside Rear Nail in tyre
Advice	Covers and shields fitted
Advice	Nearside Rear tyre wearing on edge close to limit

**MOT #10** 2015-09-28 14:19**MOT test number** 233774153067**Result** ✓ Passed**MOT #9** 2015-09-26 10:30**MOT test number** 238821530002**Result** ✗ Failed**Fail** Offside Front Tie bar/rod ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt vertical link top boot (2.4.G.2)**Fail** Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #8** 2014-09-27 10:14**MOT test number** 536210074293**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Spare wheel missing**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Items removed from driver's view prior to test**MOT #7** 2013-10-01 12:24**MOT test number** 918614973233**Result** ✓ Passed**Notice** Front brake discs lipped**Notice** Off side wiper in poor condition

**MOT #6** 2013-10-01 11:34**MOT test number** 119104573232**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Front brake discs lipped**Pass with rectification** Nearside Headlamp aim too low (1.8)**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Off side wiper in poor condition**MOT #5** 2012-09-29 09:00**MOT test number** 118863272206**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-10-01 10:48**MOT test number** 587334671237**Result** ✓ Passed**MOT #3** 2011-01-21 11:01**MOT test number** 928811621064**Result** ✓ Passed



MOT #2	2009-12-14 14:54
MOT test number	491828049308
Result	✓ Passed
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
Notice	Child seat fitted not allowing full inspection of adult belt

MOT #1	2009-12-14 14:54
MOT test number	902928249382
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Notice	Child seat fitted not allowing full inspection of adult belt
Advice	Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2006-10-16
Last registration	2020-09-28
Complete history	See info



Registration #1	2006-10-16	14 mi
Registration #2	2009-12-14	26.116 mi
Registration #3	2011-01-21	36.532 mi
Registration #4	2011-10-01	41.592 mi
Registration #5	2012-09-29	56.516 mi
Registration #6	2013-10-01	69.116 mi
Registration #7	2013-10-01	69.116 mi
Registration #8	2014-09-27	83.304 mi
Registration #9	2015-05-20	95.377 mi
Registration #10	2016-05-20	95.377 mi
Registration #11	2017-05-20	95.377 mi
Registration #12	2018-05-20	95.377 mi
Registration #13	2019-05-20	95.377 mi
Registration #14	2020-05-20	95.377 mi
Registration #15	2021-05-20	95.377 mi
Registration #16	2022-05-20	95.377 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1770 mm
Height	1660 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1495 kg
Max. allowed weight	2160 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Number of axles	2
Engine number	2AD5091090