



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V
Colour	Blue
Year of manufacture	2010
Top speed	98 mph
0 - 60 mph	15.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	29.1 mpg
Consumption extra urban	44.8 mpg
Consumption combined	37.7 mpg



LABEL UNKNOWN



Internet history

Entry 2


Date	2023-04-13
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-07-23
Pictures	12
Listing price	View report



source: [cargurus.co.uk](https://www.cargurus.co.uk)



MOT history

MOT expiry date	2024-10-03
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	46
Total items failed	16

MOT #17 2023-09-21 13:08

MOT test number 184009445731

Result ✓ Passed

Next expiry date 2024-10-03

- Advice** Central and rear exhaust boxes corroded.
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Undertrays fitted, Full inspection not carried out.
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Tyre cracking and perishing. (5.2.3 (d) (ii))
- Advice** Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Rear Coil spring corroded Both. (offside and nearside). (5.3.1 (b) (i))
- Advice** Offside Front Daytime running bulb inoperative.
- Advice** Rear Suspension components corroded.
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Central Brake hose has slight corrosion to ferrule Both. (offside and nearside). (1.1.12 (f) (i))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement All front suspension arm bushes worn. (offside and nearside). (5.3.4 (a) (i))

**MOT #16**

2023-09-12 14:02

MOT test number

921071541787

Result**✗ Failed**

Fail Nearside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Central and rear exhaust boxes corroded.

Fail Nearside Front Headlamp aim too low (4.1.2 (a))

Fail Nearside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Suspension components corroded.

Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))

Fail Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Advice Offside Front Daytime running bulb inoperative.

Advice Offside Rear Tyre slightly damaged/cracking or perishing Tyre cracking and perishing. (5.2.3 (d) (ii))

Advice Rear Coil spring corroded Both. (offside and nearside). (5.3.1 (b) (i))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement All front suspension arm bushes worn. (offside and nearside). (5.3.4 (a) (i))

Fail Offside Front Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Undertrays fitted, Full inspection not carried out.

Advice Central Brake hose has slight corrosion to ferrule Both. (offside and nearside). (1.1.12 (f) (i))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #15**

2022-10-04 09:28

MOT test number

970994975360

Result

✓ Passed

Advice Steering system slightly rough offside front macpherson strut top mounting bearing slightly rough when steering turned (2.1.1 (a))

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Offside daylight running lamp not working

MOT #14

2022-09-30 09:56

MOT test number

550807339491

Result

✗ Failed

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Windscreen washer provides insufficient washer liquid both (3.5 (a))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Fail Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Fail Nearside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

Advice Offside daylight running lamp not working

Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

Advice Steering system slightly rough offside front macpherson strut top mounting bearing slightly rough when steering turned (2.1.1 (a))

Fail Offside Front Lower Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))

**MOT #13** 2021-08-23 09:43**MOT test number** 513385948626**Result** ✓ Passed**MOT #12** 2020-10-10 13:42**MOT test number** 115478242651**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords and wearing on outside edge (5.2.3 (d) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #11** 2020-10-09 15:27**MOT test number** 880920512838**Result** ✗ Failed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords and wearing on outside edge (5.2.3 (d) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #10** 2019-04-21 12:44**MOT test number** 280308493630**Result** ✓ Passed**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #9** 2019-04-19 12:03**MOT test number** 799582983534**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #8** 2018-04-04 13:39**MOT test number** 729288300872**Result** ✓ Passed**MOT #7** 2017-04-04 15:20**MOT test number** 808536417006**Result** ✓ Passed**Advice** Offside Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Nearside Front tyre worn on inside and outside edge**Advice** Central Front Front suspension has slight movement at a wishbone pin or bush (2.5.A.1c)**Advice** Offside Front tyre worn on inside and outside edge**MOT #6** 2016-04-20 15:50**MOT test number** 935025658528**Result** ✓ Passed**MOT #5** 2016-04-20 11:39**MOT test number** 729726504927**Result** ✗ Failed**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view glass (8.1.2a)**MOT #4** 2015-04-18 12:27**MOT test number** 566908305187**Result** ✓ Passed**MOT #3** 2014-04-18 12:51**MOT test number** 237358604136**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt



MOT #2	2014-04-18 12:51
MOT test number	127118804192
Result	✗ Failed
<div>Pass with rectification</div> Offside Stop lamp not working (1.2.1b)	
<div>Notice</div> Child seat fitted not allowing full inspection of adult belt	

MOT #1	2013-04-12 10:29
MOT test number	665682203178
Result	✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 May 2025

✓
MOT

Expires:
3 October 2024

Tax status		Valid until 1 May
Days left		368
MOT expiry date		3 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2010-04-19
Last registration	2023-09-21
Complete history	See info



Registration #1	2010-04-19	17 mi
Registration #2	2013-04-12	14.885 mi
Registration #3	2014-04-18	19.563 mi
Registration #4	2015-04-18	24.951 mi
Registration #5	2016-04-20	30.202 mi
Registration #6	2016-04-20	30.202 mi
Registration #7	2017-04-04	34.921 mi
Registration #8	2018-04-04	39.344 mi
Registration #9	2019-04-19	46.058 mi
Registration #10	2019-04-21	46.061 mi
Registration #11	2020-04-21	46.061 mi
Registration #12	2021-04-21	46.061 mi
Registration #13	2022-04-21	46.061 mi
Registration #14	2023-04-21	46.061 mi
Registration #15	2024-04-21	46.061 mi
Registration #16	2025-04-21	46.061 mi
Registration #17	2026-04-21	46.061 mi
Registration #18	2027-04-21	46.061 mi
Registration #19	2028-04-21	46.061 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1904 mm
Height	1990 mm
Length	4892 mm
Kerb weight	1851 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3

Number of axles

2

Engine number

CAA 082285