



report date: 2024-03-28

General information

Make	LAND ROVER
Model	RANGE ROVER TDV8 VOGUE SE
Colour	White
Year of manufacture	2011
Top speed	130 mph
0 - 100 km/h	7.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	230 kW / 313 HP / 313 BHP
Max. torque	700 Nm at 1.500 rpm
Engine capacity	4.367 cc
Cylinders	8
Fuel type	Diesel
Consumption city	24.6 mpg
Consumption extra urban	34.5 mpg
Consumption combined	30.1 mpg
CO2 emission	253 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-02-01
Pictures	3
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-22
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	20
Total items failed	1

MOT #12	2024-04-23 15:49
MOT test number	577613624816
Result	✓ Passed
Next expiry date	2025-04-22

MOT #11	2023-04-14 10:32
MOT test number	852073059128
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
Advice	Offside Front headlight washer jet missing
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))
Advice	Rear Child Seat fitted not allowing full inspection of adult belt both sides

**MOT #10** 2022-04-11 10:56**MOT test number** 505496142828**Result** ✓ Passed**Advice** Offside Front headlight washer jet missing**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2021-04-15 13:21**MOT test number** 572757649637**Result** ✓ Passed**MOT #8** 2020-01-03 17:04**MOT test number** 465626951341**Result** ✓ Passed**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge Wearing on inner and outer edge (5.2.3 (e))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge Wearing on inner and outer edge (5.2.3 (e))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material Corroded (1.1.11 (c))**MOT #7** 2018-11-17 10:10**MOT test number** 913927614723**Result** ✓ Passed

**MOT #6** 2018-11-09 11:51**MOT test number** 557387682098**Result** ✗ Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm cords exposed on inner edge (5.2.3 (e))

MOT #5 2017-10-11 10:57**MOT test number** 404463573415**Result** ✓ Passed**MOT #4** 2016-11-02 17:33**MOT test number** 168711209265**Result** ✓ Passed**MOT #3** 2016-09-02 12:21**MOT test number** 210952692950**Result** ✓ Passed

Advice Offside Rear Brake pad(s) wearing thin (3.5.1g)

Advice Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #2 2015-09-04 11:27**MOT test number** 186580214302**Result** ✓ Passed



MOT #12014-08-27 14:55

MOT test number615589634223

Result	✓ Passed
<div><div>Advice</div>Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)</div>	
<div><div>Advice</div>Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)</div>	
<div><div>Advice</div>Offside Front Seat belt stitching slightly frayed (5.2.2b)</div>	
<div><div>Advice</div>Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
22 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-



Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-28
Current registration	XXXXXX
Plate since	2024-03-28

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-01
Last registration	2024-04-23
Complete history	See info



Registration #1	2011-09-01	6 mi
Registration #2	2014-08-27	29.793 mi
Registration #3	2015-09-04	46.046 mi
Registration #4	2016-09-02	58.128 mi
Registration #5	2016-11-02	58.745 mi
Registration #6	2017-10-11	63.226 mi
Registration #7	2018-11-09	72.626 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	2216 mm
Height	1865 mm
Length	4967 mm
Wheel base	2880 mm
Kerb weight	2710 kg
Max. allowed weight	3200 kg

Additional information

Fuel tank capacity	100 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	0006899448DT